



TREE INVENTORY

Table with columns: Tree No., Species, DBH (cm), Height (m), Biological Health, Structural Condition, Comments, Recommended Action, Location. Lists 126 individual trees with their specific characteristics and recommendations.

TREE INVENTORY LEGEND

Legend table defining symbols for Biological Health (H, M, L), Structural Condition (PL, SU, TB, TD, TH, UB), Comments (B, BF, CS, DB, GA, HA, IB, LB, MS, P, R, RC, R*, R**, T), and Recommended Action (P, R, RC, R*, R**, T).




NOTES: 1. Hoarding details to be determined following initial site inspection. 2. Private tree hoarding to be approved by Development & Design. 3. Hoarding must be supplied, installed and maintained by the applicant throughout all phases of construction. 4. Do not allow water to collect and pond behind or within hoarding. 5. T-bar supports are acceptable alternative to 4x4 posts. U-shaped metal supports will not be accepted. 6. Plywood must be utilized for 'solid' hoarding. OSB/Chipboard will not be accepted for solid hoarding. Plywood sheets must be installed on 'construction' side of frame. 7. Applicant is responsible to ensure utility locates are completed within city boulevard prior to installing framed hoarding.

TREE PRESERVATION HOARDING MISSISSAUGA

TREE INVENTORY PLAN

- TREE PROTECTION RECOMMENDATIONS: 1. Install hoarding for subsequent municipal review/approval. 2. Hoarding may be moved temporarily to provide access for tree removal only. 3. Pruning, if required, should be done prior to construction and in accordance with current arboricultural practices. 4. Excavation in close proximity to protected areas are to be undertaken with a certified arborist present. 5. Storage of any materials, fill, vehicles/equipment, and disposal of liquids is not permitted within 1m of protected areas. 6. Hydrofencing is recommended as the preferred method for excavation, within 1m of protected areas. 7. Exposed roots are to be covered immediately with mulch or topsoil and watered thoroughly. 8. Deep root fertilizer (3:1:1) following backfilling. 9. Trees should be re-assessed periodically in order to maintain an up to date understanding of health and structure.

LIMITING CONDITIONS: This tree inventory was derived from data gathered on the site using accepted arboricultural practices. This includes a visual examination of all above ground parts of the tree for structural defects and signs of health and vigor. All examination took place from the ground plane and no trees were cored, probed or climbed. There was also no detailed inspection of the root crown where excavation would have been required. This inventory describes the health, structural stability and identifies potential hazards of the trees to a reasonable extent. Where dead branches or other are identified in the notes it is the owners responsibility to take action. This inventory does not provide or imply a guarantee that these trees or branches will remain standing intact. The stability of any tree or branches of a tree cannot be predicted with absolute certainty under all circumstances. There is, likewise, no guarantee of survival for those trees to be preserved during construction but which are subject to injury. Tree preservation guidelines that are provided in this report are generally suitable for the tree as determined by the visual assessment. However, there is no guarantee that these guidelines will be followed throughout construction unless an arborist is retained for complete supervision of the site at all times. Even with complete supervision, roots in an urban environment are unpredictable. Guidelines, that suppose an even distribution of roots may not be effective in cases where roots have clustered in small areas. The assessment in this inventory is valid only at the time of inspection.



LEGEND: Tree protection - Framed Hoarding or Fast Fence Permissible if Affixed with T-bar; Building Envelope; Existing tree to be preserved; Hazardous Tree for Future Removal; Dangerous Tree to be Removed; Existing tree to be removed for road/steering construction.

Jon Woodside ISA Certified Arborist ON-1439A Baker Turner Inc.

REVISIONS table with columns: DATE, DESCRIPTION. Lists several revision events from 2020 to 2023.

NOTE: Contractor is to check and verify all dimensions and conditions on the project, and to immediately report any discrepancies to the landscape architect before proceeding with the work.



BTi Baker Turner Inc. Landscape Architecture | Site Design Suite 300 8501 Mississauga Road Brampton Ontario L6Y 5G8 Tel: (905) 453-9398 Fax: (905) 453-9376 email: tba@bakerturner.com

Project Title: Weldon Properties Inc 890 Meadow Wood Road Part of Lots 8, 9, & 10 City of Mississauga, ON TREE INVENTORY PLAN

Table with columns: Date, Issued, Job Number, Drawn By, Scale, Checked By, Sheet Number, File Number. Shows project details for August 2019.

Trees less than 15cmØ caliper, and large shrubs may exist on the site. It is the contractors responsibility to determine the extent of possible removals by field review prior to submission of quotations for removals work.