Arborist Report for

King Street East

Mississauga, Ontario

DAWhiteTreeCare.com

Tel: 416 431 2453, E-mail: DAWhiteTreeCare@GMail.com

D. Andrew White M. Sc. ISA Certified Arborist ON-0734. 78 Marcella St. Toronto, ON, M1G 1L2.

1. Introduction

The following is an arborist report for the property at King Street East Drive, in Mississauga Ontario. (The lot is SE of 188 King Street East.) The purpose of this report was to ascertain the potential impacts of the proposed construction of a new development on the trees on the site and on adjacent properties.

This report was written for MSLA.

2. Methods

An on-site inspection was made on February 12, 2021. The sizes of individual trees were measured as diameter at breast height (DBH), breast height being 137 cm from ground level. The locations of these trees are indicated on the modified site plan (Fig. 1). From the data collected plant Condition Rating (CR), Location Rating (LR), Species Rating (SR), and minimum Tree Protection Zones (TPZ), were estimated.^{1,2}

It is necessary to protect all trees designated for preservation during both demolition and construction. This tree protection can be accomplished by protecting the said trees with *tree protection barriers*. The minimum tree protection zone (TPZ) radius is based on the diameter of the tree (TPZ≈0.06_{m/cm} x DBH_{cm}). Tree barriers for road allowance areas would be composed of a 1.2 metres (4 ft.) high plastic safety fencing secured on metal T-bar supports as per city of Mississauga's "framed hoarding" detail. Usually, tree protection barriers, not on road allowance, are to be "solid board hoarding" at 1.2 metres (4 ft.) high, and composed of plywood. ³

3. Discussion

There are plans to develop the site at King Street East several non-exempt trees would need to be injured or removed, in order to allow for the proposed development (Table 1, Fig. 1).



3.2 Roadside Trees

Removal

One (1) border/city owned tree over 15cm DBH is proposed for removal. (Table 1, Fig. 1 Trees #1889). This tree is in conflict with the proposed driveway.

Two (2) city owned trees (#1900 & #1999) are to be retained and will require tree protection during the demolition and construction work on the site. They are in close proximity to the grading works on site and are potential Injury Candidates. Refer to tree & hoarding locations on the plan developed by MSLA Landscape Architects. (Fig. 1).

3.3 Private Trees

Removal

Ten (10) privately owned trees over 15cm DBH are proposed to be removal. (Table 1, Fig. 1). These trees are in conflict with the proposed development.

3.4 Neighbouring Trees

No Neighbouring trees will require removal or injury. Several Neighbouring trees are to be retained and will require tree protection during the demolition and construction work on the site. Refer to tree & hoarding locations on the plan developed by MSLA Landscape Architects.

4. Conclusion

In order to allow for the proposed construction at King Street East, several non-exempt trees would be removed or injured as follows.

Ten (10) privately owned trees over 15cm DBH are proposed for removal.

One (1) Border/ City owned trees over 15cm DBH is proposed for removal.

Two (2) City Trees are potential Injury Candidates

No (0) neighbouring trees require removal.

D. Onder Thile

D. Andrew White M. Sc.

February 15, 2021

Table #1. Tree number (No.), species, diameter at breast height (DBH), Condition Rating (CR) Tree Category (TC), Comments & Recommendations.

Light Grey Highlighted rows indicate non exempt trees proposed for removal

No.	Tree	DBH	CR	TC	Comments	Recommendation
	Species	(cm)	(%)			
Tag	Norway	41	60	City	Crown base at	To be Preserved;
#1999	Maple				2.5 m, fair	Potential Injury
					condition	
Tag	Manitoba	67	52.5	City	3-stems at 2	To be Preserved;
#1900	Maple				m, poor	Potential Injury
	•				condition	,
Tag #1889	Crab-Apple	26	55	Border/	Low-fair	To be Removed;
				City	condition	Conflict with
					with crooked	Development
					trunk	1
Tag	Black	8-17	65	Private	Coppice of	To be Removed;
#1899	Walnut				stump circa	Conflict with
					50 cm DBH	Development
Tag #1898	Black	10-17	65	Private	Coppice of	To be Removed;
	Walnut	10 17	0.5	11114	stump circa	Conflict with
					30 cm DBH	Development
Tag	Black	12-15	65	Private	3-stems at 0	To be Removed;
#1897	Walnut	12 13	0.5	Tiivate	m, possibly	Conflict with
	· · · · · · · · · · · · · · · · · · ·				coppice	Development
Tag #1895	Black	14-18	60	Private	4-stems at 0	To be Removed;
	Walnut	1110		Tiivate	m, possibly	Conflict with
	VV dilitat				coppice	Development
Tag	Black	13-15	65	Private	3-stems at 0	To be Removed;
#1896	Walnut	13-13	0.5	Tiivaic	m, possibly	Conflict with
	vv alliut				coppice	Development
Tag	Black	10-12	65	Private	3-stems at 0	To be Removed;
#1892	Walnut	10-12	03	Filvate		Conflict with
	vv alliut				m, coppice on	Development
					stump circa 25 cm DBH	Development
Tag	White	15 16	60	Private	_	To be Demonde
#1890		15-16	60	Private	Tree near	To be Removed; Conflict with
,,10,0	Cedar				fence, low- fair condition	
T	N/ '/ 1	15 10	60	D : 4		Development
Tag #1894	Manitoba	15-18	60	Private	Tree leaning	To be Removed;
111074	Maple				south, 2-stems	Conflict with
Т	3.6 1.1	10 10	60	D : .	near 0 m	Development
Tag #1893	Manitoba	12-19	60	Private	Tree leaning	To be Removed;
	Maple				south, 2-stems	Conflict with
	3.6 1.1	0.14	60	D	near 0 m	Development
Tag #1891	Manitoba	8-14	60	Private	Tree leaning	To be Removed;
	Maple				south, 2-stems	Conflict with
					at 0 m	Development
#57- 60	Black	6-14	70	Private	Small	To be Removed;
	Walnuts				naturalised	Conflict with
					trees	Development

#61	Manitoba Maple	8-15	40	Private	Fallen tree & coppice	To be Removed; Conflict with Development
#81- 114	White Cedars	12-18	55- 65	Neigh.	Hedgerow 8 trees over 15 cm DBH	To be Preserved;
#115	Cottonwood	52-62 (circa)	60	Neigh.	Large tree behind fence, 3-stems	To be Preserved;
#116	Apple tree	15	50	Neigh.	Off-site fruit tree, poor condition	To Remain; Beyond Limit of Work
#117	Plum	15-24	60	Neigh.	Off-site fruit tree, low-fair condition	To Remain; Beyond Limit of Work
#118	Apple tree	22	55	Neigh.	Off-site fruit tree, low-fair condition	To Remain; Beyond Limit of Work
#119	Juniper	14-18	50	Neigh.	Off-site tree behind fence, poor condition	To Remain; Beyond Limit of Work




Figure #1: Tree locations on the King Street East development site

4. References

- 1- Council of Tree Landscape Appraisers. 2000. Guide for Plant Appraisal. 9th Edition. International Society of Arboriculture.
- 2- International Society of Arboriculture of Ontario. 1998. Ontario Supplement to Guide for Plant Appraisal 8th Edition. Ontario Chapter, International Society of Arboriculture.
- 3- City of Mississauga. 2001. THE TREE PERMIT BY-LAW NUMBER 474-05. Corporation of the City of Mississauga, ON.
- 4- City of Mississauga. 2019. Application to Permit the Injury or Destruction of Trees on Private Property. City of Mississauga Community Services Department.
- 6- MMAH. 2005. Greenbelt Plan No. 208/2005. Feb 28, 2005. Ministry of Municipal Affairs & Housing.
- 5- Government of Canada. 1994. Migratory Birds Convention Act, 1994 (1994, c. 22). Department of Justice Canada.

5. Photographs



Image #1: Existing City Maple Trees along Camilla Road



Image #2: Existing City Maple Trees



Image #3: Existing Walnut Trees



Image #4: Existing Neighbouring Trees at North-West Corner



Image #5: Existing Neighbouring Trees along North Property Line



Image #6: Existing Trees – North View