

October 19, 2023

BEL 217067

DVB Real Estate Investments Inc.
4918 King Street, P.O. Box 1194
Beamsville, ON L0R 1B0

Re: Revised Arborist Report for 3016-3032 Kirwin Avenue & 3031 Little John Lane, Mississauga, ON

Beacon Environmental Limited (Beacon) is pleased to provide you with this Revised Arborist Report in support of the proposed redevelopment of properties located at 3016-3032 Kirwin Avenue & 3031 Little John Lane in the City of Mississauga.

The Arborist Report has been prepared in support of a re-development proposal in accordance with City of Mississauga standards. The Arborist Report summarizes the findings of the tree inventory and assessment of all trees ≥ 10 cm in diameter at breast height (DBH, measured 1.4 m above grade) located on or within 6.0 m of the subject property and identifies tree to be removed or preserved to accommodate the proposed development plan. The Arborist Report includes recommendations for tree protection, including establishing Tree Protection Zones and other measures to ensure trees identified for preservation are adequately protected.

Beacon had previously prepared Arborist Reports for these properties in December 2017, March 2019, and March 2021. This Revised Arborist Report has been updated to reflect the latest versions of the Site Plan and Grading & Servicing Plans.

Methods

All trees with stem diameters of ≥ 10 cm at breast height (DBH, measured 1.4 m above grade) located on the subject property, as well as trees within 6.0 m of the subject property boundary were inventoried and assessed by an International Society of Arboriculture (ISA) Certified Arborist on April 25, May 3, and October 20, 2017. A follow up site visit was conducted on September 30, 2022. Inventoried trees on the subject property were marked with numbered aluminum forestry tags. Trees on adjacent properties were also inventoried and assessed. All inventoried trees were surveyed by a registered Ontario Land Surveyor (O.L.S.).

The assessment included collecting data on tree species, trunk diameter (DBH), and health and condition as described below. Individual trees were assessed in terms of overall health and structural integrity based on indicators such as live buds, dead wood, decay, structural defects, and presence of disease. Each tree was assigned a condition rating of good, fair, poor, or dead, based on the following criteria:

- **Poor** – Severe dieback, significant lean, missing leader, major defects, significant decay and/or disease presence;
- **Fair** – Moderate dieback and/or lean, limb defects, multiple stems, moderate foliage damage from stress;
- **Good** – Healthy vigorous growth, minor visible defects or damage; or
- **Dead** – No live crown (epicormic growth may be present).

Limitations of the assessment are included in **Attachment A**.

Findings

A total of 228 trees were originally inventoried and assessed. Based on a follow up site visit on September 30, 2022, it was noted that three dead trees located on the adjacent City Parkland had fallen over onto the subject property. A list and description of the trees is provided in **Attachment B**. Tree locations are illustrated in **Figure 1, Attachment C**). The majority of the trees occur on the western half of the subject properties on lands that are within the floodplain of Cooksville Creek that will remain undeveloped. The remainder of the trees occur on the eastern half of the property on former residential lands that are proposed to be redeveloped.

Trees sizes ranged from 10 cm to 80 cm DBH, with a median diameter of 20 cm DBH. The majority of the trees inventoried are invasive non-native species including Norway Maple, Manitoba Maple, Black Locust, and Siberian Elm.

Description of Proposed Redevelopment

The proposed redevelopment for the subject property consists of an 8-storey rental apartment building with a total of 152 units and associated aboveground and underground parking as well as an outdoor amenity space.

Tree Removals

A total of 74 trees will require removal to accommodate the proposed redevelopment and/or due to poor condition (37 are in poor or fair-poor condition and four are dead). The majority of trees proposed for removal are non-native invasive species (Norway Maple and Manitoba Maple).

Of 74 trees proposed for removal, 63 are located on-site and 11 are located off-site or on the property line. Of the 11 trees located off-site, three are associated with the municipally-owned parkland north of the subject properties (tree # 4299, 4290, 4294), one is located within the municipally-owned boulevard along Kirwin Avenue (tree #4001), six trees are located on adjacent private properties to the south (tree # 4005, 4006, 4008, 4010, 4011, 4084), and one is located on the property line along Kirwin Avenue (4002)

Removal of trees from adjacent lands or the property line requires written consent from the adjacent landowners (public or private).

Trees situated on private property are subject to the City of Mississauga's Private Tree Protection Bylaw (0021-2022). The proponent is required to obtain a Tree Removal Permit prior to removing any tree with a DBH greater than 15 cm.

Prior to tree clearing, all trees permitted for removal should be clearly marked in the field using spray paint or flagging tape.

Tree Preservation

A total of 151 trees are situated outside areas that will be affected by the proposed development and associated grading and servicing. These trees have been identified for preservation and will be protected using standard tree protection measures.

Recommended Tree Protection Measures

Tree health and structural integrity can be compromised by grade changes, soil compaction, root cutting, and mechanical damage to trunks and branches resulting from the operation of construction equipment.

Trees to be retained shall be protected through the establishment of a tree protection zone (TPZ). Standard TPZ is generally established at the dripline of the tree crown. In situations where it is may not be feasible to implement a standard TPZ, it is possible that a lesser TPZ could be established that could also provide sufficient protection but allow for tighter integration with the development. The minimum TPZ's are provided in **Table 1**, which is based on the general rule of applying 6 cm of protection for each cm of stem diameter as described in the City of Mississauga's *Tree Preservation & Protection Standards* (2019).

Table 1. Minimum Tree Protection Zones

Trunk Diameter (DBH)	Minimum Protection Distances ¹
10 – 30 cm	1.8 m
31 – 40 cm	2.4 m
41 – 50 cm	3.0 m
51 – 60 cm	3.6 m
61 – 70 cm	4.2 m
71 – 80 cm	4.8 m
81 – 90 cm	5.4 m
91-100 cm	6.0 m

¹ to be measured from the outside edge of the base of the tree

The minimum TPZ for trees to protected are illustrated in **Figure 1**.

The TPZ should be demarcated with tree protection hoarding consisting of 1.2 m orange plastic fencing framed with solid top and bottom rail, or 1.2 m plywood (see **Figure 1** for fence location and hoarding details) or alternative as approved by the City. Fencing should be installed before any construction or site alteration takes place.

In general, no grading, soil disturbance, or surface treatments shall occur within the TPZ and no equipment or materials shall be stored inside the TPZ.

Along the north side of the property, it is Beacon's understanding that minor grading (approx. 5-10 cm of cut) will occur within the TPZs of several mature Norway Spruce trees located in the City's parkland. It is recommended that during construction of the building, tree protection fencing be established at the limit of the TPZs as illustrated in **Figure 1**. Fencing may be removed after construction is complete in order to accommodate final site grading within the TPZs. It is recommended that grading within the TPZs be performed using hand tools or assisted with an Airspade or hydrovac to minimize root impacts. Grading with the TPZs should be supervised by a Certified Arborist.

Excavation for the building foundation is required within the TPZ of tree 4287 along the north side of the property. Prior to excavation, root pruning using a hydro vacuum unit or air powered soil excavation tools should be utilized. Root pruning should be conducted by a qualified arborist or under an arborist's supervision and completed to a depth of 30 cm.

In addition to the establishment of the TPZ, the following specifications are recommended to ensure the health and survival of any retained trees:

- Before beginning works, the contractor will arrange to meet on site with a certified Arborist to review work procedures, access routes, storage areas, and TPZ hoarding;
- Any required pruning for construction clearance shall be performed by a certified Arborist; and
- Some tree roots may extend beyond the identified TPZs. Any root damage occurring during construction should be cut cleanly with a hand saw or pruning shears and be inspected by a certified Arborist.

Tree Replacement/Compensation

To compensate for the loss of trees from the subject property and adjacent lands, replacement trees should be planted in accordance with the City's Terms of Reference for Arborist Reports, Tree Inventory/Survey & Tree Preservation Plans (Sept 2022).

- One replacement tree for every 15 cm (6 inches) diameter of healthy private or public tree removed; and
- Replacement trees must be at least 1.8 m tall if it's a coniferous tree or at least 6 cm in diameter if it's a deciduous tree.

The aggregate diameter of trees being removed is 1957 cm; therefore, 130 60 mm replacement trees are required. The City has identified three areas within the adjacent John C. Price park where replacement trees can be accommodated. These areas have a combined area of approximately 2,900 m². Instead of planting all trees of the same size, Beacon recommends planting a mix of large and

smaller caliper stock that is equivalent to 130 60 mm caliper trees (i.e. a cumulative of 7800 mm trunk diameter). At a planting density of 1,200 trees per hectare, the 2,900 m² area identified by the City could accommodate approximately 355 trees. For example: 35 60mm, 72 30mm, 106 20mm, and 142 10mm trees equals 355 trees with a cumulative stem diameter of 7800 mm equivalent to 130 60 mm caliper trees. From an ecological perspective, planting a mix of tree sizes is recommended over planting all trees of the same size. Plantings within the adjacent parkland will be limited to native species approved by CVC and the City. Detailed planting plans will be prepared for these areas illustrating planting sites, species, stock size and planting specifications.

Report prepared by:
Beacon Environmental



Dan Westerhof, B.Sc., M.E.S.
Senior Terrestrial Ecologist,
ISA Certified Arborist (ON-1536A)

Report reviewed by:
Beacon Environmental



Ken Ursic, B.Sc., M.Sc.
Principal, Senior Ecologist

Attachment A

Attachment A

Limitations of Tree Assessment

It is the policy of Beacon Environmental Ltd. to attach the following clause regarding limitations of the tree assessment. The intent is to ensure that the client is aware of what is technically and professionally realistic in assessing and/or retaining trees.

The assessment of the trees presented in this report has been made using accepted arboricultural techniques. These techniques include a visual examination of the above-ground parts of each tree for structural defects, scars, external indications of decay such as fungal fruiting bodies, evidence of insect attack, crown dieback, discoloured foliage, the condition of any visible root structures, the degree and direction of lean (if any), the general condition of the tree(s) and the surrounding site, and the proximity of property and people. Except where specifically noted in the report, none of the trees examined were dissected, cored, probed, or climbed, and detailed root crown examinations involving excavation were not undertaken.

Notwithstanding the recommendations and conclusions made in this report, it must be recognized that trees are living organisms and their health and vigour constantly change over time. They are not immune to changes in site conditions, pests, or variations in the weather conditions including severe storms with high-speed winds. Furthermore, some symptoms may only be visible seasonally; the extent of observations that can be made may be limited by the time of year in which the inspection took place.

While reasonable efforts have been made to ensure that the trees recommended for retention are healthy unless stated otherwise within the report, no warranty or guarantees are offered, or implied, that these trees, or any parts of them, will have continued health or structure as noted in the report. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or group of trees or their component parts in all circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure if provided with the necessary combinations of stresses and elements. This risk can only be eliminated if the tree is removed.

Although every effort has been made to ensure that this assessment is reasonably accurate, it is recommended that trees be re-assessed periodically to identify changes in condition. Design or site plan changes may also necessitate re-assessment and/or revisions to this report. **The assessment presented in this report is valid at the time of the inspection and is intended for sole use of the client.** Any use of this report by a third party, and any decision based on this report, is the singular responsibility of the third party.

Attachment B

Attachment B

Kirwin Tree Inventory

Tag #	Species	Common Name	DBH (cm)	Location	Condition	Comments	TPZ radius (m)	Recommendation
4001	<i>Gleditsia triacanthos</i>	Honey Locust	50	Off-site - Municipal Right of Way	Good		3.6	Remove - development
4002	<i>Picea glauca</i>	White Spruce	32	Property Boundary	Good		2.4	Remove - development
4003	<i>Juniperus</i>	Juniper	23	On-site	Fair	lean	1.8	Remove - development
4005	<i>Acer platanoides</i>	Norway Maple	28,17 (33)	Off-site - private	Good		2.4	Remove - development
4006	<i>Acer platanoides</i>	Norway Maple	17	Off-site - private	Fair	crowded	1.8	Remove - development
4008	<i>Acer platanoides</i>	Norway Maple	40,28 (49)	Off-site - private	Fair-Good		3.6	Remove - development
4010	<i>Acer platanoides</i>	Norway Maple	25	Off-site - private	Fair		1.8	Remove - development
4011	<i>Acer platanoides</i>	Norway Maple	29,11 (31)	Off-site - private	Fair		2.4	Remove - development
4012	<i>Acer platanoides</i>	Norway Maple	27	On-site	Fair	uneven crown, lean	1.8	Remove - development
4013	<i>Acer platanoides</i>	Norway Maple	16,22 (27)	On-site	Fair-Good		1.8	Remove - development
4017	<i>Acer platanoides</i>	Norway Maple	16	On-site	Fair	lean, uneven crown, crowded	1.8	Remove - development
4019	<i>Acer platanoides</i>	Norway Maple	21	On-site	Fair	uneven crown, crowded	1.8	Remove - development
4020	<i>Acer platanoides</i>	Norway Maple	18	On-site	Fair-Poor	crooked trunk, uneven crown, crowded	1.8	Remove - development/poor condition
4023	<i>Acer negundo</i>	Manitoba Maple	22	On-site	Fair	lean	1.8	Remove - development
4025	<i>Acer platanoides</i>	Norway Maple	20	On-site	Fair-Good	rubbing against adjacent tree	1.8	Remove - development
4026	<i>Acer platanoides</i>	Norway Maple	18	On-site	Good		1.8	Remove - development
4027	<i>Acer platanoides</i>	Norway Maple	18,10 (21)	On-site	Good		1.8	Remove - development
4029	<i>Acer platanoides</i>	Norway Maple	17	On-site	Fair	crooked trunk, vine in crown	1.8	Remove - development
4030	<i>Acer negundo</i>	Manitoba Maple	24,24 (34)	On-site	Poor	one stem dead, other stem very twisted/bent, several cavities 2-6 m	2.4	Remove - development/poor condition
4033	<i>Acer platanoides</i>	Norway Maple	10	On-site	Poor	vine throughout crown	1.8	Remove - development/poor condition
4046	<i>Acer platanoides</i>	Norway Maple	17	Off-site - Municipal Park	Fair-Good	uneven crown	1.8	Preserve
4050	<i>Acer negundo</i>	Manitoba Maple	31	On-site	Poor	fallen over	2.4	Remove - development/poor condition
4051	<i>Acer platanoides</i>	Norway Maple	24	Off-site - Municipal Park	Fair	codominant leaders, uneven crown, bend in trunk	1.8	Preserve
4052	<i>Acer platanoides</i>	Norway Maple	46	On-site	Fair	uneven crown, lean	3	Remove - development
4053	<i>Acer negundo</i>	Manitoba Maple	23	On-site	Poor	severe lean, nearly dead	1.8	Remove - development/poor condition
4055	<i>Juglans nigra</i>	Black Walnut	18	On-site	Poor	severe bend, poor form	1.8	Remove - development/poor condition
4056	<i>Fraxinus americana</i>	White Ash	19	On-site	Dead		-	Remove - development/dead
4057	<i>Acer negundo</i>	Manitoba Maple	22	On-site	Poor	fallen over	1.8	Remove - development/poor condition
4059	<i>Acer negundo</i>	Manitoba Maple	20	On-site	Poor	significant lean, poor form	1.8	Remove - development/poor condition
4060	<i>Acer negundo</i>	Manitoba Maple	19	On-site	Poor	significant lean, poor form	1.8	Remove - development/poor condition

4061	<i>Acer negundo</i>	Manitoba Maple	21	On-site	Poor	top broken, epicormic branching	1.8	Remove - development/poor condition
4062	<i>Acer negundo</i>	Manitoba Maple	32	On-site	Fair-Poor	lean, large broken branch stub	2.4	Remove - development/poor condition
4063	<i>Acer negundo</i>	Manitoba Maple	42	On-site	Poor	severe lean, large cavity at 2 m	3	Remove - development/poor condition
4066	<i>Acer negundo</i>	Manitoba Maple	20	On-site	Dead		-	Remove - development/dead
4067	<i>Juglans nigra</i>	Black Walnut	25	On-site	Good	vine in crown	1.8	Remove - development
4068	<i>Juglans nigra</i>	Black Walnut	30	On-site	Fair-Good	uneven crown, vines	2.4	Remove - development
4070	<i>Acer platanoides</i>	Norway Maple	29	On-site	Fair-Good		1.8	Remove - development
4071	<i>Juglans nigra</i>	Black Walnut	16	On-site	Good		1.8	Remove - development
4072	<i>Acer negundo</i>	Manitoba Maple	10	On-site	Poor	poor form	1.8	Remove - development/poor condition
4074	<i>Acer platanoides</i>	Norway Maple	24	On-site	Fair	fair form, vines, branch dieback	1.8	Remove - development
4076	<i>Juglans nigra</i>	Black Walnut	25	On-site	Good	vines in crown	1.8	Remove - development
4078	<i>Acer platanoides</i>	Norway Maple	16	On-site	Good	vines in crown	1.8	Remove - development
4079	<i>Acer negundo</i>	Manitoba Maple	24	On-site	Fair-Poor	significant lean, broken branches	1.8	Remove - development/poor condition
4080	<i>Acer platanoides</i>	Norway Maple	19	On-site	Fair-Good	slight lean	1.8	Remove - development
4081	<i>Juglans nigra</i>	Black Walnut	21	On-site	Fair	significant bend in trunk (corrected)	1.8	Remove - development
4082	<i>Acer negundo</i>	Manitoba Maple	18	On-site	Poor	severe lean, overhanging fence and adjacent parking lot	1.8	Remove - development
4083	<i>Acer platanoides</i>	Norway Maple	24	On-site	Fair-Good	codominant leaders with included bark	1.8	Remove - development
4084	<i>Acer platanoides</i>	Norway Maple	20	Off-site - private	Fair	leaning over adjacent parking lot, fence embedded in trunk	1.8	Remove - development
4086	<i>Acer negundo</i>	Manitoba Maple	11,17,17 (26)	On-site	Fair-Poor	leaning over adjacent parking lot, poor form, good vigour	1.8	Remove - development/poor condition
4088	<i>Acer platanoides</i>	Norway Maple	19	On-site	Fair-Good		1.8	Remove - development
4089	<i>Acer negundo</i>	Manitoba Maple	11,13 (17)	On-site	Poor	poor form, branch dieback	1.8	Remove - development/poor condition
4090	<i>Juglans nigra</i>	Black Walnut	31	On-site	Good	small cavity @ 8 m	2.4	Remove - development
4091	<i>Acer platanoides</i>	Norway Maple	20	On-site	Fair	uneven crown, crowded	1.8	Remove - development
4092	<i>Acer negundo</i>	Manitoba Maple	50	On-site	Fair-Poor	forked @ 2m, one dead/broken leader	3.6	Remove - development/poor condition
4093	<i>Acer negundo</i>	Manitoba Maple	18	On-site	Poor	bent over, horizontal trunk	1.8	Remove - development/poor condition
4094	<i>Acer negundo</i>	Manitoba Maple	18	On-site	Fair-Poor	significant lean	1.8	Remove - development/poor condition
4095	<i>Acer negundo</i>	Manitoba Maple	34	On-site	Poor	two dead/broken leaders, top of live stem dead, trunk damage	2.4	Remove - development/poor condition
4096	<i>Acer negundo</i>	Manitoba Maple	39	On-site	Fair-Poor	open wound at base, crooked trunk, uneven crown	2.4	Remove - development/poor condition
4097	<i>Acer negundo</i>	Manitoba Maple	34	On-site	Fair-Poor	lean, uneven crown, cavity @ 2 m	2.4	Remove - development/poor condition
4099	<i>Ulmus pumila</i>	Siberian Elm	40	On-site	Poor	poor form, extensive dieback, large cavity @ 2 m	3	Remove - development/poor condition
4100	<i>Ulmus pumila</i>	Siberian Elm	31,28 (42)	On-site	Fair-Poor	many epicormics, branch dieback, codominant leaders with included bark	3	Remove - development/poor condition
4101	<i>Ulmus pumila</i>	Siberian Elm	31	On-site	Poor	poor form, epicormics, twig dieback	2.4	Remove - development/poor condition
4102	<i>Ulmus pumila</i>	Siberian Elm	26	On-site	Poor	uneven crown, twig dieback, extensive epicormics	1.8	Preserve
4104	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Poor	significant lean, thick crown	1.8	Remove - development/poor condition

4106	<i>Ulmus pumila</i>	Siberian Elm	17	On-site	Poor	uneven crown, twig dieback, extensive epicormics	1.8	Preserve
4108	<i>Ulmus pumila</i>	Siberian Elm	30	On-site	Fair	twig dieback, epicormics	2.4	Preserve
4109	<i>Catalpa sp.</i>	Catalpa	53	On-site	Fair	cavity at base, dead branches, small cavity @ 8 m	3.6	Remove - development
4110	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Poor	fallen over	1.8	Preserve
4112	<i>Catalpa sp.</i>	Catalpa	80	On-site	Fair-Poor	full crown; large, over-extended branch; large crack/cavity in trunk from branch crotch to base	5.2	Preserve
4113	<i>Ulmus pumila</i>	Siberian Elm	22	On-site	Fair-Good	twig dieback	1.8	Preserve
4114	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair	twig dieback	1.8	Preserve
4115	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair	twig dieback	1.8	Preserve
4116	<i>Ulmus pumila</i>	Siberian Elm	28	On-site	Fair-Poor	extensive twig dieback, vine in crown	1.8	Preserve
4117	<i>Ulmus pumila</i>	Siberian Elm	21	On-site	Fair	twig dieback, vine in crown	1.8	Preserve
4118	<i>Ulmus pumila</i>	Siberian Elm	22	On-site	Fair	uneven crown, twig dieback	1.8	Preserve
4121	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair	twig dieback, vine in crown	1.8	Preserve
4123	<i>Ulmus pumila</i>	Siberian Elm	17	On-site	Fair	twig dieback	1.8	Preserve
4124	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair	twig dieback	1.8	Preserve
4127	<i>Acer negundo</i>	Manitoba Maple	16	On-site	Fair	leaning, vine in crown	1.8	Preserve
4128	<i>Ulmus pumila</i>	Siberian Elm	16	On-site	Fair-Poor	uneven crown, twig dieback, vine in crown	1.8	Preserve
4129	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair	dead leader	1.8	Preserve
4130	<i>Ulmus pumila</i>	Siberian Elm	14	On-site	Fair	uneven crown, epicormics	1.8	Preserve
4131	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair-Poor	codominant leaders, branch and twig dieback	1.8	Preserve
4132	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair	twig dieback	1.8	Preserve
4133	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair	twig dieback, uneven crown	1.8	Preserve
4134	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair	twig dieback, uneven crown	1.8	Preserve
4136	<i>Ulmus pumila</i>	Siberian Elm	22	On-site	Fair	twig dieback, vine in crown	1.8	Preserve
4137	<i>Acer negundo</i>	Manitoba Maple	14	On-site	Fair	lean, branch dieback	1.8	Preserve
4142	<i>Acer negundo</i>	Manitoba Maple	19	On-site	Fair-Poor	significant lean, twig dieback	1.8	Preserve
4144	<i>Acer negundo</i>	Manitoba Maple	14	On-site	Fair	lean, twig dieback	1.8	Preserve
4145	<i>Acer negundo</i>	Manitoba Maple	11	On-site	Poor	lean, crooked trunk, branch dieback	1.8	Preserve
4146	<i>Acer negundo</i>	Manitoba Maple	14	On-site	Fair-Poor	lean, branch dieback	1.8	Preserve
4147	<i>Acer negundo</i>	Manitoba Maple	16	On-site	Fair	dieback, crooked trunk	1.8	Preserve
4148	<i>Acer negundo</i>	Manitoba Maple	21	On-site	Fair	lean, branch dieback	1.8	Preserve
4149	<i>Acer negundo</i>	Manitoba Maple	16	On-site	Fair	lean, branch dieback	1.8	Preserve
4152	<i>Acer negundo</i>	Manitoba Maple	14	On-site	Fair	lean	1.8	Preserve
4153	<i>Acer negundo</i>	Manitoba Maple	16	On-site	Fair-Poor	lean, bend in trunk, vine in crown, dieback	1.8	Preserve
4154	<i>Acer negundo</i>	Manitoba Maple	15	On-site	Fair		1.8	Preserve
4155	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Fair	lean, twig dieback	1.8	Preserve
4156	<i>Acer negundo</i>	Manitoba Maple	19,16	On-site	Poor	significant lean, top broken off one stem	1.8	Preserve
4157	<i>Acer negundo</i>	Manitoba Maple	12	Off-site - Municipal Park	Poor	severe lean	1.8	Preserve
4158	<i>Acer negundo</i>	Manitoba Maple	13,18,19,10,10	Off-site - Municipal Park	Fair	lean, uneven crown	2.4	Preserve
4159	<i>Ulmus pumila</i>	Siberian Elm	14	Off-site - Municipal Park	Fair	lean, uneven crown	1.8	Preserve
4160	<i>Acer negundo</i>	Manitoba Maple	15	Off-site - Municipal Park	Fair	uneven crown, branch dieback	1.8	Preserve
4161	<i>Acer negundo</i>	Manitoba Maple	25	Property Boundary	Poor	main trunk removed, very poor form	1.8	Preserve
4162	<i>Acer negundo</i>	Manitoba Maple	17,14	On-site	Fair	lean, branch dieback	1.8	Preserve
4163	<i>Acer negundo</i>	Manitoba Maple	24	On-site	Poor	lean, significant branch dieback	1.8	Preserve

4164	<i>Acer negundo</i>	Manitoba Maple	16,23	Off-site - Municipal Right of Way	Fair	lean, uneven crown	1.8	Preserve
4165	<i>Acer negundo</i>	Manitoba Maple	13	On-site	Fair-Poor	significant lean, branch dieback	1.8	Preserve
4166	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Fair-Poor	lean, branch dieback	1.8	Preserve
4167	<i>Acer negundo</i>	Manitoba Maple	11	On-site	Poor	poor form	1.8	Preserve
4168	<i>Acer negundo</i>	Manitoba Maple	11,12	On-site	Fair	branch dieback	1.8	Preserve
4173	<i>Acer negundo</i>	Manitoba Maple	10	On-site	Poor	significant dieback	1.8	Preserve
4174	<i>Acer negundo</i>	Manitoba Maple	11,12	On-site	Fair-Poor	significant lean, branch dieback	1.8	Preserve
4175	<i>Acer negundo</i>	Manitoba Maple	11,12,12	On-site	Fair	branch dieback	1.8	Preserve
4176	<i>Acer negundo</i>	Manitoba Maple	11,12	Off-site - Municipal Right of Way	Fair	lean, branch dieback	1.8	Preserve
4177	<i>Acer negundo</i>	Manitoba Maple	11	Off-site - Municipal Right of Way	Fair-Poor	significant lean	1.8	Preserve
4178	<i>Ulmus pumila</i>	Siberian Elm	15	Off-site - Municipal Right of Way	Poor	dead leader, twig dieback, poor form	1.8	Preserve
4179	<i>Ulmus americana</i>	White Elm	18	On-site	Fair	uneven crown	1.8	Preserve
4180	<i>Salix x rubens</i>	Hybrid Crack Willow	50	On-site	Good		3.6	Preserve
4181	<i>Ulmus americana</i>	White Elm	22,22	On-site	Fair		1.8	Preserve
4182	<i>Ulmus americana</i>	White Elm	24	On-site	Fair		1.8	Preserve
4185	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Fair	lean, dieback	1.8	Preserve
4187	<i>Acer negundo</i>	Manitoba Maple	15	On-site	Fair		1.8	Preserve
4188	<i>Acer negundo</i>	Manitoba Maple	10	On-site	Fair	lean, minor dieback	1.8	Preserve
4189	<i>Acer negundo</i>	Manitoba Maple	15	On-site	Fair	lean, minor dieback	1.8	Preserve
4190	<i>Ulmus pumila</i>	Siberian Elm	16	On-site	Poor	Poor form, dieback	1.8	Preserve
4191	<i>Ulmus pumila</i>	Siberian Elm	18,11,10	On-site	Fair	epicormics, branch/twig dieback	1.8	Preserve
4192	<i>Ulmus pumila</i>	Siberian Elm	14	On-site	Fair-Poor	branch dieback	1.8	Preserve
4193	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair-Poor	branch dieback	1.8	Preserve
4194	<i>Ulmus pumila</i>	Siberian Elm	15	On-site	Fair	twig dieback	1.8	Preserve
4195	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair	twig dieback	1.8	Preserve
4196	<i>Ulmus pumila</i>	Siberian Elm	18,18	On-site	Fair	epicormics, branch/twig dieback	1.8	Preserve
4197	<i>Robinia pseudo-acacia</i>	Black Locust	31	On-site	Fair		2.4	Preserve
4198	<i>Robinia pseudo-acacia</i>	Black Locust	33	On-site	Fair	vine in crown	2.4	Preserve
4199	<i>Robinia pseudo-acacia</i>	Black Locust	14	On-site	Fair		1.8	Preserve
4200	<i>Robinia pseudo-acacia</i>	Black Locust	22	On-site	Fair		1.8	Preserve
4201	<i>Robinia pseudo-acacia</i>	Black Locust	28	On-site	Fair		1.8	Preserve
4202	<i>Robinia pseudo-acacia</i>	Black Locust	28,28	On-site	Fair		2.4	Preserve
4203	<i>Robinia pseudo-acacia</i>	Black Locust	23	On-site	Fair		1.8	Preserve
4204	<i>Robinia pseudo-acacia</i>	Black Locust	21	On-site	Fair		1.8	Preserve
4205	<i>Robinia pseudo-acacia</i>	Black Locust	25	On-site	Fair		1.8	Preserve
4206	<i>Ulmus pumila</i>	Siberian Elm	16	On-site	Fair		1.8	Preserve
4207	<i>Ulmus pumila</i>	Siberian Elm	13	On-site	Poor	poor form, extensive epicormics	1.8	Preserve
4208	<i>Robinia pseudo-acacia</i>	Black Locust	32	On-site	Fair	codominant leaders	2.4	Preserve
4209	<i>Acer negundo</i>	Manitoba Maple	17	On-site	Poor	severe lean	1.8	Preserve
4210	<i>Robinia pseudo-acacia</i>	Black Locust	15	On-site	Poor	poor form	1.8	Preserve
4211	<i>Acer negundo</i>	Manitoba Maple	13	On-site	Fair		1.8	Preserve
4212	<i>Robinia pseudo-acacia</i>	Black Locust	24	On-site	Fair		1.8	Preserve
4213	<i>Robinia pseudo-acacia</i>	Black Locust	24,17	On-site	Fair		2.4	Preserve
4214	<i>Robinia pseudo-acacia</i>	Black Locust	10	On-site	Fair-Poor		1.8	Preserve

4215	<i>Ulmus pumila</i>	Siberian Elm	30	On-site	Poor	extensive dieback	2.4	Preserve
4216	<i>Robinia pseudo-acacia</i>	Black Locust	24	On-site	Fair		1.8	Preserve
4217	<i>Ulmus pumila</i>	Siberian Elm	17	On-site	Poor	extensive epicormics	1.8	Preserve
4218	<i>Robinia pseudo-acacia</i>	Black Locust	20	On-site	Fair-Poor	crowded, uneven crown	1.8	Preserve
4219	<i>Robinia pseudo-acacia</i>	Black Locust	24,25	On-site	Fair		2.4	Preserve
4220	<i>Acer negundo</i>	Manitoba Maple	27	On-site	Poor	poor form, crowded	1.8	Preserve
4221	<i>Robinia pseudo-acacia</i>	Black Locust	38	On-site	Fair		2.4	Preserve
4222	<i>Robinia pseudo-acacia</i>	Black Locust	41	On-site	Fair		3	Preserve
4223	<i>Robinia pseudo-acacia</i>	Black Locust	27	On-site	Fair		1.8	Preserve
4224	<i>Robinia pseudo-acacia</i>	Black Locust	25	On-site	Fair		1.8	Preserve
4225	<i>Acer negundo</i>	Manitoba Maple	11	On-site	Poor	trunk bent over, very poor form	1.8	Preserve
4226	<i>Robinia pseudo-acacia</i>	Black Locust	13,15	On-site	Fair	diverging trunks	1.8	Preserve
4227	<i>Robinia pseudo-acacia</i>	Black Locust	21,16	On-site	Fair	diverging trunks	1.8	Preserve
4228	<i>Robinia pseudo-acacia</i>	Black Locust	24,16	On-site	Fair	diverging trunks	2.4	Preserve
4229	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair-Poor	twig dieback, uneven crown	1.8	Preserve
4230	<i>Acer negundo</i>	Manitoba Maple	13	On-site	Fair	lean	1.8	Preserve
4231	<i>Robinia pseudo-acacia</i>	Black Locust	26	On-site	Fair		1.8	Preserve
4232	<i>Robinia pseudo-acacia</i>	Black Locust	16	On-site	Poor	poor form, severe bend	1.8	Preserve
4233	<i>Acer negundo</i>	Manitoba Maple	14	On-site	Fair-Poor	severe lean	1.8	Preserve
4234	<i>Acer negundo</i>	Manitoba Maple	16	On-site	Fair-Poor	lean, crooked trunk, twig dieback	1.8	Preserve
4235	<i>Robinia pseudo-acacia</i>	Black Locust	11	On-site	Fair		1.8	Preserve
4236	<i>Robinia pseudo-acacia</i>	Black Locust	35	On-site	Fair-Good		2.4	Preserve
4237	<i>Acer negundo</i>	Manitoba Maple	10	Off-site - Municipal Right of Way	Fair	crooked trunk	1.8	Preserve
4238	<i>Acer negundo</i>	Manitoba Maple	28,23	Off-site - Municipal Right of Way	Poor	significant lean, one trunk cracked, poor form	2.4	Preserve
4239	<i>Ulmus americana</i>	White Elm	16	Off-site - Municipal Right of Way	Fair-Poor	poor form, crowded	1.8	Preserve
4240	<i>Acer negundo</i>	Manitoba Maple	30,34,15	On-site	Fair-Poor	fence embedded through trunk, heavily pruned, several trunks removed, old wounds at base, lean	3	Preserve
4241	<i>Acer negundo</i>	Manitoba Maple	14,14	On-site	Fair	embedded fence	1.8	Preserve
4242	<i>Acer negundo</i>	Manitoba Maple	17,15,14,12	On-site	Fair-Poor	poor form	2.4	Preserve
4243	<i>Acer negundo</i>	Manitoba Maple	19,23	On-site	Fair-Poor	poor form	1.8	Preserve
4244	<i>Robinia pseudo-acacia</i>	Black Locust	10	On-site	Fair		1.8	Preserve
4245	<i>Acer negundo</i>	Manitoba Maple	15	On-site	Poor	poor form, embedded fence	1.8	Preserve
4246	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Fair-Poor	one leader dead	1.8	Preserve
4247	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Poor	very poor form, nearly dead	1.8	Preserve
4248	<i>Acer negundo</i>	Manitoba Maple	11	On-site	Poor	overtopped by grape vine	1.8	Preserve
4249	<i>Acer negundo</i>	Manitoba Maple	27	On-site	Fair	fenced embedded in base of trunk, slight lean, uneven crown	1.8	Preserve
4250	<i>Acer negundo</i>	Manitoba Maple	30,23	On-site	Poor	one stem dead, poor form, uneven crown, branch dieback, split at base	3	Preserve
4251	<i>Ulmus pumila</i>	Siberian Elm	17,18	On-site	Fair-Poor	extensive epicormics, branch/twig dieback	1.8	Preserve
4254	<i>Ulmus pumila</i>	Siberian Elm	38	On-site	Fair-Poor	large dead branch, twig dieback, uneven crown	2.4	Preserve
4255	<i>Ulmus pumila</i>	Siberian Elm	44	On-site	Fair-Poor	crowded, uneven crown, branch dieback	3	Preserve
4256	<i>Ulmus pumila</i>	Siberian Elm	52	On-site	Fair	several large dead branches, twig dieback	3.6	Preserve
4257	<i>Ulmus pumila</i>	Siberian Elm	25	On-site	Poor	poor form, uneven crown, branch dieback	1.8	Preserve

4258	<i>Ulmus pumila</i>	Siberian Elm	18	On-site	Poor	poor form, twig dieback, epicormics	1.8	Preserve
4259	<i>Ulmus pumila</i>	Siberian Elm	22	On-site	Poor	poor form, twig dieback, epicormics	1.8	Preserve
4261	<i>Ulmus pumila</i>	Siberian Elm	32	Off-site - Municipal Park	Fair-Poor		2.4	Preserve
4262	<i>Ulmus pumila</i>	Siberian Elm	15	On-site	Poor		1.8	Preserve
4263	<i>Ulmus pumila</i>	Siberian Elm	36	On-site	Fair-Poor	uneven crown, twig dieback	2.4	Preserve
4264	<i>Ulmus pumila</i>	Siberian Elm	27	On-site	Poor	trunk arched over	1.8	Remove - development/poor condition
4265	<i>Ulmus pumila</i>	Siberian Elm	52	On-site	Fair-Poor	many broken branches, twig dieback, uneven crown	3.6	Remove - development/poor condition
4266	<i>Ulmus pumila</i>	Siberian Elm	50	On-site	Poor	extensive epicormics, reduced crown, broken branches	3.6	Remove - development/poor condition
4267	<i>Ulmus pumila</i>	Siberian Elm	50	On-site	Poor	extensive epicormics, reduced crown, broken branches	3.6	Remove - development/poor condition
4268	<i>Acer platanoides</i>	Norway Maple	17	On-site	Fair-Poor	uneven crown, thin crown	1.8	Remove - development/poor condition
4269	<i>Acer platanoides</i>	Norway Maple	18,12 (22)	On-site	Poor	crowded, poor form, tops bent	1.8	Remove - development/poor condition
4272	<i>Ulmus pumila</i>	Siberian Elm	20	On-site	Fair	uneven crown, twig dieback	1.8	Preserve
4274	<i>Acer negundo</i>	Manitoba Maple	26	On-site	Poor	severe lean over adjacent parking lot	1.8	Preserve
4275	<i>Acer negundo</i>	Manitoba Maple	22	On-site	Poor	severe lean over adjacent parking lot	1.8	Remove - development/poor condition
4276	<i>Acer negundo</i>	Manitoba Maple	27	On-site	Poor	poor form, significant bend in trunk	1.8	Preserve
4277	<i>Acer negundo</i>	Manitoba Maple	50,35	Off-site - Municipal Park	Fair-Poor	significant lean, widely diverging trunks, branch dieback	4.2	Preserve
4278	<i>Acer negundo</i>	Manitoba Maple	33	On-site	Poor	poor form, branch dieback, cavity @ 6 m	2.4	Preserve
4279	<i>Pinus resinosa</i>	Red Pine	40	On-site	Dead		3	Preserve
4280	<i>Pinus sylvestris</i>	Scotch Pine	32	On-site	Dead		2.4	Preserve
4281	<i>Pinus sylvestris</i>	Scotch Pine	28	Off-site - Municipal Park	Dead		-	Preserve
4282	<i>Acer negundo</i>	Manitoba Maple	22	On-site	Poor	significant lean	1.8	Preserve
4283	<i>Pinus sylvestris</i>	Scotch Pine	25	On-site	Dead		-	Preserve
4284	<i>Acer negundo</i>	Manitoba Maple	26,34 (42)	On-site	Poor	severe lean/fallen over	3	Remove - development/poor condition
4285	<i>Acer negundo</i>	Manitoba Maple	42	On-site	Fair-Poor	dead/broken leaders, lean, uneven crown, four woodpecker holes at top of dead leader	3	Remove - development/poor condition
4286	<i>Picea abies</i>	Norway Spruce	30	Off-site - Municipal Park	Fair-Poor	uneven crown, crowded, twig dieback	2.4	Preserve
4287	<i>Picea abies</i>	Norway Spruce	50	Off-site - Municipal Park	Fair	uneven crown, crowded	3.6	Preserve
4288	<i>Picea abies</i>	Norway Spruce	36	Off-site - Municipal Park	Fair	uneven crown, crowded	2.4	Preserve
4290	<i>Picea abies</i>	Norway Spruce	20	Off-site - Municipal Park	Dead		-	Remove - dead
4291	<i>Picea abies</i>	Norway Spruce	46	Off-site - Municipal Park	Fair	uneven crown, crowded	3	Preserve
4292	<i>Picea abies</i>	Norway Spruce	29	Off-site - Municipal Park	Fair	uneven crown, crowded	1.8	Preserve
4294	<i>Acer negundo</i>	Manitoba Maple	19	Off-site - Municipal Park	Poor	severe lean/fallen over	1.8	Remove - development/poor condition
4298	<i>Picea abies</i>	Norway Spruce	50	Off-site - Municipal Park	Fair-Good		3.6	Preserve
4299	<i>Picea abies</i>	Norway Spruce	34	Off-site - Municipal Park	Dead	uneven crown, crowded	2.4	Remove - dead

Attachment C
