







MAINTENANCE SCHEDULE

-INSPECT AFTER EVERY MAJOR RAIN EVENT.
-INSPECT EVERY 3 WEEKS MINIMUM.
-SILTSACK SHOULD NEVER BE OVER HALF FULL.
-FULL BAG CAN BE REMOVED, DUMPED, CLEANED AND REUSED (TO REMOVE INSERT 25mm REBAR INTO REMOVAL FLAP POCKETS) (TO DUMP INSERT 25mm REBAR INTO BOTH DUMPING STRAPS)

SILTSACK DETAIL

N.T.S.

No.	REVISIONS	DATE	BY
2	ISSUED FOR ZONING	NOV. 13, 2026	R.B.T.M.
1	ISSUED FOR ZONING	APR. 10, 2026	R.B.T.M.

REGISTERED PROFESSIONAL ENGINEER
R.B.T. MERWIN
100009772
NOV. 13, 2026
PROVINCE OF ONTARIO

URBANTECH
Urbantech® Consulting
A Division of Leighton-Zec Ltd.
2030 Bristol Circle, Suite 105
Oakville, ON. L6H 0H2
TEL 905.829.8818 • urbantech.com

2233 & 2235 HURONTARIO LTD.

Region of Peel
working with you

MISSISSAUGA

EROSION & SEDIMENT CONTROL DETAILS

REGION FILE No. C-XXXXXX			CITY FILE No. OZ 26-8 W7
SCALE: N.T.S		PROJECT No.	24-326
DRAWN BY: R.B.	CHECKED BY: R.M./R.B.T.M	PLAN No.	**C502**
DATE: MARCH, 2026	SHEET OF	C-XXXXXX	

File: C:\USERS\RBABAR\DC\ACCDOCS\URBANTECH\24-326 2233 HURONTARIO ST\PROJECT FILES\1000 - EROSION\502-ESC DETAILS.DWG

PLOT DATE:November 13, 2026 11:33:19 AM