TREE INVENTORY TABLE

Tree No.	Scientific Name	Common Name	DBH (cm)	Crown Diameter (m)	Condition	Comments	Ownership	TPZ Radius (m)	Recommendation
144	*Picea glauca*	White Spruce	30	6.5	Fair	Smothered in grapevines; Good form.	City (Public Natural Area MVS)	1.8	Preserve
147	*Picea glauca*	White Spruce	20	4	Poor-Fair	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.5	Preserve
148	*Picea glauca*	White Spruce	25	5	Poor-Fair	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.8	Preserve
401	*Picea pungens*	White Spruce	48	6.5	Fair	Good form; Tip dieback.	City (Public Natural Area MVS)	3.0	Preserve (with injury)
404	*Acer platanoides*	Norway Maple	30	7	Poor	Dieback and thinning; Decay on south side of trunk.	Subject Property	N/A	Remove Due to Development
405	*Gleditsia triacanthos*	Honey Locust	47	10	Fair-Good	Good form and vigour; Construction activity and materials inside TPZ.	Subject Property	N/A	Remove Due to Development
409	*Gleditsia triacanthos*	Honey Locust	39	8	Good	Good form and vigour	Subject Property	N/A	Remove Due to Development
410	*Gleditsia triacanthos*	Honey Locust	19	6	Good	Good form and vigour	Subject Property	N/A	Remove Due to Development
411	*Gleditsia triacanthos*	Honey Locust	15	N/a	Dead	Standing snag.	Subject Property	N/A	Remove Due to Development
412	*Gleditsia triacanthos*	Honey Locust	29	7	Good	Good form and vigour	Subject Property	N/A	Remove Due to Development
413	*Abies lasiocarpa*	Siberian Cedar/apple	28	4	Poor-Fair	Dieback and thinning; Epicormic shoots along trunk.	Subject Property	N/A	Remove Due to Development
414	*Gleditsia triacanthos*	Honey Locust	25	6	Good	Good form and vigour; Signs of construction activities within TPZ.	Subject Property	N/A	Remove Due to Development
415	*Gleditsia triacanthos*	Honey Locust	38	6.5	Good	Good form and vigour	Subject Property	N/A	Remove Due to Development
416	*Gleditsia triacanthos*	Honey Locust	15	4.5	Good	Good form and vigour	Subject Property	N/A	Remove Due to Development
417	*Picea glauca*	White Spruce	45	7	Fair	Smothered in grapevines; Construction activity and debris on north side of trunk; Good form.	Subject Property	3.0	Preserve
418	*Picea glauca*	White Spruce	44	8	Fair	Smothered in grapevines; Good form.	Subject Property	3.0	Preserve
419	*Picea glauca*	White Spruce	25	7	Fair-Good	Some grapevines throughout canopy; Good form and vigour.	Subject Property	1.8	Preserve
420	*Pinus sylvestris*	Eastern White Pine	40	6	Fair-Good	Some grapevines throughout canopy; Good form and vigour.	Subject Property	3.0	Preserve
421	*Pinus sylvestris*	Eastern White Pine	19	5	Fair	Smothered in grapevines.	Subject Property	1.5	Preserve (with injury)
423	*Pinus sylvestris*	Eastern White Pine	18	5	Fair	Smothered in grapevines.	Subject Property	1.5	Preserve
424	*Pinus sylvestris*	Eastern White Pine	15	5	Poor-Fair	Dieback and thinning.	Subject Property	1.5	Preserve
425	*Picea glauca*	White Spruce	34	6	Poor-Fair	Co-dominate stems; Suppressed by neighbouring trees; Girdling by rope tied near base; Construction equipment inside TPZ.	Subject Property	N/A	Remove Due to Development
426	*Picea glauca*	White Spruce	16, 17 (23)	5	Poor-Fair	Co-dominate stems; Suppressed by neighbouring trees; Mechanical damage on east side of smaller trunk; Construction equipment inside TPZ.	Subject Property	1.8	Preserve (with injury)
427	*Picea glauca*	White Spruce	32	6.5	Fair-Good	Smothered in grapevines; Construction activity and debris on north side of trunk; Good form.	City (Public Natural Area MVS)	1.8	Preserve
428	*Picea glauca*	White Spruce	36	5	Fair-Good	Smothered in grapevines; Good form.	Subject Property	1.8	Preserve (with injury)
430	*Picea glauca*	White Spruce	25	5	Fair-Good	Some grapevines throughout canopy; Good form and vigour.	Subject Property	1.8	Preserve
431	*Pinus sylvestris*	Eastern White Pine	21	6	Fair-Good	Good form and vigour; Slightly suppressed by neighbouring trees and vines; Construction equipment inside TPZ.	City (Public Natural Area MVS)	1.8	Preserve
433	*Picea glauca*	White Spruce	21	N/a	Dead	Standing snag.	City (Public Natural Area MVS)	1.8	Preserve
434	*Pinus sylvestris*	Eastern White Pine	20	5	Fair	Good form; Suppressed by neighbouring trees and vines.	City (Public Natural Area MVS)	1.5	Preserve
436	*Picea glauca*	White Spruce	20	5	Poor	Smothered in grapevines; Dieback and thinning.	Subject Property	1.5	Preserve
437	*Pinus sylvestris*	Eastern White Pine	38	6	Fair	Good form; Suppressed by neighbouring trees; Construction equipment inside TPZ; Metal frame screwed into tree trunk.	Subject Property	N/A	Remove Due to Development
438	*Pinus sylvestris*	Eastern White Pine	23	6	Fair-Good	Good form and vigour; Slightly suppressed by neighbouring trees.	Subject Property	N/A	Remove Due to Development
440	*Pinus sylvestris*	Eastern White Pine	28	5	Fair	Good form; Suppressed by neighbouring trees.	Subject Property	1.8	Preserve
441	*Picea glauca*	Blue Spruce	53	10	Poor-Fair	Dieback and thinning; Suppressed by neighbouring trees and vines.	Subject Property	3.0	Preserve (with injury)
442	*Picea glauca*	White Spruce	28	8	Poor-Fair	Dieback and thinning; Suppressed by neighbouring trees and vines.	Subject Property	1.8	Preserve (with injury)
443	*Picea glauca*	White Spruce	42	9	Poor	Dieback and thinning; Suppressed by neighbouring trees and vines.	Subject Property	3.0	Preserve (with injury)
444	*Picea glauca*	White Spruce	46	N/a	Dead	Standing snag.	City (Public Natural Area MVS)	N/A	Remove due to Development
445	*Picea glauca*	White Spruce	38	6	Fair	Good form; Smothered by grapevines.	City (Public Natural Area MVS)	2.4	Preserve
448	*Fraxinus pennsylvanica*	Green Ash	23	N/a	Dead	Standing snag.	Subject Property	N/A	Remove Due to Development
449	*Quercus rubra*	Northern Red Oak	53	10	Good	Good form and vigour; Growing on slight lean to the east.	City (Public Natural Area MVS)	3.6	Preserve (with injury)
450	*Fraxinus pennsylvanica*	Green Ash	34	4	Poor	Nearly dead.	Subject Property	2.4	Preserve
451	*Acer saccharum*	Sugar Maple	63	16	Good	Good form and vigour	City (Public Natural Area MVS)	5.4	Preserve (with injury)
452	*Acer saccharum*	Sugar Maple	58	14	Good	Good form and vigour	Subject Property	3.6	Preserve
453	*Acer saccharum*	Sugar Maple	62	12	Good	Good form and vigour	Subject Property	4.2	Preserve
454	*Ulmus americana*	White Elm	18	3	Poor	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.5	Preserve
455	*Acer saccharum*	Sugar Maple	17	5	Fair-Good	Good for and vigour; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	1.5	Preserve
456	*Acer saccharum*	Sugar Maple	72, 71 (101)	20	Poor	Large open wound on stem with significant decay; Dieback and thinning.	City (Public Natural Area MVS)	6.0	Preserve
457	*Acer saccharum*	Sugar Maple	68	20	Fair-Good	Good for and vigour; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	4.2	Preserve
458	*Acer saccharum*	Sugar Maple	115	25	Good	Healthy mature tree; Good root flare and branching structure; No major defects observed.	City (Public Natural Area MVS)	6.9	Preserve
459	*Quercus rubra*	Northern Red Oak	70	12	Fair	Good form; Some dieback and thinning.	City (Public Natural Area MVS)	4.2	Preserve (with injury)
460	*Quercus rubra*	Northern Red Oak	40	9	Fair-Good	Good form; Minor dieback.	City (Public Natural Area MVS)	3.0	Preserve
461	*Quercus macrocarpa*	Bur Oak	36	5	Fair	Suppressed by neighbouring trees.	City (Public Natural Area MVS)	1.8	Preserve
462	*Quercus rubra*	Northern Red Oak	28	9	Good	Good form and vigour	City (Public Natural Area MVS)	2.4	Preserve
463	*Quercus rubra*	Northern Red Oak	28	10	Good	Good form and vigour	City (Public Natural Area MVS)	1.8	Preserve
464	*Quercus macrocarpa*	Bur Oak	33	10	Fair-Good	Good form and vigour; Sapsucker holes along trunk.	City (Public Natural Area MVS)	2.4	Preserve
465	*Quercus macrocarpa*	Bur Oak	32	7	Fair-Good	Good form; Minor dieback and thinning.	City (Public Natural Area MVS)	1.8	Preserve
466	*Quercus rubra*	Northern Red Oak	36	9	Good	Good form and vigour	City (Public Natural Area MVS)	1.8	Preserve
467	*Quercus macrocarpa*	Bur Oak	33	10	Fair	Good form; Epicormic shoots along trunk; Minor thinning.	City (Public Natural Area MVS)	2.4	Preserve
471	*Acer platanoides*	Norway Maple	33	8	Fair-Good	Good form and vigour; Minor tarspot; Construction activity inside TPZ.	Subject Property	N/A	Remove Due to Development
487	*Rhamnus cathartica*	European Buckthorn	21	5	Poor-Fair	Smothered in grapevines; Dieback and thinning.	Subject Property	N/A	Remove Due to Development
1301	*Fraxinus pennsylvanica*	Green Ash	17	3	Poor	Nearly dead; Infested with EAB.	Subject Property	1.5	Preserve
1302	*Picea glauca*	White Spruce	28	6	Fair	Smothered in grapevines; Good form.	City (Public Natural Area MVS)	1.8	Preserve
1303	*Picea glauca*	White Spruce	20	6	Poor-Fair	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.5	Preserve
1304	*Acer negundo*	Manitoba Maple	23	7	Fair	Good vigour; Growing horizontally towards the west.	City (Public Natural Area MVS)	1.8	Preserve
1305	*Picea glauca*	White Spruce	32	6	Poor-Fair	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	2.4	Preserve
1306	*Picea glauca*	White Spruce	22	4	Poor-Fair	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.8	Preserve
1307	*Picea glauca*	White Spruce	31	N/a	Dead	Standing snag.	Subject Property	2.4	Preserve
1308	*Picea glauca*	White Spruce	28	5	Poor	Smothered in grapevines; Dieback and thinning.	City (Public Natural Area MVS)	1.8	Preserve
1309	*Acer negundo*	Manitoba Maple	15	5	Fair	Good vigour; Mechanical wounds down east side of trunk.	Subject Property	1.5	Preserve
1310	*Picea glauca*	White Spruce	15	N/a	Dead	Standing snag.	Subject Property	1.5	Preserve
1311	*Picea glauca*	White Spruce	16, 15 (22)	6	Fair	Good vigour; Slightly suppressed by neighbouring trees and vines; Co-dominate stems; Mechanical damage on east side of trunk; Construction equipment inside TPZ.	Subject Property	1.8	Preserve
1312	*Acer negundo*	Manitoba Maple	15	6	Fair-Good	Good vigour; Slight lean to the west.	City (Public Natural Area MVS)	1.5	Preserve
1313	*Acer negundo*	Manitoba Maple	16	5	Good	Good form and vigour.	City (Public Natural Area MVS)	1.5	Preserve
1314	*Pinus sylvestris*	Eastern White Pine	27	6	Poor-Fair	Dieback and yellowing foliage; Construction equipment inside TPZ; Metal frame nailed into tree trunk; signs of decay around nails.	Subject Property	N/A	Remove Due to Development
1315	*Picea glauca*	White Spruce	35	7	Fair	Good form; Slightly suppressed by neighbouring trees and vines.	City (Public Natural Area MVS)	2.4	Preserve (with injury)
1316	*Picea glauca*	White Spruce	22	5	Poor	Dieback and thinning.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1317	*Picea glauca*	White Spruce	25	N/a	Dead	Standing snag.	City (Public Natural Area MVS)	1.8	Preserve
1318	*Pinus sylvestris*	Eastern White Pine	53	10	Good	Good form and vigour.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1319	*Picea glauca*	White Spruce	16, 14 (21)	N/a	Dead	Standing snag.	City (Public Natural Area MVS)	2.4	Preserve
1320	*Picea glauca*	White Spruce	19	5	Fair	Minor dieback and thinning.	City (Public Natural Area MVS)	1.5	Preserve
1321	*Picea glauca*	White Spruce	38	7	Fair	Minor dieback and thinning.	City (Public Natural Area MVS)	2.4	Preserve
1322	*Picea glauca*	White Spruce	46	8	Fair-Good	Good form and vigour.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1323	*Picea glauca*	White Spruce	28	7	Fair-Good	Good form; Minor thinning.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1324	*Picea glauca*	White Spruce	29	6	Fair	Good form; Minor thinning.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1325	*Picea glauca*	White Spruce	35	7	Fair	Good form; Minor thinning; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1326	*Picea glauca*	White Spruce	38	7	Fair-Good	Good form; Minor thinning; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	N/A	Remove Due to Development
1327	*Picea glauca*	White Spruce	38	8	Fair-Good	Good form; Minor thinning; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	2.4	Preserve
1328	*Picea glauca*	White Spruce	28	6	Fair	Good form; Minor thinning; Slightly suppressed by neighbouring trees.	City (Public Natural Area MVS)	2.4	Preserve
1329	*Picea glauca*	White Spruce	46	7	Fair	Good form; Suppressed by neighbouring trees and vines.	City (Public Natural Area MVS)	N/A	Preserve
1330	*Quercus rubra*	Northern Red Oak	50	11	Good	Good form and vigour.	City (Public Natural Area MVS)	3.0	Preserve
1361	*Acer negundo*	Manitoba Maple	21	9	Good	Good form and vigour.	Subject Property	1.8	Preserve (with injury)
1332	*Acer negundo*	Manitoba Maple	38	10	Fair	Good vigour; Growing horizontally towards the east.	Subject Property	N/A	Remove Due to Development
1333	*Picea glauca*	White Spruce	38	10	Poor	Dieback and thinning; Suppressed by neighbouring trees and vines.	City (Public Natural Area MVS)	2.4	Preserve (with injury)
1334	*Acer negundo*	Manitoba Maple	21	7	Fair	Lean to the south; Suppressed by neighbouring trees and vines.	Subject Property	N/A	Remove Due to Development
1335	*Acer negundo*	Manitoba Maple	22	9	Fair	Good vigour; Heavy lean to the east.	Subject Property	1.8	Preserve
1336	*Picea glauca*	White Spruce	26	6	Fair-Good	Good form and vigour; Construction activity and root damage inside the TPZ.	Subject Property	N/A	Remove Due to Development
1337	*Picea glauca*	White Spruce	19	4	Fair	Good form and vigour; Construction activity and root damage inside the TPZ; Suppressed by neighbouring trees.	Subject Property	N/A	Remove Due to Development
1338	*Picea glauca*	White Spruce	26	6	Fair	Good form and vigour; Construction activity and root damage inside the TPZ; Mechanical damage on north side of trunk.	Subject Property	N/A	Remove Due to Development
1339	*Acer negundo*	Manitoba Maple	10, 11, 10, 8 (19)	6	Fair-Good	Good vigour; Co-dominate stems.	City (Public Natural Area MVS)	1.5	Preserve
1340	*Quercus macrocarpa*	Bur Oak	18	7	Fair	Good form; Dieback and thinning.	City (Public Natural Area MVS)	1.5	Preserve
1361	*Quercus rubra*	Northern Red Oak	28	10	Fair-Good	Good form and vigour; Girdling root on south side.	City (Public Natural Area MVS)	1.8	Preserve
1342	*Prunus serotina*	Black Cherry	15	6	Poor-Fair	Suppressed by neighbouring trees and vines.	City (Public Natural Area MVS)	1.5	Preserve
1343	*Acer platanoides*	Norway Maple	39	8	Fair	Tree appears to have been previously topped. Good vigour; Construction activity inside TPZ; Construction sign nailed to trunk.	Subject Property	N/A	Remove Due to Development
1344	*Acer platanoides*	Norway Maple	43	9	Fair	Good form vigour; Construction activity and materials inside TPZ; Construction sign nailed to trunk; Mechanical damage on north side of trunk.	Subject Property	N/A	Remove Due to Development
1345	*Quercus macrocarpa*	Bur Oak	17	9	Fair	Good form; Dieback and thinning.	Subject Property	N/A	Remove Due to Development

02830-6

Hoarding
Framed Protective Construction Hoarding
Solid Board- Plastic Snow Fence

NOTE:
TO BE USED AS A GUIDELINE ONLY.
NOT TO SCALE. REMOVE CITY TITLE BLOCK AND REDRAW TO REPRESENT SITE SPECIFIC CONDITIONS. ALL SITE SPECIFIC CONDITIONS ARE TO BE CONFIRMED BY THE PROJECT CONSULTANT.



NOTES:
1. HOARDING LOCATION AS PER DRAWINGS. HOARDING INSTALLATIONS ARE TO INCLUDE WOVEN GEOTEXTILE FABRIC FOR SEDIMENT CONTROL.
2. NO MOBILIZATION OR CONSTRUCTION WORK TO OCCUR UNTIL HOARDING HAS BEEN INSPECTED AND APPROVED BY COMMUNITY SERVICES PROJECT MANAGER (CSPM). CONTRACTOR TO ARRANGE FOR A HOARDING INSPECTION WITH (CSPM), 48 HOUR NOTICE RQUIRED.
3. HOARDING TO BE SUPPLIED, INSTALLED AND MAINTAINED BY THE CONTRACTOR THROUGH ALL PHASES OF WORK ON SITE.
4. THE CONTRACTOR IS TO REMOVE AND DISPOSE THE HOARDING OFF SITE WHEN DIRECTED BY THE (CSPM).
5. ALL WOOD PRODUCTS TO BE NEW AND LUMBER KILN DRIED SPF.
6. ALL FASTENERS TO BE NEW GALVANIZED STEEL AND SECURELY INSTALLED. WIRE TIES MIN 3.5mm DIA. GALVANIZED STEEL
7. DO NOT ALLOW WATER TO COLLECT AND/OR POND ON EITHER SIDE OF THE HOARDING.
8. WHEN INSTALLING DIRECT BURY TIMBER POSTS AND T-BARS, TAKE CARE TO AVOID VISIBLE AND ASCERTAINABLE TREE ROOTS.
9. PLACE HOARDING AT LIMIT OF TREE CANOPY DRIP LINE OR BEYOND (E.G. FURTHER AWAY FROM TRUNK) OF TREE.
10. HOARDED OFF AREA TO REMAIN UNDISTURBED. NO STOCKPILING, STAGING OR MOVEMENT OF VEHICLES TO OCCUR WITHIN PROTECTED AREA.
11. FOR PROTECTION OF TREE'S AND ROOT SYSTEM, CONTRACTOR MAY BE REQUIRED TO PROVIDE WATERING, MULCHING, FERTILIZING, PRUNING OR OTHER ACTIVITIES TO ENSURE THE HEALTH OF THE TREE(S).
12. ALL MEASUREMENTS IN MILLIMETRES UNLESS NOTED OTHERWISE (E.G. DIMENSIONAL LUMBER).
13. CONTRACTOR RESPONSIBLE FOR LOCATES

N.T.S.

Detail: 02830-6

ORIGINAL DATE: Mar 08/18
REVISION DATE: Mar 08/18

MISSISSAUGA



LEGEND

Notes: Scale shown is for an 36" x 24" page.
For illustrative purposes. Do not scale

Nº	REVISIONS	DATE:	BY:
6			
5			
4			
3			
2			
1	COMMENT	xxxxxx/xx	xx

SCALE

NORTH ARROW

CERTIFIED ARBORIST ISA
Holly Benaurt
#ON-2005A

BEACON ENVIRONMENTAL
MARKHAM OFFICE
80 MAIN ST NORTH
MARKHAM, ON L3P 1X5
T) 905.201.1622
F) 905.201.0639
www.beaconenviro.com

CLIENT
DIBLASIO HOMES

PROJECT
BLOCK 21 VINTAGES

SHEET TITLE
TREE INVENTORY AND PRESERVATION PLAN

DESIGN BY: –	PROJECT Nº: 215194
DRAWN BY: MB	FIGURE Nº: TP-2
CHECKED BY: DW	
DATE: 28 November 2024	