PROJECT NO.: SM 260253-E

JUNE 8, 2026

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
60 HARBORN ROAD
MISSISSAUGA, ONTARIO

PREPARED FOR:

W. E. OUGHTRED AND ASSOCIATES INC.

Soil-Mat

BY

SOIL-MAT ENGINEERS & CONSULTANTS LTD.
401 GRAYS ROAD
HAMILTON, ONTARIO
L8E 2Z3

PROJECT NO.: SM 260253-E

JUNE 8, 2026

PHASE ONE ENVIRONMENTAL SITE ASSESSMENT
60 HARBORN ROAD
MISSISSAUGA, ONTARIO

PREPARED FOR:

W. E. OUGHTRED AND ASSOCIATES INC.

BY

SOIL-MAT ENGINEERS & CONSULTANTS LTD.
401 GRAYS ROAD
HAMILTON, ONTARIO
L8E 2Z3

1.0 EXECUTIVE SUMMARY

The Phase One Environmental Site Assessment [ESA] conducted for this property consisted of a historical records review, interviews and a reconnaissance of the lands subject to the specific Phase One ESA research. The research and reporting were conducted in accordance with Ontario Regulation 153/04 [as amended] in order to support the future filing of a Record of Site Condition [RSC] for the property, if required. However, it is noted that based on the current and historical residential use of the property there would not be a requirement for an RSC filing under the Regulation for ongoing residential use, or future redevelopment for residential or commercial use. It is our understanding that the Phase One ESA Report is required as part of planning conditions for the Site.

At the time of this Report, the Phase One Property was comprised of a roughly rectangular shaped parcel of land located on the east side of Harborn Road between Premium Way and Autumn Breeze Drive South, and was recognized with the municipal address of 60 Harborn Road in the City of Mississauga, Ontario. Specifically, the Phase One Property was occupied by a two-storey brick dwelling, with a basement level, on the eastern portion of the property and an asphaltic-concrete driveway extending from Harborn Drive to the existing dwelling. The remainder of the Phase One Property was comprised primarily of grass covered areas, with trees lining the majority of the northern, southern, and eastern limits of the property.

The Phase One research, and reconnaissance of the Phase One Property, did not reveal any information that suggests there is an active or historical potentially contaminating activity [PCA] on the Phase One Property that is considered likely to cause an area of potential environmental concern [APEC].

The lands in the general vicinity of the Phase One Property were comprised of a mixture of residential, community, commercial and vacant undeveloped lands that based on the information currently available to SOIL-MAT ENGINEERS are not anticipated to cause an APEC on the Phase One Property.

Based on the findings of the Phase One Environmental Site Assessment, SOIL-MAT ENGINEERS & CONSULTANTS LTD. find the potential of Site contamination to be considered **LOW** and therefore recommend that additional investigations **ARE NOT** required at this time.

Although not considered an environmental liability to the Site, given the construction date of the building, it is possible that designated substances, such as asbestos containing materials, and ozone depleting substances, may be present in the buildings. As such, it is recommended that a non-intrusive designated substance survey of the buildings be undertaken before any planned demolition activities that may disturb building materials to identify where possible, designated substances that may be present in the buildings.

In addition, if a suspected groundwater well is encountered during future construction activities to make arrangements for the water well to be abandoned as per *Ontario Regulation 903 – Water Wells*.

2.0 INTRODUCTION

W.E. OUGHTRED AND ASSOCIATES INC. retained SOIL-MAT ENGINEERS & CONSULTANTS LTD. [SOIL-MAT ENGINEERS] to conduct a Phase One ESA for the property located at 60 Harborn Road in Mississauga, Ontario.

For the purpose of this Report, the lands subject to the specific Phase One ESA research are hereinafter referred to as the Phase One Property and/or the 'Site'.

2(A) PHASE ONE PROPERTY INFORMATION

The Phase One Property is comprised of the following parcel of land:

1. 60 Harborn Road, Mississauga, Ontario. The property identification number [PIN] is '13359-1321. The registered owner of the Site is "1000635365 Ontario Inc".

At the time of this Report, the Phase One Property was occupied by a two-storey brick dwelling, with a basement level, on the eastern portion of the Site and an asphaltic-concrete driveway extending from Harborn Drive to the existing dwelling. The remainder of the Phase One Property was comprised primarily of grass covered areas, with trees lining the majority of the northern, southern, and eastern limits of the Site.

The Site was bounded to the north by residential lands, to the east by a vacant, undeveloped lot, to the south by a dwelling which was utilized as retail commercial use space, and to the west by Harborn Road. In addition, "Mary Fix Creek" was observed to bisect the property located directly south of the Site.

The legal description of the Site is "Part Lot 1 Range 3 Credit Indian Reserve Toronto as in RO1104142 ; Mississauga".

The geographic coordinates of the Site, recorded using a hand held global positioning unit, are [NAD 83] 17T 612828E/ 4824892N.

A general site location drawing and overview of the Phase One Study Area are included in Appendix 'A' for reference.

2(b) DESCRIPTION OF ADJACENT LAND USE

The adjacent properties are comprised of a mixture of residential, community and retail commercial operations.

A description of the adjacent properties, based on visual observations recorded from the Site, is presented in table format on the following page:

	North	East	South	West
Adjoining Property/ Operation	Residential	Vacant undeveloped lot	Retail Commercial/ Residential, Mary Fix Creek	Harborn Road
Potential Hazardous Materials	None observed	None observed	None observed	None observed
Potential Storage Tanks	None observed	None observed	None observed	None observed
Direction with respect to the inferred ground water flow	Up-gradient	Trans-gradient	Down-gradient	Trans-gradient
General Vicinity	Residential, Community [St. Hilary's Church], Commercial [Starbucks, BSO Beauty Supply Outlet, Pharma Choice, Sanctuary Grooming Lounge, Onaré Salon, Harborn Dental, Rabba Fine Foods]	Residential, Commercial [Community Legal Services, Cooksville Service Centre, J&D Dry Cleaners], Queen Elizabeth Way	Residential	Residential

The visual observations of the adjoining lands did not reveal any obvious PCAs that are considered likely to cause an APEC on the Phase One Property.

3.0 SCOPE OF INVESTIGATION

The Phase One ESA follows the protocol outlined in *Ontario Regulation 153/04 [as amended]*, which suggests a four-step approach to Phase One Environmental Site Assessments, including the following;

1. RECORDS REVIEW: including aerial photographs, property use records, title search, previous Phase One ESA reports, regulatory agency documentation, company records, Site specific geotechnical reports and any other relevant material;

2. SITE VISITATION: including a visual reconnaissance of the Site, suspect adjacent properties, and the different land uses within the vicinity of the Site;

3. INTERVIEWS: including persons that may have pertinent information with regard to the Site, including contacts from the City of Mississauga, Ministry of Environment, Conservation and Parks [MECP], and current / previous land owners, etc.;

4. EVALUATIONS: Based on the information gathered, a professional evaluation of the property is presented in a final Phase One ESA Report.

Ontario Regulation 153/04 [as amended] lists fifty-nine [59] potentially contaminating activities that require intrusive assessment activities, i.e. a Phase Two ESA, to determine if an adverse environmental impact is present on the Site if a PCA is found to have occurred on the Phase One Property. In some circumstances a Phase Two ESA may be required if a PCA has occurred on a neighbouring or nearby property within the Phase One Study Area if deemed necessary by the Qualified Person [QP] overseeing the Phase One ESA. However, it is noted that under *Ontario Regulation 153/04* [as amended] the mandatory Phase Two ESA activities apply only to properties that are subject to a Record of Site Condition [RSC] filing. It is our understanding that this Phase One ESA report is not required as a supporting document for the submission of a Record of Site Condition for the Site.

4.0 RECORDS REVIEW

4(a)i PHASE ONE ESA STUDY AREA DETERMINATION

The Phase One Study Area consists of the lands generally in a 250-metre radius from the limits of the Phase One Property. These lands are comprised primarily of a mixture of residential, community and retail commercial operations.

The research undertaken during this Phase One ESA did not reveal any information that suggests there is a PCA on one of these lands that may result in an APEC on the Phase One ESA property.

Additional information, specific to the nature of the land use of the properties of interest in the Phase One ESA Study Area, if any, is presented in Section 4(b), 4(c), and 6(b) of this Report.

4(a)ii FIRST DEVELOPED USE DETERMINATION

Based on the available information compiled during the completion of this Report, including City Directories, aerial photographs and topographic, etc., the Phase One Property was first developed circa 1938 to 1954 as residential use lands.

4(a)iii FIRE INSURANCE PLANS

The Underwriter's Survey Bureau Limited Fire Insurance Plans were reviewed for the purpose of identifying structures, building materials and/ or underground storage tanks that may have been present on, or near the Site. However, the Fire Insurance Plans [to date] do not include the vicinity of the Site.

4(a)iv CHAIN OF TITLE

A representative of SOIL-MAT ENGINEERS undertook a title search of the Site on the Ontario Land Registry Website [https://www.onland.ca/ui/].

The title search of the Site did not reveal any past owners of the Site that suggest there is a potential environmental liability on the Site.

The Site was owned by the numbered company '1000635365 Ontario Inc.' at the time of the title search.

The chain of previous ownership is presented in table format on the following page:

Years	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
2023 to Present	1000635365 Ontario Inc.	The Site was occupied by a dwelling.	Residential	• Our reconnaissance of the Site revealed a two-storey brick dwelling, with a basement level, on the eastern portion of the Site. • An aerial photograph from 2024, revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance].
1995 to 2003	Alexander Air	The Site was occupied by a dwelling.	Residential	• Aerial photographs from 1995, 2000, 2005, 2007, 2009, 2014 and 2018 revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance].
1986 to 1995	Ghulan Haider Khan & Farkahnda Shaheen Khan	The Site was occupied by a dwelling.	Residential	• Aerial photographs from 1989 and 1995, revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance]. • A topographic map from 1994 illustrates Phase One Property as developed.
1983 to 1986	John E. Kelly & Josephine Kelly	The Site was occupied by a dwelling.	Residential	• There were no readily available visual aids for the Phase One Property for this time period.
1982 to 1983	Betty J. Rogers	The Site was occupied by a dwelling.	Residential	• There were no readily available visual aids for the Phase One Property for this time period.
1979 to 1982	Konstantine Vlahos & Irene Vlahos	The Site was occupied by a dwelling.	Residential	• An aerial photograph from 1980, revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance]. • A topographic map from 1962 illustrates one building on the Phase One Property.
1979	Margaret D. McVicar, Catherine B. Hickey, George N. McVicar & Edward J. Hickey	The Site was occupied by a dwelling.	Residential	• There were no readily available visual aids for the Phase One Property for this time period.
1979	Margaret D. McVicar & Catherine B. Hickey	The Site was occupied by a dwelling.	Residential	• There were no readily available visual aids for the Phase One Property for this time period.
Unknown to 1979	Margaret D. McVicar & Catherine B. Hickey (Executives of Catherine H.	The Site was occupied by a dwelling.	Residential	• There were no readily available visual aids for the Phase One Property for this time period.

Years	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
	Mc. Jannett's Estate)			
1960 to Unknown	William H. McJannett	The Site was occupied by a dwelling.	Residential	• An aerial photograph from 1960, revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance].
1948 to 1960	The Director, The Veteran's Land Act	The Site was occupied by a dwelling.	Residential	• Aerial photographs from 1954 and 1966, revealed a dwelling on the Phase One Property [as observed during the Site reconnaissance].
1942 to 1948	William G. McJannett & Catharine H. McJannett	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1927 to 1942	Henry L. Tarbush & Wife	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1938 illustrates the Phase One Property as vacant undeveloped lands.
1919 to 1927	Arthur L. Gordon & Wife	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
Unknown to 1919	Burgoyne Gordon & Wife, Ottilie Rubidge & Beaumont Gordon	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1909 illustrates the Phase One Property as vacant undeveloped lands.
1907 to Unknown	May Elizabeth Gordon	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1909 illustrates the Phase One Property as vacant undeveloped lands.
1883 to 1907	Melville Parker	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1878 to 1883	Lady M.J. Parker	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
Up to 1878	The Crown	The Phase One Property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.

4(a)v ENVIRONMENTAL REPORTS

SOIL-MAT ENGINEERS contacted the City of Mississauga to request a copy of previous environmental reports for the Site that may be on file with the City. However, the results were not available during the completion of this Report.

In addition, a search of the MOE's *Brownfields Environmental Site Registry* did not reveal a previous Phase One ESA that may have been undertaken on the Site.

Our request for information with the City is included in Appendix 'C' of this Report for reference.

4(a)VI HISTORICAL SITE USE AND CONDITIONS/PAST LAND USES

The Criss Cross City Directory series were reviewed dating back to 1968 [the earliest available year that the Phase One Study Area is listed] to establish the general historical land use on and in the immediate vicinity of the Site. It is noted that the 2001 directory is the most recent readily available directory for the Site and surrounding area.

A summary of SOIL-MAT ENGINEERS' findings for the Site is provided below:

Occupant	Years Occupied
Alexander D. Air	5+ years [1996 – 2001]
Not Listed	8+ year[s] [1983 – 1991]
C. Egleston	1+ years [1979]
William G. McJannett	7+ years [1968 – 1975]
William G. McJannett & P. Kieller	1+ years [1971]

The directories do not list any current or past occupant of the Site that should be considered a potentially contaminating activity that may result in an area of potential environmental concern on the Site.

In addition to the above, a review of the Criss Cross City Directory series did not list any current or past occupant of the adjacent lands that should be considered a PCA likely to cause an APEC on the Site.

4(b) ENVIRONMENTAL SOURCE INFORMATION

1. National Pollutant Release Inventory: One record was identified on a property in the Phase One Study Area, located approximately 225 metres north of the Site. Given the location of the property to the Site with respect to the inferred groundwater flow direction [trans-gradient] and the distance between the property and the Site an adverse environmental impact to the Site is considered remote.

2. A review of the Ministry of Environment and Energy's "Ontario Inventory of PCB Storage Sites", October, 1991, did not reveal any PCB Storage Sites within 1.5 kilometres of the site.

   It is noted that although the inventory is considered a comprehensive document not all of the storage sites are listed in the inventory.

3. Environmental Compliance Approvals, Permit to Take Water, Certificate of Property Use: One record was identified in the Phase One Study Area, located approximately 230 metres west-northwest from the Site. The record indicates that the approval was issued to conduct storm and sanitary sewer construction on Grange Drive which is not anticipated to cause an APEC on the Site.

4. Coal Gasification Plants: No records were found for the Site or properties within the Phase One Study Area.

5. Records Concerning Environmental Incidents, Orders, Offences, Spills, Discharges of Contaminants or Inspections Maintained by the MECP: The MECP's Freedom of Information and Protection of Privacy Office was contacted to determine if any spills have been reported in the area of the Site, if any buried tanks are recorded to be on-site, or if there are any orders and/or notices on file outstanding against the Owner of the Site. The results of the Ministry Search confirmed there were no records found within their database.

   SOIL-MAT ENGINEERS' MECP database search request is attached in Appendix 'D' for reference.

6. Waste Management Records: No records were found for the Site. However, seven [7] waste generator records were found for properties within the Study Area. However, a review of the available waste generator information did not reveal any information that is considered a PCA likely to cause an APEC on the Site.

7. Reports Submitted to the MOE: A review of the ERIS EcoLog report identified eleven [11] records of spills within the Phase One Study Area, ranging approximately 45 metres to 200 metres from the Phase One Property.

   Given the location of the spills to the Site with respect to the inferred groundwater flow direction [up, trans and down-gradient] and the distance between the spills and the Site an adverse environmental impact to the Site is considered remote.

   With respect to the spill located approximately 45 meters from the Phase One Property. Although this spill occurred up-gradient of the Site, the available record indicates the spill was a 'natural gas vapour' release. As such, this release is not considered a PCA likely to cause an APEC on the Site.

8. Retail Fuel Storage Tanks: SOIL-MAT ENGINEERS contacted the T.S.S.A. to undertake a search of the Site and neighbouring properties for the registered presence of any underground storage tanks. The T.S.S.A does not have records on file of any underground storage tanks located on the Site or neighbouring properties.

   It is however noted that the T.S.S.A. does not have records of USTs installed prior 1987. In addition, "private use" USTs were not registered with the agency until 1990, and even then many owners of "private use" USTs do not register the tanks with T.S.S.A.

   SOIL-MAT ENGINEERS' correspondence with the T.S.S.A. is included in Appendix 'E' for reference.

   In addition to the above, our review of the EcoLog ERIS Database search revealed a commercial fuel oil tank located approximately 48 metres [down-gradient] and 193 metres [trans-gradient] from the Phase One Property. Given the location of the properties to the Site with respect to the inferred groundwater flow direction and the distance between the properties and the Site, an adverse environmental impact to the Site is considered remote.

9. Notices and Instruments Posted to the MOE Registry: No records were found for the Site.

10. Identification of Areas of Natural Significance [Ministry of Natural Resources]: No records were found for area(s) of natural significance on the Site or adjacent properties.

11. Landfill Information Maintained by the MOE: A review of the Ministry of Environment and Energy's "Waste Disposal Site Inventory", June 1991, did not reveal any active or inactive landfills site within a 2km radius of the Site.

    It is noted that although the waste disposal site inventory is considered a ccomprehensive document not all of the inactive landfill sites are listed in the inventory.

    In addition, no Municipal Coal Gasification Plants or Coal Tar Distillation Plants were in operation in the area.

12. EcoLog ERIS Database Search: A review of historical records and regulatory agency databases was completed for the Site and lands located within 300 metres from the boundaries of the Phase One Property. The report includes information from the following sources:

    - Abandoned Aggregate Inventory
    - Aggregate Inventory
    - Borehole
    - Certificates of Approval
    - Environmental Registry
    - ERIS Historical Searches
    - Fuel Storage Tanks
    - Ontario Regulation 347 Waste Generators Summary
    - Private and Retail Fuel Storage Tanks
    - Record of Site Conditions
    - Ontario Spills
    - Water Well Information Systems

    The EcoLog ERIS database search report revealed limited PCAs on nearby properties. However, given the location of these properties to the Site with respect to the inferred groundwater flow direction and distance between these properties and the Site an adverse environmental impact to the Site is considered remote.

    A copy of the EcoLog ERIS Report is included in Appendix 'F' for reference.

4(C) PHYSICAL SETTING SOURCES

1. Aerial Photographs: Aerial photographs from 1954, 1966, 1980, 1989, 1995, 2000, 2005, 2007, 2009, 2014, 2018 and 2024 were available for the Site and surrounding lands and were reviewed by SOIL-MAT ENGINEERS.

   A summary of information obtained from the photographs is presented on the following page:

Aerial Photo Date [Scale]	Site Description	Description of Adjacent Lands
1954 [1:2,257]	The Site is occupied by a dwelling. The remainder of the Site is comprise of open space.	The surrounding lands include a mixture of residential, forested, and agricultural uses. Mary Fix Creek is present to the south and the Queen Elizabeth Way is located to the southeast.
1966 [1:4,514]	There are no significant changes to the Site.	Nearby agricultural lands have been developed as residential use lands.
1980 [1:4,514]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
1989 [1:4,514]	A driveway, from Harborn Road to the dwelling is present. With the exception of the above, there are no significant changes to the Site.	There are no significant changes to the surrounding lands.
1995 [1:4,514]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
2000 [1:4,514]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
2005 [1:1,585]	There are no significant changes to the Site.	There is a commercial development present to the north of the Site.
2007 [1:1,975]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
2009 [1:1,943]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
2014 [1:1,128]	There are no significant changes to the Site.	With the exception of residential development to the north, there are no significant changes to the surrounding lands.
2018 [1:1,128]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.
2024 [1:4,514]	There are no significant changes to the Site.	There are no significant changes to the surrounding lands.

The review of the noted aerial photographs did not reveal any information that would suggest there is a potential environmental liability on the Site.

The aerial photographs are included in Appendix 'G' for reference.

2. Topography, Hydrology, Geology: Readily available topographic maps for the Site and Phase One Study Area were reviewed as part of this Phase One ESA and revealed the following information:

Map Year [Scale]	Site Description	Description of Surrounding Lands
1909 [1:63,360]	The Site is illustrated as vacant undeveloped land.	The Phase One Study Area is primarily comprised of vacant, undeveloped land with sparse residential presence. Mary Fix Creek is located to the south of the Site, and a hydro line is situated to the south-southeast.

Map Year [Scale]	Site Description	Description of Surrounding Lands
1938 [1:63,360]	The Site is illustrated as vacant undeveloped land.	The Phase One Study Area is primarily comprised of vacant, undeveloped land, and residential use lands along Hurontario Street. Mary Fix Creek is located to the south of the Site, and a hydro line is situated to the south-southeast.
1962 [1:25,000]	There is one building illustrated on the Site.	The Phase One Study Area is primarily comprised of vacant, undeveloped land, and residential use lands along Hurontario Street. Mary Fix Creek is located to the south of the Site, and a hydro line and QEW are situated to the south-southeast.
1994 [1:50,000]	There is one building illustrated on the Site.	The Phase One Study Area is primarily comprised of vacant, undeveloped land, and residential use lands along Hurontario Street. Mary Fix Creek is located to the south of the Site, and a hydro line and QEW are situated to the south-southeast.

The review of the topographic maps did not reveal any PCAs that are considered likely to cause an APEC on the Phase One Property.

A copy of the topographic maps is included in Appendix 'H' for reference.

A review of the Ministry of Northern Development and Mine's "Quaternary Geology of the Brampton Area, Southern Ontario Sheet Map P3171" and the "Paleozoic Geology of the Brampton Area, Southern Ontario Sheet Map M2337", revealed the Site to be underlain by deltaic and lacustrine deposits of predominantly gravelly sand and silty sand, in turn, underlain by Upper Ordovician Georgian Bay Formation shale bedrock.

The project area is generally flat and level with surface water runoff generally being directed to the northwest toward Harborn Road and to the south towards Mary Fix Creek.

Local groundwater flow is expected to the south towards Mary Fix Creek. Regional groundwater flow is expected to the southeast towards Lake Ontario.

3. Fill Materials: The reconnaissance of the Site did not reveal any obvious visual evidence of significant fill material on the Site.

4. Water Bodies and Areas of Natural Significance: With the exception of Mary Fix Creek, located approximately 12 metres south of the Site, surface water was not encountered on the Phase One Property. In addition, no areas of natural significance were identified on the Phase One Property or within the Phase One Study Area.

5. Well Records: The reconnaissance of the Site did not reveal any obvious visual evidence of a suspected potable groundwater well and/or a suspected groundwater monitoring well(s) on the Phase One Property. In addition, our review

of the MECP's water well records did not reveal any potable groundwater wells or groundwater monitoring wells on the Phase One Property.

In addition to the above, our review of the MECP's water well records did not reveal any potable groundwater wells within the Phase One Study Area. However, our review of the available records revealed thirty-six [36] groundwater monitoring wells in the Phase One Study Area. The groundwater monitoring wells are reportedly located between 105 and 225 metres from the Site and range from 4.6 to 10.7 metres in depth.

4(d) SITE OPERATING RECORDS

1. Title of the Information Sheet or Document: Not Applicable

2. Description of Data, Analysis or Findings as the Information Sheet or Document relates to the Phase One ESA Property: Not Applicable

5.0 INTERVIEWS

Mr. Evgen Myronov [One of the Owners], accompanied SOIL-MAT ENGINEERS' representative during the site reconnaissance. According to Mr. Myronov, the dwelling was constructed in the 1950s, although he was uncertain with an exact date. According to Mr. Myronov, the home has always been serviced with municipal water/sewers/natural gas, and he is unaware of any home heating fuel storage tanks or potable groundwater wells historically being present on the Site.

SITE RECONNAISSANCE

6.0 (a) GENERAL REQUIREMENTS:

Reporting Requirements	SOIL-MAT ENGINEERS' Details
Date and Time of the Reconnaissance	April 21, 2026 [10:15am to 11:00am]
Weather Conditions	The weather conditions did not limit the visual observations of the Site.
Duration of Site Visit	~0.75 hours
Enhanced Investigation Property	The Site is not considered an Enhanced Investigation property
Field Representative	Mr. Peter Markesic [qualifications included in the appendix]

6.0(b) SPECIFIC OBSERVATIONS AT PHASE ONE ESA PROPERTY

Reporting Requirements	SOIL-MAT ENGINEERS' Details
Description of Structures and Other Improvements	A two-storey brick building with a basement level is present on the eastern portion of the Site. An asphaltic-driveway extends from Harborn Road to the dwelling. The remainder of the Site is primarily grass covered with trees lining the majority of the Site.
Description of the Number, Age and Depth of Below-Ground Structures	None observed
Details of all tanks (aboveground and underground)	None observed
Details of any potable and non-potable water sources	The Site is serviced with a municipal water supply.
Buried Utilities	The Site is serviced with natural gas and water/ sewer/ storm sewer services. The depth of these service trenches is not anticipated to affect contaminant distribution on the Site.
Existing Buildings: Exit/Entry Points	There are two [2] man door entrances to the building, with one being on the north side, and one being on the west side of the dwelling.
Existing Buildings: Cooling / Heating System	Natural Gas forced air heating with central air cooling
Existing Buildings: Drains, Pits, Sumps, etc.	There is a sump pump in the basement level on the eastern side of the dwelling.
Existing Buildings: Details of any unidentified substances	None observed
Existing Buildings: Details of Stains, Corrosion on Floors other than from Water	None observed
Details of Former and Current Wells	None observed. In addition, the research during this phase one did not indicate any past wells on the property.
Details of Sewage Works	The Site is serviced with municipal sanitary and storm sewer services
Details of Ground Surface Cover	Primarily overgrown grass and weeds with some low-lying shrubs and trees throughout.
Details of Former or Current Railway Lines	None observed

Reporting Requirements	SOIL-MAT ENGINEERS' Details
Details of Stained Soil, Damaged Vegetation or Pavement	None observed
Details of Stressed Vegetation	None observed
Areas Where Fill and Debris Materials Appear to be Present	None observed
PCAs	None observed

1. Enhanced Investigation Property

Reporting Requirements	SOIL-MAT ENGINEERS' Details
Details of the Operations at the Site	Not Applicable
Hazardous Materials Used/Stored on the Site	Not Applicable
Products Manufactured on the Site	Not Applicable
By-Products and Wastes at the Site	Not Applicable
Raw Materials, including the Handling and Storage	Not Applicable
Details of Drums, Totes, Bins	Not Applicable
Details of Oil/Water Separators	Not Applicable
Details of Vehicle and Equipment Maintenance Areas	Not Applicable
Details of Known Spills	Not Applicable
Details of Liquid Discharge Points	Not Applicable
Details of Operations at the Site [processing or manufacturing and equipment used]	Not Applicable
Details of Hydraulic Lift Equipment	Not Applicable

6.0 (c) WRITTEN DESCRIPTION OF INVESTIGATION

The information gathered during the completion of this Phase One ESA report revealed that the Site was first developed circa 1938 to 1954 as residential use lands. The first readily available visual aid for the Site is a topographic map from 1909 which illustrates the Site as vacant undeveloped land. Other visual aids, including aerial photographs from 1954, 1966, 1980, 1989, 1995, 2000, 2005, 2007, 2009, 2014, 2018 and 2024, and topographic maps from 1909, 1938, 1962, and 1994 confirm the development timeline above.

The lands in the general vicinity of the Phase One Property were comprised of a mixture of residential, community, commercial and vacant undeveloped lands that based on the information currently available to SOIL-MAT ENGINEERS are not anticipated to cause an area of potential environmental concern on the Phase One Property.

7.0 REVIEW AND EVALUATION OF INFORMATION

(i) Current and Past Uses: SOIL-MAT ENGINEERS' Table of Current and Past Uses is included in Appendix 'I' of this Report.

(ii) Potential Contaminating Activity: No PCAs were identified on the Site or in the Phase One Study Area that are considered to cause an APEC on the Site.

(iii) Areas of Potential Environmental Concern: No APECs were identified on the Site.

(iv) Phase One Conceptual Site Model: SOIL-MAT ENGINEERS' Phase One CSM is included in Appendix 'J' for reference.

8.0 CONCLUSIONS

The Phase One Environmental Site Assessment [ESA] conducted for this property consisted of a historical records review, interviews and a reconnaissance of the lands subject to the specific Phase One ESA research. The research and reporting were conducted in accordance with Ontario Regulation 153/04 [as amended] in order to support the future filing of a Record of Site Condition [RSC] for the property, if required. However, it is noted that based on the current and historical residential use of the property there would not be a requirement for an RSC filing under the Regulation for ongoing residential use, or future redevelopment for residential or commercial use. It is our understanding that the Phase One ESA Report is required as part of planning conditions for the Site.

At the time of this Report, the Phase One Property was comprised of a roughly rectangular shaped parcel of land located on the east side of Harborn Road between Premium Way and Autumn Breeze Drive South, and was recognized with the municipal address of 60 Harborn Road in the City of Mississauga, Ontario. Specifically, the Phase One Property was occupied by a two-storey brick dwelling, with a basement level, on the eastern portion of the property and an asphaltic-concrete driveway extending from Harborn Drive to the existing dwelling. The remainder of the Phase One Property was comprised primarily of grass covered areas, with trees lining the majority of the northern, southern, and eastern limits of the property.

The Phase One research, and reconnaissance of the Phase One Property, did not reveal any information that suggests there is an active or historical potentially contaminating activity on the Phase One Property that is considered likely to cause an area of potential environmental concern.

The lands in the general vicinity of the Phase One Property were comprised of a mixture of residential, community, commercial and vacant undeveloped lands that based on the information currently available to SOIL-MAT ENGINEERS are not anticipated to cause an area of potential environmental concern on the Phase One Property.

Based on the findings of the Phase One Environmental Site Assessment, SOIL-MAT ENGINEERS & CONSULTANTS LTD. find the potential of Site contamination to be considered **LOW** and therefore recommend that additional investigations **ARE NOT** required at this time.

Although not considered an environmental liability to the Site, given the construction date of the building, it is possible that designated substances, such as asbestos containing materials, and ozone depleting substances, may be present in the buildings. As such, it is recommended that a non-intrusive designated substance survey of the buildings be undertaken before any planned demolition activities that may disturb building materials to identify where possible, designated substances that may be present in the buildings.

In addition, if a suspected groundwater well is encountered during future construction activities to make arrangements for the water well to be abandoned as per *Ontario Regulation 903 – Water Wells*.

9.0 REPORT LIMITATIONS

Achieving the objectives that are stated in this report has required SOIL-MAT ENGINEERS to derive conclusions based upon the best and most recent information currently available to SOIL-MAT ENGINEERS. No investigative method can completely eliminate the possibility of obtaining partially imprecise information. SOIL-MAT ENGINEERS has expressed professional judgement in gathering and analysing the information obtained and in the formulation of its conclusions.

Information in this report was obtained from sources deemed to be reliable, however, no representation or warranty is made as to the accuracy of this information. To the best of SOIL-MAT ENGINEERS' knowledge, the information gathered from outside sources contained in this report on which SOIL-MAT ENGINEERS has formulated its opinions and conclusions, are both true and correct. SOIL-MAT ENGINEERS assumes no responsibility for any misrepresentation of facts gathered from outside sources.

This report was prepared to assess and document evidence of potential environmental contamination, and not to judge the acceptability of the risks associated with such environmental contamination. Much of the information gathered for this report is only accurate at the time of collection and a change in the Site conditions may alter the interpretation of SOIL-MAT ENGINEERS' findings. Furthermore, the reader should note that the Site reconnaissance described in this report was an environmental assessment of the Site, not a regulatory compliance or an environmental audit of the Site.

SOIL-MAT ENGINEERS & CONSULTANTS LTD. prepared this Report for the account of W.E. OUGHTRED AND ASSOCIATES INC. The material in it reflects SOIL-MAT ENGINEERS' best judgement in light of the information available to it at the time of preparation. Any use which a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. SOIL-MAT ENGINEERS accepts no responsibility for damages, if any suffered by any third party as a result of decisions made or actions based on this report.

We trust that this Phase One Environmental Site Assessment is satisfactory for your purposes. Please feel free to contact the undersigned if you have any questions.


Sincerely,
SOIL-MAT ENGINEERS & CONSULTANTS LTD.



Peter Markesic, B.Sc.
Project Manager



Keith Gleadall, B.A., EA Dipl.
Environmental Manager





Ian Shaw, P. Eng., QP_{ESA}
Senior Engineer


Distribution: W.E. OUGHTRED AND ASSOCIATES INC. [1]

Enclosures:

Appendix 'A'	Site Plan Drawings
Appendix 'B'	Chain of Title
Appendix 'C'	City of Mississauga Information Request
Appendix 'D'	MOE Database Search Results
Appendix 'E'	T.S.S.A. Correspondence
Appendix 'F'	Ecolog ERIS Report
Appendix 'G'	Aerial Photographs
Appendix 'H'	Topographic Maps
Appendix 'I'	Table of Current and Past Uses
Appendix 'J'	Phase One Conceptual Site Model
Appendix 'K'	Site Photographs
Appendix 'L'	Qualifications of Assessors

Appendix ‘A’

1. Drawing No.: 1.: Site Plan;
2. Drawing No.: 2: Study Area View;
3. Drawing No.: 3: Site Location;



LEGEND

= Site Boundary

NOTES:

1. This map should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260523-E

Soil-Mat
Engineers & Consultants Ltd.

CLIENT

W.E. OUGHTRED AND ASSOCIATES INC.

PROJECT TITLE

Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE


Site Plan Drawing

PROJECT No.	SM 260253-E
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME

260253 Site Plan.vsd

DRAWING No. 1



LEGEND

= Site Boundary

= Phase One Study Area

NOTES:

1. This map should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Base map provided by: © 2025 Google

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.


PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Study Area View

PROJECT No.	SM 260253-E
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Site Plan 2.vsd

DRAWING No. 2



LEGEND

★ = Site Location

NOTES:

1. This map should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Base map provided by: © 2026 Mapquest

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.

PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Site Location Plan

PROJECT No.	SM 260253-E
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Site Location.vsd

DRAWING No. 3

Appendix ‘B’

1. Title Search Documents

PROPERTY DESCRIPTION: PT LT 1 RANGE 3 CIR TORONTO AS IN RO1104142 ; MISSISSAUGA

PROPERTY REMARKS:

ESTATE/QUALIFIER:
FEE SIMPLE
LT CONVERSION QUALIFIED

RECENTLY:
RE-ENTRY FROM 13359-2234

PIN CREATION DATE:
1999/03/25

OWNERS' NAMES
1000635365 ONTARIO INC.

CAPACITY SHARE
ROWN

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
EFFECTIVE 2000/07/29 THE NOTATION OF THE "BLOCK IMPLEMENTATION DATE" OF 1997/06/24 ON THIS PIN						
WAS REPLACED WITH THE "PIN CREATION DATE" OF 1999/03/25						
*** PRINTOUT INCLUDES ALL DOCUMENT TYPES AND DELETED INSTRUMENTS SINCE 1999/03/25 ***						
***SUBJECT, ON FIRST REGISTRATION UNDER THE LAND TITLES ACT, TO:*						
*** SUBSECTION 44(1) OF THE LAND TITLES ACT, EXCEPT PARAGRAPH 11, PARAGRAPH 14, PROVINCIAL SUCCESSION DUTIES **						
*** AND ESCHEATS OR FORFEITURE TO THE CROWN.*						
*** THE RIGHTS OF ANY PERSON WHO WOULD, BUT FOR THE LAND TITLES ACT, BE ENTITLED TO THE LAND OR ANY PART OF*						
*** IT THROUGH LENGTH OF ADVERSE POSSESSION, PRESCRIPTION, MISDESCRIPTION OR BOUNDARIES SETTLED BY*						
*** CONVENTION.*						
*** ANY LEASE TO WHICH THE SUBSECTION 70(2) OF THE REGISTRY ACT APPLIES.*						
***DATE OF CONVERSION TO LAND TITLES: 1999/03/26 ***						
RO984898	1991/10/01	CHARGE		*** COMPLETELY DELETED ***	NATIONAL TRUST COMPANY	
RO1104142	1995/11/30	TRANSFER		*** DELETED AGAINST THIS PROPERTY ***	AIR, ALEXANDER AIR, FLORENCE	
RO1104143	1995/11/30	CHARGE		*** COMPLETELY DELETED ***	KHAN, GHULAM HAIDER KAHN, FARKAHNDA SHAHEEN	
RO1170726	1998/05/26	TRANSFER OF CHARGE		*** DELETED AGAINST THIS PROPERTY *** NATIONAL TRUST COMPANY	CIBC MORTGAGES INC.	
REMARKS: MULTIPLE						
PR216570	2002/03/15	LIEN		*** COMPLETELY DELETED *** HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
				THE MINISTER OF NATIONAL REVENUE		
	REMARKS: INCOME TAX ACT					
PR342388	2002/11/04	DISCH OF CHARGE		*** COMPLETELY DELETED *** KHAN, GHULAM HAIDER KAHN, FARKAHNDA SHAHEEN		
	REMARKS: RE: RO1104143					
PR607482	2004/03/18	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER AIR, FLORENCE	MAPLE TRUST COMPANY	
PR610799	2004/03/25	DISCHARGE INTEREST		*** COMPLETELY DELETED ***	HER MAJESTY THE QUEEN IN RIGHT OF CANADA AS REPRESENTED BY THE MINISTER OF NATIONAL REVENUE	
	REMARKS: RE: PR216570					
PR644158	2004/05/27	DISCH OF CHARGE		*** COMPLETELY DELETED *** CIBC MORTGAGES INC.		
	REMARKS: RE: RO984898					
PR1235801	2007/04/02	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER AIR, FLORENCE	FIRST NATIONAL FINANCIAL GP CORPORATION	
PR1252584	2007/05/03	DISCH OF CHARGE		*** COMPLETELY DELETED *** MAPLE TRUST COMPANY		
	REMARKS: RE: PR607482					
PR1440835	2008/04/04	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER AIR, FLORENCE	FIRST NATIONAL FINANCIAL GP CORPORATION	
PR1458255	2008/05/08	DISCH OF CHARGE		*** COMPLETELY DELETED *** FIRST NATIONAL FINANCIAL GP CORPORATION		
	REMARKS: RE: PR1235801					
PR1548540	2008/10/08	APL OF SURV-LAND		*** COMPLETELY DELETED *** AIR, FLORENCE	AIR, ALEXANDER	
PR1564426	2008/11/05	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	THE TORONTO-DOMINION BANK	
PR1581324	2008/12/10	DISCH OF CHARGE		*** COMPLETELY DELETED *** FIRST NATIONAL FINANCIAL GP CORPORATION		

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
	REMARKS: RE: PR1440835					
PR1689398	2009/08/20	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	THE CANADA TRUST COMPANY	
PR1812013	2010/04/29	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	THE CANADA TRUST COMPANY	
PR2356479	2013/04/16	TRANSFER OF CHARGE		*** COMPLETELY DELETED *** THE CANADA TRUST COMPANY	THE EFFORT TRUST COMPANY	
	REMARKS: PR1689398.					
PR2356480	2013/04/16	TRANSFER OF CHARGE		*** COMPLETELY DELETED *** THE CANADA TRUST COMPANY	THE EFFORT TRUST COMPANY	
	REMARKS: PR1812013.					
PR2709122	2015/05/07	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	CANADIAN IMPERIAL BANK OF COMMERCE	
PR2712726	2015/05/15	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE TORONTO-DOMINION BANK		
	REMARKS: PR1564426.					
PR2723816	2015/06/05	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE EFFORT TRUST COMPANY		
	REMARKS: PR1689398.					
PR2723818	2015/06/05	DISCH OF CHARGE		*** COMPLETELY DELETED *** THE EFFORT TRUST COMPANY		
	REMARKS: PR1812013.					
PR3529196	2019/08/27	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	PRUDENT FINANCIAL SERVICES INC.	
PR3645339	2020/04/30	DISCH OF CHARGE		*** COMPLETELY DELETED *** PRUDENT FINANCIAL SERVICES INC.		
	REMARKS: PR3529196.					
PR3649671	2020/05/11	CHARGE		*** COMPLETELY DELETED *** AIR, ALEXANDER	HOME EQUITY MORTGAGE CORPORATION	
PR3659900	2020/06/03	DISCH OF CHARGE		*** COMPLETELY DELETED *** CANADIAN IMPERIAL BANK OF COMMERCE		
	REMARKS: PR2709122.					

REG. NUM.	DATE	INSTRUMENT TYPE	AMOUNT	PARTIES FROM	PARTIES TO	CERT/ CHKD
PR4256921	2023/09/29	TRANSFER	$2,000,000	AIR, ALEXANDER	1000635365 ONTARIO INC.	C
PR4256922	2023/09/29	CHARGE	$1,260,000	1000635365 ONTARIO INC.	CANADIAN IMPERIAL BANK OF COMMERCE	C
PR4263278	2023/10/18	DISCH OF CHARGE		*** COMPLETELY DELETED *** HOME EQUITY MORTGAGE CORPORATION		
REMARKS: PR3649671.						

Appendix ‘C’

1. City of Mississauga Correspondence

Peter Markesic

From: Lianne Crawford
Sent: Tuesday, May 5, 2026 1:54 PM
To: Adam.Lucas@mississauga.ca; Andrea.Dear@mississauga.ca
Cc: Peter Markesic
Subject: Information on a property in Mississauga

Hello,

I am looking for some information on a property in Mississauga.
The property is 60 Harborn Road and I am looking to see if the Planning Department has any previous Phase One Environmental Site Assessments on file with the City in regards to this property.

Regards,

Lianne Crawford
Environmental Technician
SOIL-MAT ENGINEERS & CONSULTANTS LTD.
401 Grays Road, Hamilton, ON L8E 2Z3
T: 905.318.7440 M: 905.906.8768 www.soil-mat.ca

Peter Markesic

From: Mississauga Customer Service <public.info@mississauga.ca>
Sent: Tuesday, May 5, 2026 2:06 PM
To: Lianne Crawford
Subject: City of Mississauga - Online contact form submission

Thank you for contacting the City of Mississauga.

Your message has been received and we will follow up with you soon.

Appendix 'D'

1. MOE Database Search Results

Peter Markesic

From: Jaramillo, Daniela (MECP) <Daniela.Jaramillo@ontario.ca>
Sent: Tuesday, June 2, 2026 11:49 AM
To: Lianne Crawford
Subject: MECP FOI A-2026-03736 - Decision Letter

Hello / Bonjour Lianne Crawford,

This email is in response to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to:

60 Harborn Road, Mississauga

Time Frame; 1990/01/01 - 2026/05/26

After a thorough search through the ministry files, no records were located responsive to your request. The official responsible for making the access decision on your request is the undersigned. This file is now closed.

You may request a review of my decision within 30 days from the date of this letter by contacting the Information and Privacy Commissioner/Ontario at http://www.ipc.on.ca. Please note there may be a fee associated with submitting the appeal.

If you have any questions, please email me.

Yours truly,
Daniela Jaramillo

for
Josephine DeSouza
Manager, Access and Privacy Office

Ontario

Appendix ‘E’

1. T.S.S.A Correspondence

Lianne Crawford

From: Public Information Services <publicinformationservices@tssa.org>
Sent: Wednesday, May 6, 2026 9:10 AM
To: Lianne Crawford
Subject: RE: Underground Fuel Tanks

Hello ,

NO RECORDS FOUND IN CURRENT DATABASE:

- We confirm that there are NO **fuels records** in our database at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please go to the **TSSA Client Portal** to complete an Application for Release of Public Information.

Please refer to Training (tssa.org) for instructions on how to use the portal. Please refer to How to Submit a Public Information Request (tssa.org) for instructions.

The associated fee must be paid via credit card (Visa or MasterCard).

Once all steps have been successfully completed you will receive your payment receipt via email.

TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.

If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

Aleena Tahir | Public Information & Records Agent
Public Information
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3546 | E-Mail: ATahir@tssa.org
www.tssa.org

Winner of 2025 5-Star Safety Cultures Award

From: Lianne Crawford <lcrawford@soilmat.ca>
Sent: Tuesday, May 5, 2026 4:30 PM
To: Public Information Services <publicinformationservices@tssa.org>

Cc: Peter Markesic <pmarkesic@soilmat.ca>
Subject: Underground Fuel Tanks

⚠ External Email >

[⚠ CAUTION]: THIS EMAIL ORIGINATED OUTSIDE THE ORGANISATION.
DO NOT CLICK LINKS OR OPEN ATTACHMENTS UNLESS YOU KNOW THE SENDER AND ARE EXPECTING THIS EMAIL. PLEASE REPORT WITH THE PHISH REPORT BUTTON IF SUSPICIONS.

Hi,

I'm looking for any records of underground fuel storage tanks located at the following addresses in Mississauga, Ontario:

40 Harborn Road
50 Harborn Road
60 Harborn Road
68 Harborn Road
45 Harborn Road
57 Harborn Road
65 Harborn Road
69 Harborn Road
35 Premium Way
39 Premium Way

Thank you,

Lianne Crawford
Environmental Technician
SOIL-MAT ENGINEERS & CONSULTANTS LTD.
401 Grays Road, Hamilton, ON L8E 2Z3
T: 905.318.7440 M: 905.906.8768 www.soil-mat.ca

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Lianne Crawford

From: Public Information Services <publicinformationservices@tssa.org>
Sent: Monday, May 11, 2026 1:14 PM
To: Lianne Crawford
Subject: RE: Underground Fuel Tanks

RECORD FOUND IN CURRENT DATABASE

Hello,

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are records in our current database of any fuel storage tanks at the subject address(es).

Inventory Number	Address	City	Province	Postal Code	Reason Code	Asset Type / Invento
60985374	42 HARBORN ROAD	MISSISSAUGA	ON	L5B 1A4	Active	FS FUEL OIL TANK

Accessing the applications

1. Click Request a Public Record - TSSA and click "need a copy of a document"
2. Select the appropriate application, download it, complete it in full and save it (Note: you will have to upload the application)
3. Proceed to page 3 of the application and click the "TSSA Service Prepayment Portal" link under payment options (the link will take you the secure site where you can pay for the request via credit card)

Accessing the Service Prepayment Portal

1. Select new or existing customer (*if you are an existing customer, you will need your account number & postal code to access your account)
2. Under "Program Area" select **Public Information** and click continue
3. Enter application form number (found on the bottom left corner of the application form) and click continue
4. Complete the primary contact information section
5. Complete the fee section
6. Upload your completed application
7. Upload supporting documents (if required) and click continue

Once all steps have been successfully completed you will receive your payment receipt via email.
TSSA does not make any representations or warranties with respect to the accuracy or completeness of any records released. The requestor assumes all risk in using or relying on the information provided.
If you have any questions or concerns, please do not hesitate to contact our Public Information Release team at publicinformationservices@tssa.org.

Kind regards,

Kimberly Gage | Public Information & Records Agent
Public Information
345 Carlingview Drive
Toronto, Ontario M9W 6N9
Tel: +1 416-734-3581 | Fax: +1 416-734-3568 | E-Mail: kgage@tssa.org
www.tssa.org

Winner of 2025 5-Star Safety Cultures Award

From: Lianne Crawford <lcrawford@soilmat.ca>
Sent: Monday, May 11, 2026 12:54 PM
To: Public Information Services <publicinformationservices@tssa.org>
Subject: Underground Fuel Tanks

⚠ External Email >

[⚠ CAUTION]: THIS EMAIL ORIGINATED OUTSIDE THE ORGANISATION.
DO NOT CLICK LINKS OR OPEN ATTACHMENTS UNLESS YOU KNOW THE SENDER AND ARE EXPECTING THIS EMAIL. PLEASE REPORT WITH THE PHISH REPORT BUTTON IF SUSPICIONS.

Hi,

I'm looking for any records of underground fuel storage tanks located at the following address in Mississauga, Ontario:

42 Harborn Road

Thank you,

Lianne Crawford
Environmental Technician
SOIL-MAT ENGINEERS & CONSULTANTS LTD.
401 Grays Road, Hamilton, ON L8E 2Z3
T: 905.318.7440 M: 905.906.8768 www.soil-mat.ca

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.
This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied,

forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Appendix ‘F’

1. Ecolog ERIS Report;

DATABASE REPORT

Project Property:	*60 Harborn Road, Mississauga* *60 Harborn Road* *Mississauga ON*
Project No:	*260253-E*
Report Type:	*RSC Report (Urban)*
Order No:	*26042400864*
Requested by:	*Soil-Mat Engineers & Consultants Ltd.*
Date Completed:	*April 24, 2026*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....7
Executive Summary: Site Report Summary - Surrounding Properties.....8
Executive Summary: Summary By Data Source.....16
Map.....27
Aerial.....28
Topographic Map.....29
Detail Report.....30
Unplottable Summary.....164
Unplottable Report.....167
Appendix: Database Descriptions.....200
Definitions.....211

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*60 Harborn Road, Mississauga* *60 Harborn Road Mississauga ON*
Project No:	*260253-E*

Order Information:

Order No:	*26042400864*
Date Requested:	*April 24, 2026*
Requested by:	*Soil-Mat Engineers & Consultants Ltd.*
Report Type:	*RSC Report (Urban)*

Historical/Products:

ERIS Xplorer	*ERIS Xplorer*
Topographic Map	*RSC Maps*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	0	0	0
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	0	0	0
BORE	Borehole	Y	0	2	2
CA	Certificates of Approval	Y	0	7	7
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	3	3
CHEM	Chemical Manufacturers and Distributors	Y	0	0	0
CHM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
DTNK	Delisted Fuel Tanks	Y	0	0	0
EASR	Environmental Activity and Sector Registry	Y	0	3	3
EBR	Environmental Registry	Y	0	1	1
ECA	Environmental Compliance Approval	Y	0	5	5
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	1	16	17
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EOR	Environmental Offenders Registry	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
ESNR	Excess Soil Registry	Y	0	0	0
EXP	List of Expired Fuels Safety Facilities	Y	0	0	0
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FRST	Federal Identification Registry for Storage Tank Systems (FIRSTS)	Y	0	0	0
FST	Fuel Storage Tank	Y	0	0	0
FSTH	Fuel Storage Tank - Historic	Y	0	0	0
GEN	Ontario Regulation 347 Waste Generators Summary	Y	0	16	16

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HBAR	Historical Business Activity Risk	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	Fuel Oil Spills and Leaks	Y	0	2	2
LIMO	Landfill Inventory Management Ontario	Y	0	0	0
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NOC	Notice of Contamination List	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPR2	National Pollutant Release Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory - Historic	Y	0	1	1
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	0	0
PFAS	Ontario PFAS Spills	Y	0	0	0
PFCH	NPRI Reporters - PFAS Substances	Y	0	0	0
PFHA	Potential PFAS Handlers from NPRI	Y	0	0	0
PINC	Pipeline Incidents	Y	0	2	2
PPHA	Potential PFAS Handlers from EASR	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	0	0	0
PTTW	Permit to Take Water	Y	0	1	1
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	0	1	1
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directories	Y	0	10	10
SPL	Ontario Spills	Y	0	14	14
SRDS	Wastewater Discharger Registration Database	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.30km	Total
TANK	***Anderson's Storage Tanks***	*Y*	*0*	*0*	*0*
TCFT	***Transport Canada Fuel Storage Tanks***	*Y*	*0*	*0*	*0*
VAR	***Variances for Abandonment of Underground Storage Tanks***	*Y*	*0*	*0*	*0*
WDS	***Waste Disposal Sites - MOE CA Inventory***	*Y*	*0*	*0*	*0*
WDSH	***Waste Disposal Sites - MOE 1991 Historical Approval Inventory***	*Y*	*0*	*0*	*0*
WMS	***Waste Management Site***	*Y*	*0*	*0*	*0*
WWIS	***Water Well Information System***	*Y*	*0*	*10*	*10*
		Total:	*1*	*94*	*95*

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	EHS		50 and 60 Harborn Road Mississauga ON L5B 1A4	NNE/4.0	1.87	30

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
2	INC		43 Harborn Road, Mississauga ON	NNW/44.9	3.69	30
3	CFOT	E C LILLIE	42 HARBORN ROAD MISSISSAUGA ON	NE/47.9	3.57	31
4	PINC		40 Harborn Road, Mississauga ON	NNE/55.8	3.69	31
5	CA	R.M. OF PEEL	GRANGE DR/HARBORN RD. MISSISSAUGA CITY ON	N/59.6	3.69	31
6	EHS		39 and 42 Harborn Road Mississauga ON	NNE/69.2	3.69	32
7	EASR	TRANS-NORTHERN PIPELINES INC./ PIPELINES TRANS-NORD INC.	ON	SE/78.5	-3.87	32
8	WWIS		N/A NE Premium Way+ Harborn Rd Mississauga ON ***Well ID:*** 7484830	NNE/84.7	3.69	32
9	WWIS		HURONTARIO & HARBORN RD. Mississauga ON ***Well ID:*** 7105998	NE/108.9	3.69	35
10	ECA	Dejan Ciprovski	100 Harborn Rd Mississauga ON L5B 1A4	SW/110.3	3.01	82
10	SPL	ENBRIDGE GAS INC.	100 Harborn Rd, Mississauga ON MISSISSAUGA ON	SW/110.3	3.01	83
11	WWIS		HURONTOARIO AND HARBORN MISSISSAUGA ON ***Well ID:*** 4909961	NE/113.0	3.69	84
12	WWIS		ON	NE/117.2	3.69	87

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Well ID: 7170331			
13	WWIS		2100 Hurontario St ON ***Well ID:*** 7371898	NE/127.6	3.69	87
14	INC		2112 GRANGE DR, MISSISSAUGA ON	NW/133.5	3.69	91
14	SPL		2112 Grange Dr. Mississauga ON	NW/133.5	3.69	92
15	GEN	Summerville Family Health Team	2090 Hurontario St. Mississauga ON ***Generator No.*** **|** ***Years Reported:*** ON4630519	11,10	N/136.7	3.69	93
15	GEN	Harborn Dental	3-2090 Hurontario St Mississauga ON L5B1M8 ***Generator No.*** **|** ***Years Reported:*** ON3307537	25,24,23,22,21,20,19,18,17,16,15	N/136.7	3.69	93
16	CA		Harborn Road/Gordon Drive Mississauga ON	SW/157.6	3.77	96
17	CA	MISSISSAUGA CITY	HURONTARIO ST/HARBORN RD. MISSISSAUGA CITY ON	NE/161.3	3.69	96
17	SPL		Hurontario St and North Service Rd, Mississauga MISSISSAUGA ON	NE/161.3	3.69	97
18	WWIS		2055 Hurontario St ON ***Well ID:*** 7371907	E/166.3	1.03	98
19	CA	HURONTARIO OFFICE CENTRE INC.	2100 HURONTARIO ST. MISSISSAUGA CITY ON L5B 1M8	N/173.8	3.69	101
19	EHS		2100 Hurontario St Mississauga ON L5B 1M8	N/173.8	3.69	101
19	GEN	Mobilinx	2100 Hurontario Street Mississauga ON L5B 1M8 ***Generator No.*** **|** ***Years Reported:*** ON5973701	22,21	N/173.8	3.69	101
20	GEN	Stewart Foodservice Inc	Hurrontario , QEW EB on ramp Mississauga ON	E/190.6	-0.03	102

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
			Generator No. **|** ***Years Reported:*** ONS0305-1-5SRL29-1 | 25,24			
20	SPL	TRANSPORT TRUCK	HURONTARIO ST. (JUST NORTH OF QEW) TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON	E/190.6	-0.03	103
20	SPL	PRIVATE OWNER	QEW WESTBOUND, EAST OF HWY 10 MOTOR VEHICLE (OPERATING FLUID) MISSISSAUGA CITY ON	E/190.6	-0.03	104
20	SPL		QEW & Hurontario St. Mississauga ON	E/190.6	-0.03	105
20	SPL		QEW Eastbound Hunrontario Street exit ramp Mississauga ON	E/190.6	-0.03	106
21	WWIS		ON ***Well ID:*** 7260102	NNW/192.4	3.69	107
22	CFOT	VICKI BURKHOLDER	96 PREMIUM WAY MISSISSAUGA ON	S/193.1	2.69	108
23	EHS		2114 Hurontario Street Mississauga ON L5B 1M8	NNW/197.4	3.69	108
24	SPL		NE of QEW off Ramp at Hurontario MISSISSAUGA ON	E/199.8	0.41	108
25	PINC	ENBRIDGE GAS INC	2080 GORDON DR,,MISSISSAUGA,ON, L5B 1S5,CA ON	SW/203.1	2.89	109
25	SPL	Enbridge Energy Distribution Inc.	2080 Gordon Dr. Mississauga ON	SW/203.1	2.89	109
26	EHS		Hurontario St/ QEW (Ramps on Hwy) Mississauga ON	E/206.6	1.43	110
27	WWIS		60 S Service Rd ON ***Well ID:*** 7371899	E/214.3	0.52	111

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	CA	GWL Realty Advisors Inc.	2085 Hurontario St Mississauga ON L5A 4G1	NNE/224.5	3.69	114
28	EASR	GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA	2085 HURONTARIO STREET MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	115
28	EASR	GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA	2085 HURONTARIO STREET MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	115
28	EBR	GWL Realty Advisors Inc.	2085 Hurontario St Mississauga Ontario Mississauga ON	NNE/224.5	3.69	115
28	ECA	GWL Realty Advisors Inc.	2085 Hurontario St Mississauga ON	NNE/224.5	3.69	116
28	EHS		2085 Hurontario Street MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	116
28	EHS		2085 Hurontario Street Mississauga ON L5A 4G1	NNE/224.5	3.69	116
28	EHS		2085 Hurontario St Mississauga ON L5A4G1	NNE/224.5	3.69	117
28	EHS		2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1	NNE/224.5	3.69	117
28	GEN	The Great West Life Assurance Company	2085 Hurontario St. Mississauga ON ***Generator No.*	*Years Reported:*** ON8446233 | 09,08,07,06,05,04	NNE/224.5	3.69	117
28	GEN	Starneon Ltd partnership	2085 Hurontario St. Mississauga ON L5A4G1 ***Generator No.*	*Years Reported:*** ON8164955 | 21,20	NNE/224.5	3.69	118
28	GEN	Trillium Health Partners	2085 Hurontario Street Missisauga ON L5A4G1 ***Generator No.*	*Years Reported:*** ON4047570 | 25,24,23,22,21,20,19,18,17,16,15,14,13,12,11,10	NNE/224.5	3.69	119
28	NPRI	GWL REALTY ADVISORS	2085 HURONTARIO Street MISSISSAUGA ON L5A4G1	NNE/224.5	3.69	123

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
28	SCT	J T GILMOUR INC.	2085 HURONTARIO ST SUITE 300 MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	125
28	SCT	REPRODUX LIMITED	2085 HURONTARIO ST SUITE 101 MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	126
28	SCT	STEPHAN MACHINERY (CANADA) LTD	2085 HURONTARIO ST SUITE 300 MISSISSAUGA ON L5A 4G1	NNE/224.5	3.69	126
28	SCT	Cincom Systems of Canada Ltd	2085 Hurontario St Suite 200 Mississauga ON L5A 4G1	NNE/224.5	3.69	127
28	SCT	ONIX SYSTEMS GROUP INC.	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	NNE/224.5	3.69	127
28	SCT	Reprodux Copy Centres Ltd.	2085 Hurontario St Suite 101 Mississauga ON L5A 4G1	NNE/224.5	3.69	127
28	SCT	Stephan Machinery (Canada) Limited	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	NNE/224.5	3.69	128
28	SCT	Autobranch Technologies	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	NNE/224.5	3.69	129
28	SCT	Owen Media Partners Inc.	2085 Hurontario St Suite 208 Mississauga ON L5A 4G1	NNE/224.5	3.69	129
28	SCT	OCWA Corporate Head office	2085 Hurontario St Mississauga ON L5A2E6	NNE/224.5	3.69	129
29	EHS		2085 Hurontario Street Mississauga ON Mississauga ON L5A 4G1	NNE/224.8	3.69	130
30	BORE		ON	NNE/230.0	3.69	130
31	ECA	Berkley Homes (Gordon Woods II) Inc.	Grange Dr Mississauga ON L4K 3N3	WNW/231.8	-1.02	132

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
32	EHS		2143 Grange Drive Mississauga ON	NW/232.2	4.69	132
33	WWIS		HURONTARIO ST Mississauga ON ***Well ID:*** 7277550	N/233.4	3.69	132
34	EHS		2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1	NNE/240.5	3.69	135
35	EHS		Forntinf West Side of Hurontario 2130 Hurontario Street Mississauga ON	NNW/244.9	3.69	135
36	WWIS		lot 2 con 3 ON ***Well ID:*** 4902195	S/246.2	2.69	135
37	SPL	ELF ATOCHEM CANADA INC.	QEW EAST/WESTBOUND - 2055 HURONTARIO ST. TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON L5A 2E6	NE/260.5	2.69	138
38	CA	PLM Holdings Inc.	2150 Hurontario Street Mississauga ON L5B 1M8	NNW/264.0	3.69	139
38	ECA	PLM Holdings Inc.	2150 Hurontario Street Mississauga ON M8Z 1N6	NNW/264.0	3.69	139
39	BORE		ON	ENE/286.7	2.69	140
40	EHS		2156 Hurontario Street Mississauga ON L5B 1M8	NNW/292.6	3.69	141
41	EHS		88 Bronte College Court Mississauga ON L5B 1M9	WNW/294.0	3.76	141
41	GEN	BRONTE COLLEGE OF CANADA	88 BRONTE COLLEGE COURT MISSISSAUGA ON L5B 1M9 ***Generator No.*** **|** ***Years Reported:*** ON4119045 | 22,21,20,19,18,17,16,15,14,13,12,11,10	WNW/294.0	3.76	141

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
41	GEN	Kenaidan Contracting Ltd	88 Bronte College Court Mississauga ON L5B 1M9 ***Generator No.* | *Years Reported:*** ON001066937 | 25	WNW/294.0	3.76	144
42	SPL		155 Harborn Road MISSISSAUGA ON	SW/297.4	2.69	145
43	CA	Fernanda Leal	2122 Gordon Drive Mississauga ON L5B 1S7	W/297.4	2.64	146
43	ECA	Fernanda Leal	2122 Gordon Drive Mississauga ON L4Y 3R7	W/297.4	2.64	146
44	GEN	SNC LAVALIN PROFAC INC.	49 South Service Road Mississauga ON ***Generator No.* | *Years Reported:*** ON6197573 | 09	E/297.6	2.69	146
44	GEN	Civil Underground and excavation company	49 south service rd mississauga ON ***Generator No.* | *Years Reported:*** ON5756807 | 10	E/297.6	2.69	147
44	GEN	Mobilinx	49 South Service Rd Mississauga ON L5G 2R8 ***Generator No.* | *Years Reported:*** ON9628654 | 22	E/297.6	2.69	147
44	GEN	SNC Lavalin-ProFac	49 South Service Road Mississauga ON ***Generator No.* | *Years Reported:*** ON8719017 | 09,08,07	E/297.6	2.69	148
44	PTTW	Salini Impregilo Civil Works Inc.	49 South Service Road Mississauga, ON L5G 2R8 Canada ON L5G 2R8	E/297.6	2.69	149
44	RSC	EDENSHAW SSR DEVELOPMENTS LIMITED	49 South Service RD Mississauga ON	E/297.6	2.69	150
44	SPL	SNC Lavalin Profac<UNOFFICIAL>	49 South Service Road Mississauga ON L5G 2R8	E/297.6	2.69	150
45	EHS		2100 Sherobee Road Mississauga ON L5A 4C5	NNE/297.7	3.69	151
45	GEN	Enersource Hydro Mississauga	2100 Sherobee Road Mississauga ON L5A4C5 ***Generator No.* | *Years Reported:*** ON6368899 | 16	NNE/297.7	3.69	151

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
45	SPL		2100 Sherobe Dr Mississauga ON	NNE/297.7	3.69	152
45	SPL	Enersource Hydro Mississauga Inc.	2100 Sherobee Rd. Mississauga ON	NNE/297.7	3.69	153
46	CFOT	BRUCE PARSONS	1637 GLENBURNIE ROAD MISSISSAUGA ON	SSE/298.1	-0.16	154
47	EHS		2180 Hurontario Street Mississauga ON L5B 1M8	NW/298.8	4.05	154
47	GEN	TURNER & PORTER FUNERAL DIRECTORS	2180 HURONTARIO STREET MISSISSAUGA ON L5B 1M8 ***Generator No.* | *Years Reported:*** ONF037100 | 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,04,03,01,00,99,98,97,96,95,94,93,92,91,90,89,88	NW/298.8	4.05	154
47	GEN	Turner & Porter Funeral Directors Ltd.	2180 Hurontario Street Mississauga ON L5B 1M8 ***Generator No.* | *Years Reported:*** ON9465628 | 25,23	NW/298.8	4.05	162

Executive Summary: Summary By Data Source

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 2 BORE site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	230.0	30
	ON	286.7	39

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 7 CA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
R.M. OF PEEL	GRANGE DR/HARBORN RD. MISSISSAUGA CITY ON	59.6	5
	Harborn Road/Gordon Drive Mississauga ON	157.6	16
MISSISSAUGA CITY	HURONTARIO ST/HARBORN RD. MISSISSAUGA CITY ON	161.3	17
HURONTARIO OFFICE CENTRE INC.	2100 HURONTARIO ST. MISSISSAUGA CITY ON L5B 1M8	173.8	19
GWL Realty Advisors Inc.	2085 Hurontario St Mississauga ON L5A 4G1	224.5	28
PLM Holdings Inc.	2150 Hurontario Street Mississauga ON L5B 1M8	264.0	38

Site	Address	Distance (m)	Map Key
Fernanda Leal	2122 Gordon Drive Mississauga ON L5B 1S7	297.4	43

CFOT - Commercial Fuel Oil Tanks

A search of the CFOT database, dated Oct 2023 has found that there are 3 CFOT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
E C LILLIE	42 HARBORN ROAD MISSISSAUGA ON	47.9	3
VICKI BURKHOLDER	96 PREMIUM WAY MISSISSAUGA ON	193.1	22
BRUCE PARSONS	1637 GLENBURNIE ROAD MISSISSAUGA ON	298.1	46

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011 - Feb 28, 2026 has found that there are 3 EASR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
TRANS-NORTHERN PIPELINES INC./ PIPELINES TRANS-NORD INC.	ON	78.5	7
GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA	2085 HURONTARIO STREET MISSISSAUGA ON L5A 4G1	224.5	28
GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA	2085 HURONTARIO STREET MISSISSAUGA ON L5A 4G1	224.5	28

EBR - Environmental Registry

A search of the EBR database, dated 1994 - Mar 31, 2026 has found that there are 1 EBR site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GWL Realty Advisors Inc.	2085 Hurontario St Mississauga Ontario Mississauga ON	224.5	28

ECA - Environmental Compliance Approval

A search of the ECA database, dated Oct 2011 - Feb 28, 2026 has found that there are 5 ECA site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Dejan Ciprovski	100 Harborn Rd Mississauga ON L5B 1A4	110.3	10
GWL Realty Advisors Inc.	2085 Hurontario St Mississauga ON	224.5	28
Berkley Homes (Gordon Woods II) Inc.	Grange Dr Mississauga ON L4K 3N3	231.8	31
PLM Holdings Inc.	2150 Hurontario Street Mississauga ON M8Z 1N6	264.0	38
Fernanda Leal	2122 Gordon Drive Mississauga ON L4Y 3R7	297.4	43

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Feb 28, 2026 has found that there are 17 EHS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	50 and 60 Harborn Road Mississauga ON L5B 1A4	4.0	1

Site	Address	Distance (m)	Map Key
	39 and 42 Harborn Road Mississauga ON	69.2	6
	2100 Hurontario St Mississauga ON L5B 1M8	173.8	19
	2114 Hurontario Street Mississauga ON L5B 1M8	197.4	23
	Hurontario St/ QEW (Ramps on Hwy) Mississauga ON	206.6	26
	2085 Hurontario Street MISSISSAUGA ON L5A 4G1	224.5	28
	2085 Hurontario Street Mississauga ON L5A 4G1	224.5	28
	2085 Hurontario St Mississauga ON L5A4G1	224.5	28
	2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1	224.5	28
	2085 Hurontario Street Mississauga ON Mississauga ON L5A 4G1	224.8	29
	2143 Grange Drive Mississauga ON	232.2	32
	2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1	240.5	34
	Forntinf West Side of Hurontario 2130 Hurontario Street Mississauga ON	244.9	35

Site	Address	Distance (m)	Map Key
	2156 Hurontario Street Mississauga ON L5B 1M8	292.6	40
	88 Bronte College Court Mississauga ON L5B 1M9	294.0	41
	2100 Sherobee Road Mississauga ON L5A 4C5	297.7	45
	2180 Hurontario Street Mississauga ON L5B 1M8	298.8	47

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Sep 30, 2025 has found that there are 16 GEN site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Harborn Dental	3-2090 Hurontario St Mississauga ON L5B1M8	136.7	15
	Generator No.* | *Years Reported: ON3307537 | 25,24,23,22,21,20,19,18,17,16,15		
Summerville Family Health Team	2090 Hurontario St. Mississauga ON	136.7	15
	Generator No.* | *Years Reported: ON4630519 | 11,10		
Mobilinx	2100 Hurontario Street Mississauga ON L5B 1M8	173.8	19
	Generator No.* | *Years Reported: ON5973701 | 22,21		
Stewart Foodservice Inc	Hurrontario , QEW EB on ramp Mississauga ON	190.6	20
	Generator No.* | *Years Reported: ONS0305-1-5SRL29-1 | 25,24		
The Great West Life Assurance Company	2085 Hurontario St. Mississauga ON	224.5	28
	Generator No.* | *Years Reported: ON8446233 | 09,08,07,06,05,04		

Site	Address	Distance (m)	Map Key
Starneon Ltd partnership	2085 Hurontario St. Mississauga ON L5A4G1	224.5	28
	Generator No.* | *Years Reported: ON8164955 | 21,20		
Trillium Health Partners	2085 Hurontario Street Missisauga ON L5A4G1	224.5	28
	Generator No.* | *Years Reported: ON4047570 | 25,24,23,22,21,20,19,18,17,16,15,14,13,12,11,10		
Kenaidan Contracting Ltd	88 Bronte College Court Mississauga ON L5B 1M9	294.0	41
	Generator No.* | *Years Reported: ON001066937 | 25		
BRONTE COLLEGE OF CANADA	88 BRONTE COLLEGE COURT MISSISSAUGA ON L5B 1M9	294.0	41
	Generator No.* | *Years Reported: ON4119045 | 22,21,20,19,18,17,16,15,14,13,12,11,10		
SNC LAVALIN PROFAC INC.	49 South Service Road Mississauga ON	297.6	44
	Generator No.* | *Years Reported: ON6197573 | 09		
Civil Underground and excavation company	49 south service rd mississauga ON	297.6	44
	Generator No.* | *Years Reported: ON5756807 | 10		
Mobilinx	49 South Service Rd Mississauga ON L5G 2R8	297.6	44
	Generator No.* | *Years Reported: ON9628654 | 22		
SNC Lavalin-ProFac	49 South Service Road Mississauga ON	297.6	44
	Generator No.* | *Years Reported: ON8719017 | 09,08,07		
Enersource Hydro Mississauga	2100 Sherobee Road Mississauga ON L5A4C5	297.7	45
	Generator No.* | *Years Reported: ON6368899 | 16		
Turner & Porter Funeral Directors Ltd.	2180 Hurontario Street Mississauga ON L5B 1M8	298.8	47
	Generator No.* | *Years Reported: ON9465628 | 25,23		
TURNER & PORTER FUNERAL DIRECTORS	2180 HURONTARIO STREET MISSISSAUGA ON L5B 1M8	298.8	47
	Generator No.* | *Years Reported: ONF037100 | 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,04,03,01,00,99,98,97,96,95,94,93,92,91,90,89,88		

INC - Fuel Oil Spills and Leaks

A search of the INC database, dated Oct 2023 has found that there are 2 INC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	43 Harborn Road, Mississauga ON	44.9	2
	2112 GRANGE DR, MISSISSAUGA ON	133.5	14

NPRI - National Pollutant Release Inventory - Historic

A search of the NPRI database, dated 1993-May 2017 has found that there are 1 NPRI site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
GWL REALTY ADVISORS	2085 HURONTARIO Street MISSISSAUGA ON L5A4G1	224.5	28

PINC - Pipeline Incidents

A search of the PINC database, dated Feb 28, 2021 has found that there are 2 PINC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	40 Harborn Road, Mississauga ON	55.8	4
ENBRIDGE GAS INC	2080 GORDON DR,,MISSISSAUGA,ON,L5B 1S5,CA ON	203.1	25

PTTW - Permit to Take Water

A search of the PTTW database, dated 1994 - Mar 31, 2026 has found that there are 1 PTTW site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Salini Impregilo Civil Works Inc.	49 South Service Road Mississauga, ON L5G 2R8 Canada ON L5G 2R8	297.6	44

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004 - 31 Mar, 2026 has found that there are 1 RSC site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
EDENSHAW SSR DEVELOPMENTS LIMITED	49 South Service RD Mississauga ON	297.6	44

SCT - Scott's Manufacturing Directories

A search of the SCT database, dated 1992-Mar 2011; Feb 2025 has found that there are 10 SCT site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Cincom Systems of Canada Ltd	2085 Hurontario St Suite 200 Mississauga ON L5A 4G1	224.5	28
STEPHAN MACHINERY (CANADA) LTD	2085 HURONTARIO ST SUITE 300 MISSISSAUGA ON L5A 4G1	224.5	28
REPRODUX LIMITED	2085 HURONTARIO ST SUITE 101 MISSISSAUGA ON L5A 4G1	224.5	28
Autobranch Technologies	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	224.5	28
Owen Media Partners Inc.	2085 Hurontario St Suite 208 Mississauga ON L5A 4G1	224.5	28
OCWA Corporate Head office	2085 Hurontario St Mississauga ON L5A2E6	224.5	28

Site	Address	Distance (m)	Map Key
Stephan Machinery (Canada) Limited	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	224.5	28
ONIX SYSTEMS GROUP INC.	2085 Hurontario St Suite 300 Mississauga ON L5A 4G1	224.5	28
Reprodux Copy Centres Ltd.	2085 Hurontario St Suite 101 Mississauga ON L5A 4G1	224.5	28
J T GILMOUR INC.	2085 HURONTARIO ST SUITE 300 MISSISSAUGA ON L5A 4G1	224.5	28

SPL - Ontario Spills

A search of the SPL database, dated 1988- Feb 2026 has found that there are 14 SPL site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ENBRIDGE GAS INC.	100 Harborn Rd, Mississauga ON MISSISSAUGA ON	110.3	10
	2112 Grange Dr. Mississauga ON	133.5	14
	Hurontario St and North Service Rd, Mississauga MISSISSAUGA ON	161.3	17
	QEW Eastbound Hunrontario Street exit ramp Mississauga ON	190.6	20
	QEW & Hurontario St. Mississauga ON	190.6	20
PRIVATE OWNER	QEW WESTBOUND, EAST OF HWY 10 MOTOR VEHICLE (OPERATING FLUID) MISSISSAUGA CITY ON	190.6	20


Site	Address	Distance (m)	Map Key
TRANSPORT TRUCK	HURONTARIO ST. (JUST NORTH OF QEW) TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON	190.6	20
	NE of QEW off Ramp at Hurontario MISSISSAUGA ON	199.8	24
Enbridge Energy Distribution Inc.	2080 Gordon Dr. Mississauga ON	203.1	25
ELF ATOCHEM CANADA INC.	QEW EAST/WESTBOUND - 2055 HURONTARIO ST. TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON L5A 2E6	260.5	37
	155 Harborn Road MISSISSAUGA ON	297.4	42
SNC Lavalin Profac<UNOFFICIAL>	49 South Service Road Mississauga ON L5G 2R8	297.6	44
Enersource Hydro Mississauga Inc.	2100 Sherobee Rd. Mississauga ON	297.7	45
	2100 Sherobe Dr Mississauga ON	297.7	45

WWIS - Water Well Information System

A search of the WWIS database, dated Jul 31, 2025 has found that there are 10 WWIS site(s) within approximately 0.30 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	N/A NE Premium Way+ Harborn Rd Mississauga ON ***Well ID:*** 7484830	84.7	8

Site	Address	Distance (m)	Map Key
	HURONTARIO & HARBORN RD. Mississauga ON ***Well ID:*** 7105998	108.9	9
	HURONTOARIO AND HARBORN MISSISSAUGA ON ***Well ID:*** 4909961	113.0	11
	ON ***Well ID:*** 7170331	117.2	12
	2100 Hurontario St ON ***Well ID:*** 7371898	127.6	13
	2055 Hurontario St ON ***Well ID:*** 7371907	166.3	18
	ON ***Well ID:*** 7260102	192.4	21
	60 S Service Rd ON ***Well ID:*** 7371899	214.3	27
	HURONTARIO ST Mississauga ON ***Well ID:*** 7277550	233.4	33
	lot 2 con 3 ON ***Well ID:*** 4902195	246.2	36



Map: 0.3 Kilometer Radius

Order Number: 26042400864

Address: 60 Harborn Road, Mississauga, ON

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major Arterial; Minor Arterial
- Local Road
- Service Road; Traffic Circle; Ramp
- Rail
- Beach
- Airport
- Industrial Area
- Military Base
- Aircraft Roads
- Native Reservation
- Hospital
- Shopping & Sports Area
- University/College
- Cemetery; Golf Course
- Parkt (National)
- Park (City/County)

Source: © 2021 ESRI StreetMap Premium.

© ERIS Information Limited Partnership



Aerial


Year: 2025

Order Number: 26042400864

Address: 60 Harborn Road, Mississauga, ON

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Address: 60 Harborn Road, ON

Source: ESRI World Topographic Map

Order Number: 26042400864

ERIS

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	NNE/4.0	99.0 / 1.87	50 and 60 Harborn Road Mississauga ON L5B 1A4	EHS

Order No:	25052900265	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	03-JUN-25	**Search Radius (km):**	.25
Date Received:	29-MAY-25	**X:**	-79.60269827
Previous Site Name:		**Y:**	43.56856435
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	NNW/44.9	100.8 / 3.69	43 Harborn Road, Mississauga ON	INC

Incident No:	456596	**Any Health Impact:**	No
Incident ID:	2608452	**Any Enviro Impact:**	Unknown
Instance No:		**Service Intrp:**	Yes
Status Code:	Causal Analysis Complete	**Was Prop Damaged:**	Yes
Incident Status:		**Reside App. Type:**	
Incident Severity:		**Commer App. Type:**	
Task No:	3063525	**Indus App. Type:**	
Attribute Category:	FS-Perform L1 Incident Insp	**Institut App. Type:**	
Context:		**Depth Ground Cover:**	0.8
Date of Occurrence:	2010/09/15 00:00:00	**Operation Pressure:**	ip
Time of Occurrence:	13:42:49	**Equipment Type:**	
Occr Insp Start Dt:	2010/09/21 00:00:00	**Equipment Model:**	
Incident Creat On:		**Serial No:**	
Instance Creat Dt:		**Cylinder Capacity:**	
Instance Install Dt:		**Cylinder Cap Units:**	
Approx Quant Rel:		**Cylinder Mat Type:**	
Tank Capacity:		**Pump Flow Rate Cap:**	
Fuels Occur Type:	Vapour Release	**Contam. Migrated:**	
Occur Type Rpt:		**Near Body of Water:**	
Occur Category:		**Drainage System:**	
Fuel Type Involved:	Natural Gas	**Sub Surface Contam:**	
Fuel Type Reported:		**Tank Material Type:**	
Enforcement Policy:	NULL	**Tank Storage Type:**	
Prc Escalation Req:	NULL	**Tank Location Type:**	
Item:			
Item Description:			
Device Installed Location:			
Venting Type:			
Vent Conn Mater:			
Vent Chimney Mater:			
Pipeline Type:	Service / Riser Distribution Pipeline		
Pipeline Involved:			
Pipe Material:	Plastic		
Regulator Location:	Outside		
Regulator Type:	Service Regulator (up to 60 psi intake)		
Liquid Prop Make:			
Liquid Prop Model:			
Liquid Prop Serial No:			
Liquid Prop Notes:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Inventory Address: 43 Harborn Road, Mississauga - 1/2" Pipeline Hit
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: Line damage no locates
Operation Type Involved: Construction Site (including excavation)

---

3 | **1 of 1** | **NE/47.9** | **100.7 / 3.57** | **E C LILLIE**
42 HARBORN ROAD
MISSISSAUGA ON | **CFOT**

Inventory No: 60985374
Inventory Status: Active
Installation Year: 1952
Capacity: 3784
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Steel
Corrosion Protect:
Overfill Protection:
Inventory Context: FS Fuel Oil Tank
Inventory Item: FS FUEL OIL TANK

---

4 | **1 of 1** | **NNE/55.8** | **100.8 / 3.69** | **40 Harborn Road, Mississauga ON** | **PINC**

Incident Id: 2828674
Incident No: 671850
Incident Reported Dt:
Type: FS-Pipeline Incident
Status Code: Pipeline Damage Reason Est
Tank Status: RC Established
Task No: 3508580
Spills Action Centre:
Fuel Type: Natural Gas
Fuel Occurrence Tp: Pipeline Strike
Date of Occurrence: 10/3/2011 0:00
Occurrence Start Dt: 2011/10/16
Depth:
Customer Acct Name:
Incident Address:
Operation Type: Construction Site (pipeline strike)
Pipeline Type:
Regulator Type:
Summary: 40 Harborn Road, Mississauga - 1/2" Pipeline Hit
Reported By: Blackburn, Chris - Enbridge
Affiliation: Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
Occurrence Desc: Damaged 1/2" PE IP gas service
Damage Reason: Excavation practices not sufficient
Notes:

Pipe Material:
Fuel Category: Natural Gas
Health Impact: No
Environment Impact: No
Property Damage: No
Service Interrupt: Yes
Enforce Policy: No
Public Relation: No
Pipeline System:
PSIG:
Attribute Category: FS-Perform P-line Inc Invest
Regulator Location:
Method Details: E-mail

---

5 | **1 of 1** | **N/59.6** | **100.8 / 3.69** | **R.M. OF PEEL**
GRANGE DR/HARBORN RD.
MISSISSAUGA CITY ON | **CA**

Certificate #: 7-1184-95-006
Application Year: 95
Issue Date: 12/20/95
Approval Type: Municipal water
Status: Approved
Application Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

6 | **1 of 1** | **NNE/69.2** | **100.8 / 3.69** | **39 and 42 Harborn Road Mississauga ON** | **EHS**

Order No:	20060907030	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	9/18/2006	**Search Radius (km):**	0.25
Date Received:	9/7/2006	**X:**	-79.602747
Previous Site Name:		**Y:**	43.569336
Lot/Building Size:			
Additional Info Ordered:			

---

7 | **1 of 1** | **SE/78.5** | **93.3 / -3.87** | **TRANS-NORTHERN PIPELINES INC./ PIPELINES TRANS-NORD INC.** | **EASR**

ON

Approval No:	R-009-2112152807	**MOE District:**	Halton-Peel
Status:	REGISTERED	**Municipality:**	
Date:	2020-03-19	**Latitude:**	43.5675
Record Type:	EASR	**Longitude:**	-79.60194444
Link Source:	MOFA	**Geometry X:**	
Project Type:	Water Taking - Construction Dewatering	**Geometry Y:**	
Full Address:			
Approval Type:	EASR-Water Taking - Construction Dewatering		
SWP Area Name:	Credit Valley		
PDF NAICS Code:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2226947		
PDF Site Location:			

---

8 | **1 of 1** | **NNE/84.7** | **100.8 / 3.69** | **N/A NE Premium Way+ Harborn Rd Mississauga ON** | **WWIS**

Well ID:	7484830	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	08/27/2024
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	N84UPRME	**Contractor:**	6607
Tag:	A401732	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	MISSISSAUGA CITY (PORT CREDIT)		

Site Info: Grass Area at NE corner of Premium way + Harborn R

Bore Hole Information

Bore Hole ID:	1010406758	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612880.00
Code OB Desc:		***North83:***	4824992.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	04/08/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1010406964
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	28
Material 3 Desc:	SAND
Formation Top Depth:	0.0
Formation End Depth:	3.299999952316284
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1010406965
Layer:	2
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	
Material 3 Desc:	
Formation Top Depth:	3.299999952316284
Formation End Depth:	6.0
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1010407141
Layer:	2
Plug From:	0.30000001192092896
Plug To:	2.700000047683716

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1010407140
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1010407098
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1010406849
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1010406823
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1010407006
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: -0.6000000238418579
Depth To: 3.0
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1010407030
Layer: 1
Slot: 10
Screen Top Depth: 3.0
Screen End Depth: 6.0
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1010406824
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1010406911
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.299999952316284
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1010407068
Diameter: 21.0
Depth From: 0.0
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

---

9 | ***1 of 1*** | ***NE/108.9*** | ***100.8 / 3.69*** | ***HURONTARIO & HARBORN RD. Mississauga ON*** | ***WWIS***

Well ID: 7105998
Construction Date:
Use 1st: Dewatering
Use 2nd:
Final Well Status: Dewatering
Water Type:
Casing Material:
Audit No: M00383
Tag: A066205
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 06/04/2008
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6926
Form Version: 5
Owner:
County: PEEL
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Additional Detail(s) (Map)

Bore Hole ID: 1002773345
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5696327111058
Longitude: -79.6020368998431
Point Y: 43.569632708375785
Point X: -79.602036750359

Additional Detail(s) (Map)

Bore Hole ID: 1002773363
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5696678086673
Longitude: -79.6019617868727
Point Y: 43.56966780678356
Point X: -79.60196163684901

Additional Detail(s) (Map)

Bore Hole ID: 1002773465
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5695056301585
Longitude: -79.6019531552713
Point Y: 43.56950562729724
Point X: -79.6019530049545

Additional Detail(s) (Map)

Bore Hole ID: 1002773483
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5695500320153
Longitude: -79.601902594122
Point Y: 43.569550029875906
Point X: -79.60190244418922

Additional Detail(s) (Map)

Bore Hole ID: 1002773501
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5695852809171
Longitude: -79.6018398611687
Point Y: 43.56958527868182
Point X: -79.60183971125655

Additional Detail(s) (Map)

Bore Hole ID: 1002773429
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.569408279072
Longitude: -79.6020916254356
Point Y: 43.569408276835986
Point X: -79.60209147483017

Additional Detail(s) (Map)

Bore Hole ID: 1002773354
Depth (m):
Year Completed: 2008
Well Completed Dt: 05/09/2008
Audit No: M00383
Path:
Tag No: A066205
Contractor: 6926
Latitude: 43.5696502598929
Longitude: -79.6019993433687
Point Y: 43.569650257582225
Point X: -79.6019991927057

Additional Detail(s) (Map)

Bore Hole ID:	1002773372	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.569694358934
Well Completed Dt:	05/09/2008	***Longitude:***	-79.6019240221056
Audit No:	M00383	***Point Y:***	43.569694356751405
Path:		***Point X:***	-79.60192387168415

Additional Detail(s) (Map)

Bore Hole ID:	1002773538	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5696557786137
Well Completed Dt:	05/12/2008	***Longitude:***	-79.6017143950437
Audit No:	M00383	***Point Y:***	43.569655776882705
Path:		***Point X:***	-79.60171424539115

Additional Detail(s) (Map)

Bore Hole ID:	1001605983	***Tag No:***	A066205
Depth (m):	6.1	***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5694613796864
Well Completed Dt:	05/30/2008	***Longitude:***	-79.6020160963103
Audit No:	M00383	***Point Y:***	43.56946137763963
Path:		***Point X:***	-79.60201594629706

Additional Detail(s) (Map)

Bore Hole ID:	1002773309	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5695350571382
Well Completed Dt:	05/08/2008	***Longitude:***	-79.6021506102109
Audit No:	M00383	***Point Y:***	43.56953505481623
Path:		***Point X:***	-79.60215045997839

Additional Detail(s) (Map)

Bore Hole ID:	1002773327	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5695884605894
Well Completed Dt:	05/08/2008	***Longitude:***	-79.6020998409568
Audit No:	M00383	***Point Y:***	43.569588458811495
Path:		***Point X:***	-79.60209969080324

Additional Detail(s) (Map)

Bore Hole ID:	1002773456	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5694789284686
Well Completed Dt:	05/09/2008	***Longitude:***	-79.6019785399379
Audit No:	M00383	***Point Y:***	43.56947892559425
Path:		***Point X:***	-79.60197839044038

Additional Detail(s) (Map)

Bore Hole ID:	1002773474	***Tag No:***	A066205
Depth (m):		***Contractor:***	6926
Year Completed:	2008	***Latitude:***	43.5695233303373

Well Completed Dt:	05/09/2008	**Longitude:**	-79.6019279788298
Audit No:	M00383	**Point Y:**	43.56952332754173
Path:		**Point X:**	-79.6019278287768

Additional Detail(s) (Map)

Bore Hole ID:	1002773520	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.5696295312877
Well Completed Dt:	05/12/2008	**Longitude:**	-79.6017769198717
Audit No:	M00383	**Point Y:**	43.56962952889934
Path:		**Point X:**	-79.60177676991398

Additional Detail(s) (Map)

Bore Hole ID:	1002773529	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.5696472314258
Well Completed Dt:	05/12/2008	**Longitude:**	-79.6017517433271
Audit No:	M00383	**Point Y:**	43.56964722845652
Path:		**Point X:**	-79.60175159283796

Additional Detail(s) (Map)

Bore Hole ID:	1002773291	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.569490655169
Well Completed Dt:	05/08/2008	**Longitude:**	-79.6022011711679
Audit No:	M00383	**Point Y:**	43.5694906528774
Path:		**Point X:**	-79.60220102074366

Additional Detail(s) (Map)

Bore Hole ID:	1002773336	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.569606009398
Well Completed Dt:	05/08/2008	**Longitude:**	-79.602062284528
Audit No:	M00383	**Point Y:**	43.56960600672912
Path:		**Point X:**	-79.60206213494658

Additional Detail(s) (Map)

Bore Hole ID:	1002773511	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.5696118311438
Well Completed Dt:	05/12/2008	**Longitude:**	-79.6018020964016
Audit No:	M00383	**Point Y:**	43.569611828686064
Path:		**Point X:**	-79.60180194609167

Additional Detail(s) (Map)

Bore Hole ID:	1002773547	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:	2008	**Latitude:**	43.5696734787376
Well Completed Dt:	05/12/2008	**Longitude:**	-79.60168921847
Audit No:	M00383	**Point Y:**	43.5696734764322
Path:		**Point X:**	-79.60168906831512

Additional Detail(s) (Map)

Bore Hole ID: 1002773300 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5695173569097
Well Completed Dt: 05/08/2008 **Longitude:** -79.6021757865934
Audit No: M00383 **Point Y:** 43.569517354575225
Path: **Point X:** -79.60217563705442

Additional Detail(s) (Map)

Bore Hole ID: 1002773420 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5697030575997
Well Completed Dt: 05/09/2008 **Longitude:** -79.6018990538291
Audit No: M00383 **Point Y:** 43.569703055520556
Path: **Point X:** -79.60189890391634

Additional Detail(s) (Map)

Bore Hole ID: 1002773438 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5694349807885
Well Completed Dt: 05/09/2008 **Longitude:** -79.6020662408488
Audit No: M00383 **Point Y:** 43.5694349785703
Path: **Point X:** -79.60206609114088

Additional Detail(s) (Map)

Bore Hole ID: 1002773492 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5695227246572
Well Completed Dt: 05/09/2008 **Longitude:** -79.6018784589239
Audit No: M00383 **Point Y:** 43.5695227228869
Path: **Point X:** -79.60187830916257

Additional Detail(s) (Map)

Bore Hole ID: 1002773318 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5695617588668
Well Completed Dt: 05/08/2008 **Longitude:** -79.6021252255952
Audit No: M00383 **Point Y:** 43.56956175649433
Path: **Point X:** -79.60212507628913

Additional Detail(s) (Map)

Bore Hole ID: 1002773447 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5694436794874
Well Completed Dt: 05/09/2008 **Longitude:** -79.6020412727002
Audit No: M00383 **Point Y:** 43.56944367672608
Path: **Point X:** -79.60204112337307

Additional Detail(s) (Map)

Bore Hole ID: 1002773556 **Tag No:** A066205
Depth (m): **Contractor:** 6926
Year Completed: 2008 **Latitude:** 43.5695600934289
Well Completed Dt: 05/12/2008 **Longitude:** -79.6019890457596
Audit No: M00383 **Point Y:** 43.569560090277534
Path: **Point X:** -79.60198889622713

Bore Hole Information

Bore Hole ID:	1002773511	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612907.00
Code OB Desc:		***North83:***	4825022.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	05/12/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773515
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773514
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773516
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773518
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773517
Layer:	
Slot:	
Screen Top Depth:	4.0

Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773519
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773513
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773520
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/12/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612909.00
North83: 4825024.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773524
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:	1002773523
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773525
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773527
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773526
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773528
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID: 1002773522
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773556
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/12/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612892.00
North83: 4825016.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773560
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773559
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773561
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773563
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1002773562
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773564
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002773558
Diameter:	20.31999969482422
Depth From:	
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002773291	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612875.00
Code OB Desc:		***North83:***	4825008.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	05/08/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment

Sealing Record

Plug ID:	1002773295
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773294
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773296
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773298
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773297
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773299
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	

Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773293
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773345
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612888.00
North83: 4825024.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773349
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773348
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773350
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773352
Layer:

Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773351
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773353
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773347
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773372
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:

Elevation:
Elevrc:
Zone: 17
East83: 612897.00
North83: 4825031.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002773376
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773375
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773377
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773379
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773378
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773380
Pump Set At:
Static Level:
Final Level After Pumping:

Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773374
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773429
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 612884.00
North83: 4824999.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773433
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773432
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773434
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773436
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773435
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773437
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773431
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773483
DP2BR:
Spatial Status:
Code OB:
Elevation:
Elevrc:
Zone: 17
East83: 612899.00

Code OB Desc:		**North83:**	4825015.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	05/09/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773487
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773486
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773488
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773490
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773489
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773491
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773485
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773318
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/08/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612881.00
North83: 4825016.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773322
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773321
Method Construction Code:

Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773323
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773325
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773324
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773326
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773320
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1002773447	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612888.00
Code OB Desc:		***North83:***	4825003.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	05/09/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773451
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773450
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773452
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773454
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773453
Layer:	
Slot:	

Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773455
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773449
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773474
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 612897.00
North83: 4825012.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773478
Layer:
Plug From:
Plug To:

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773477
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773479
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773481
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773480
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773482
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773476
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773529
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/12/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612911.00
North83: 4825026.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773533
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773532
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773534
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773536
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773535
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773537
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773531
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773547
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/12/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612916.00
North83: 4825029.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID:	1002773551
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773550
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773552
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773554
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773553
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773555
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	

Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773549
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773309
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/08/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612879.00
North83: 4825013.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773313
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773312
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773314
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773316

Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773315
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773317
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773311
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773336
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/08/2008
Remarks:
Location Method Desc: on Water Well Record

Elevation:
Elevrc:
Zone: 17
East83: 612886.00
North83: 4825021.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002773340
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773339
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773341
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773343
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773342
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773344
Pump Set At:
Static Level:

Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773338
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773456
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612893.00
North83: 4825007.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773460
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773459
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773461

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773463
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773462
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773464
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773458
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773492 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17

Code OB:		**East83:**	612901.00
Code OB Desc:		**North83:**	4825012.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	05/09/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773496
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773495
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773497
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773499
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773498
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773500
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773494
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773538
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/12/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612914.00
North83: 4825027.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773542
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773541
Method Construction Code:

Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773543
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773545
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773544
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773546
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773540
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1002773354	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612891.00
Code OB Desc:		***North83:***	4825026.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	05/09/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773358
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773357
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773359
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773361
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773360
Layer:	
Slot:	

Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773362
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773356
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773420
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612899.00
North83: 4825032.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773424
Layer:
Plug From:
Plug To:

Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773423
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773425
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773427
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773426
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773428
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773422
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773438
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612886.00
North83: 4825002.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773442
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773441
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773443
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773445
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773444
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773446
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773440
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001605983
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole: No
Cluster Kind:
Date Completed: 05/30/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612890.00
North83: 4825005.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID:	1002773568
Layer:	3
Color:	2
General Color:	GREY
Material 1:	28
Material 1 Desc:	SAND
Material 2:	11
Material 2 Desc:	GRAVEL
Material 3:	84
Material 3 Desc:	SILTY
Formation Top Depth:	3.9000000953674316
Formation End Depth:	6.099999904632568
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002773567
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	06
Material 2 Desc:	SILT
Material 3:	01
Material 3 Desc:	FILL
Formation Top Depth:	0.8999999761581421
Formation End Depth:	3.9000000953674316
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002773566
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	02
Material 1 Desc:	TOPSOIL
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.8999999761581421
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002773570
Layer:	1
Plug From:	0.0
Plug To:	1.0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 1002773572
Layer: 3
Plug From: 3.5
Plug To: 6.099999904632568
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002773571
Layer: 2
Plug From: 1.0
Plug To: 3.5
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1002773576
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 1002773565
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773573
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 4.099999904632568
Casing Diameter: 5.599999904632568
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773574
Layer: 1
Slot: 20
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.800000190734863

Hole Diameter

Hole ID: 1002773569
Diameter: 20.31999969482422
Depth From: 0.0
Depth To: 6.099999904632568

Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773300
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/08/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612877.00
North83: 4825011.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773304
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773303
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773305
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773307
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773306

Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773308
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773302
Diameter: 20.299999237060547
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773363
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation:
Elevrc:
Zone: 17
East83: 612894.00
North83: 4825028.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773367
Layer:

Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773366
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773368
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002773370
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.0
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773369
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773371
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1002773365
Diameter:	20.299999237060547
Depth From:	
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002773465	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612895.00
Code OB Desc:		***North83:***	4825010.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	05/09/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002773469
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773468
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773470
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773472
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0

Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002773471
Layer:
Slot:
Screen Top Depth: 4.0
Screen End Depth: 6.0
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1002773473
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773467
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773501
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/09/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612904.00
North83: 4825019.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID:	1002773505
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	1002773504
Method Construction Code:	
Method Construction:	
Other Method Construction:	AUGER

Pipe Information

Pipe ID:	1002773506
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002773508
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773507
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773509
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	

Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002773503
Diameter: 20.31999969482422
Depth From:
Depth To: 6.0
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002773327
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 05/08/2008
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612883.00
North83: 4825019.00
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002773331
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID: 1002773330
Method Construction Code:
Method Construction:
Other Method Construction: AUGER

Pipe Information

Pipe ID: 1002773332
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1002773334
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002773333
Layer:	
Slot:	
Screen Top Depth:	4.0
Screen End Depth:	6.0
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1002773335
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002773329
Diameter:	20.299999237060547
Depth From:	
Depth To:	6.0
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
10	1 of 2	SW/110.3	100.2 / 3.01	***Dejan Ciprovski*** ***100 Harborn Rd*** ***Mississauga ON L5B 1A4***	ECA

Approval No:	3297-CJB5FF	***MOE District:***	Halton-Peel
Approval Date:	October 24, 2022	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	-8861448.9152000006

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SWP Area Name: Credit Valley **Geometry Y:** 5398741.9655999979
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Dejan Ciprovski
Address: 100 Harborn Rd
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2250-CJ3KS2-14.pdf
PDF Site Location: 100 Harborn Road
City of Mississauga, Regional Municipality of Peel

10	2 of 2	SW/110.3	100.2 / 3.01	ENBRIDGE GAS INC. 100 Harborn Rd, Mississauga ON MISSISSAUGA ON	SPL

Ref No: 1-3WBWJ8 **Municipality No:**
Year: **Nature of Damage:**
Incident Dt: 10/3/2023 9:48:08 AM **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**
MOE Reported Dt: 10/3/2023 1:21:08 PM **Impact to Health:**
Dt Document Closed: **Agency Involved:**
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 100 Harborn Rd, Mississauga ON
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: MISSISSAUGA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: ENBRIDGE GAS INC.
Client Type: Public Utilities Corporation
Source Type: Pipeline/Components
Incident Cause:
Incident Preceding Spill: Line Strike
Incident Reason: Human error (Specify)
Incident Summary: TSSA: 4" pl IP main; made safe - Mississauga
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 other - see notes
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: NATURAL GAS
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Activity Preceding Spill: Construction or repair
Property 2nd Watershed: 02H | Northern Lake Ontario and Niagara River
Property Tertiary Watershed: 02HB | Sixteen Mile Creek - Credit River
Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001815913"],"wkts":["POINT (-79.6037307000 43.5674511000)"],"creation_date":"2023-10-03"}
Time Reported:

System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

11 | **1 of 1** | **NE/113.0** | **100.8 / 3.69** | **HURONTOARIO AND HARBORN MISSISSAUGA ON** | **WWIS**

Well ID:	4909961	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Not Used	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Test Hole	**Date Received:**	11/30/2005
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z39680	**Contractor:**	7230
Tag:	A035793	**Form Version:**	3
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	MISSISSAUGA CITY (PORT CREDIT)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4909961.pdf

Additional Detail(s) (Map)

Well Completed Date:	10/25/2005
Year Completed:	2005
Depth (m):	7.7
Latitude:	43.5694348293857
Longitude:	-79.6020538608896
Point X:	-79.60205371146192
Point Y:	43.569434826918226
Path:	490\4909961.pdf

Bore Hole Information

Bore Hole ID:	11323694	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	612887.00
Code OB Desc:		**North83:**	4825002.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/25/2005	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			

Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	933021868
Layer:	3
Color:	2
General Color:	GREY
Material 1:	05
Material 1 Desc:	CLAY
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	5.5
Formation End Depth:	7.699999809265137
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933021866
Layer:	1
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	01
Material 2 Desc:	FILL
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.0
Formation End Depth:	0.3100000023841858
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933021867
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	0.3100000023841858
Formation End Depth:	5.5
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933282280
Layer:	1
Plug From:	0.0
Plug To:	0.3100000023841858
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933282279
Layer:	2
Plug From:	0.3100000023841858
Plug To:	2.5
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	964909961
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	11338549
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930866744
Layer:	1
Material:	
Open Hole or Material:	
Depth From:	0.0
Depth To:	4.0
Casing Diameter:	
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933415776
Layer:	1
Slot:	10
Screen Top Depth:	4.0
Screen End Depth:	5.5
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Water Details

Water ID:	934068402
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	3.0999999046325684
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	11543563
Diameter:	12.5

Depth From:	0.0
Depth To:	7.699999809265137
Hole Depth UOM:	m
Hole Diameter UOM:	cm

12 *1 of 1* *NE/117.2* *100.8 / 3.69* *ON* *WWIS*

Well ID:	7170331	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	10/20/2011
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	M03466	**Contractor:**	6926
Tag:	A066205	**Form Version:**	5
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	MISSISSAUGA CITY (PORT CREDIT)		
Site Info:			

Additional Detail(s) (Map)

Bore Hole ID:	1003588086	**Tag No:**	A066205
Depth (m):		**Contractor:**	6926
Year Completed:		**Latitude:**	43.5694613796864
Well Completed Dt:		**Longitude:**	-79.6020160963103
Audit No:	M03466	**Point Y:**	43.56946137763963
Path:		**Point X:**	-79.60201594629706

Bore Hole Information

Bore Hole ID:	1003588086	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	612890.00
Code OB Desc:		**North83:**	4825005.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:		**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

13 *1 of 1* *NE/127.6* *100.8 / 3.69* *2100 Hurontario St ON* *WWIS*

Well ID:	7371898	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	

Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	11/03/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	YRSC4WRL	**Contractor:**	7360
Tag:	A288829	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: MISSISSAUGA CITY (PORT CREDIT)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7371898.pdf

Additional Detail(s) (Map)

Well Completed Date: 04/15/2020
Year Completed: 2020
Depth (m): 7.62
Latitude: 43.5693939777715
Longitude: -79.6016585353926
Point X: -79.6016583854927
Point Y: 43.569393975354885
Path: 737\7371898.pdf

Bore Hole Information

Bore Hole ID:	1008490861	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	612919.00
Code OB Desc:		**North83:**	4824998.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/15/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008490988
Layer: 1
Color: 6
General Color: BROWN
Material 1: 02
Material 1 Desc: TOPSOIL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:

Formation Top Depth: 0.0
Formation End Depth: 4.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490991
Layer: 4
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 14.0
Formation End Depth: 25.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490990
Layer: 3
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 10.0
Formation End Depth: 14.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490989
Layer: 2
Color: 6
General Color: BROWN
Material 1: 01
Material 1 Desc: FILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 4.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491115
Layer: 1
Plug From: 3.0
Plug To: 13.0

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491086
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008490944
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008490914
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008491037
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 15.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008491052
Layer: 1
Slot: 0.1
Screen Top Depth: 15.0
Screen End Depth: 25.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008490915
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:

Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008490978
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 19.5
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1008491067
Diameter: 6.0
Depth From: 0.0
Depth To: 25.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

14 ***1 of 2*** ***NW/133.5*** ***100.8 / 3.69*** ***2112 GRANGE DR, MISSISSAUGA ON*** ***INC***

Incident No: 1409592
Incident ID:
Instance No:
Status Code:
Incident Status:
Incident Severity:
Task No: 5039900
Attribute Category: FS-Perform L1 Incident Insp
Context:
Date of Occurrence: 2014/06/04 00:00:00
Time of Occurrence: 15:24:00
Occr Insp Start Dt: 2014/08/06 00:00:00
Incident Creat On:
Instance Creat Dt:
Instance Install Dt:
Approx Quant Rel:
Tank Capacity:
Fuels Occur Type: Leak
Occur Type Rpt:
Occur Category:
Fuel Type Involved: Fuel Oil
Fuel Type Reported:
Enforcement Policy: NULL
Prc Escalation Req: NULL
Item:
Item Description:
Device Installed Location:
Venting Type:
Vent Conn Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:

Any Health Impact: No
Any Enviro Impact: No
Service Intrp: No
Was Prop Damaged: No
Reside App. Type:
Commer App. Type:
Indus App. Type:
Institut App. Type:
Depth Ground Cover:
Operation Pressure:
Equipment Type:
Equipment Model:
Serial No:
Cylinder Capacity:
Cylinder Cap Units:
Cylinder Mat Type:
Pump Flow Rate Cap:
Contam. Migrated:
Near Body of Water:
Drainage System:
Sub Surface Contam:
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Regulator Location:
Regulator Type:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Liquid Prop Notes:
Inventory Address: 2112 GRANGE DR, MISSISSAUGA - LEAK
Invent Postal Code:
Notes:
Contact Natural Env:
Aff Prop Use Water:
Occurence Narrative: No equipment on site. Cleanup is complete
Operation Type Involved: Private Dwelling

---

14 | ***2 of 2*** | ***NW/133.5*** | ***100.8 / 3.69*** | ***2112 Grange Dr. Mississauga ON*** | ***SPL***

Ref No: 1627-9KRQV4
Year:
Incident Dt: 2014/05/20
Dt MOE Arvl on Scn:
MOE Reported Dt: 2014/06/04
Dt Document Closed: 2014/07/03
Site No: NA
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 2112 Grange Dr.<UNOFFICIAL>
Site Address: 2112 Grange Dr.
Site Region:
Site Municipality: Mississauga
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Leak/Break
Incident Preceding Spill:
Incident Reason: Unknown / N/A
Incident Summary: JFM Environmental: Historic furnace oil to soil
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 13
Contaminant Name: FURNACE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Tank - Underground
SAC Action Class: TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

15 ***1 of 2*** ***N/136.7*** ***100.8 / 3.69*** ***Summerville Family Health Team*** ***GEN***
2090 Hurontario St.
Mississauga ON

Generator No.: ON4630519
Years Reported: 11,10

Alternate Locations

Generator No: ON4630519
Generator Nm: SUMMERVILLE FAMILY HEALTH TEAM
Site Addr: 2090 HURONTARIO ST.
City: MISSISSAUGA
Reported Year(s): 11,10

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 11,10

2011 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Facility: N
MHSW Facility: N

2011 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 36
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3

2010 Generator Info

NAICS Code 1: 621110
NAICS 1 Description: Offices of Physicians
Contaminated Facility: N
MHSW Facility: N

2010 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 28
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

---

15 ***2 of 2*** ***N/136.7*** ***100.8 / 3.69*** ***Harborn Dental*** ***GEN***
3-2090 Hurontario St

Mississauga ON L5B1M8

Generator No.: ON3307537
Years Reported: 25,24,23,22,21,20,19,18,17,16,15

Alternate Locations

Generator No: ON3307537
Generator Nm: HARBORN DENTAL
Site Addr: 3-2090 HURONTARIO ST
City: MISSISSAUGA
Reported Year(s): 25,24,23,22,21,20,19,18,17,16,15

2025 Generator Info

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 24,23,22,21,20,19,18,17,16,15

2025 Waste Info

Waste Code: 312
Waste Description: Pathological Wastes
Waste Char Cd: P
Waste Char Desc: Pathological

2024 Generator Info

NAICS Code: 621210
NAICS Description: Offices of Dentists
Contamin'd Fac: No
MHSW Facility: No

2024 Manifest Summary

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 10
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 2

2023 Generator Info

NAICS Code: 621210
NAICS Description: Offices of Dentists
Contamin'd Fac: No
MHSW Facility: No

2023 Manifest Summary

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 11
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 1

2022 Generator Info

NAICS Code 1: 621210
NAICS 1 Description: Offices of Dentists
Contaminated Fac: N

MHSW Facility: N

2022 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	21.0	***Waste Count:***	2.0

2021 Generator Info

NAICS Code 1:	621210
NAICS 1 Description:	Offices of Dentists
Contaminated Fac:	N
MHSW Facility:	N

2021 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	18.0	***Waste Count:***	2

2020 Generator Info

NAICS Code 1:	621210
NAICS 1 Description:	Offices of Dentists
Contaminated Fac:	N
MHSW Facility:	N

2019 Generator Info

NAICS Code 1:	621210
NAICS 1 Description:	Offices of Dentists
Contaminated Fac:	N
MHSW Facility:	N

2019 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	21.0	***Waste Count:***	2

2018 Generator Info

NAICS Code 1:	621210
NAICS 1 Description:	Offices of Dentists
Contaminated Fac:	N
MHSW Facility:	N

2018 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	13.0	***Waste Count:***	2

2017 Generator Info

NAICS Code 1:	621210
NAICS 1 Description:	Offices of Dentists

Contaminated Fac: N
MHSW Facility: N

2017 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 11.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

2016 Generator Info

NAICS Code 1: 621210
NAICS 1 Description: Offices of Dentists
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 9.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

2015 Generator Info

NAICS Code 1: 621210
NAICS 1 Description: Offices of Dentists
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 5.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 1

---

16 | ***1 of 1*** | ***SW/157.6*** | ***100.9 / 3.77*** | ***Harborn Road/Gordon Drive Mississauga ON*** | ***CA***

Certificate #: 2840-4FQM9R
Application Year: 00
Issue Date: 1/24/00
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: John & Maddalena Boyle
Client Address: 120 Harborn Road
Client City: Mississauga
Client Postal Code: L5B 1A4
Project Description: This application is for the installation of sanitary sewers on Harborn Road from Gordon Drive to approximately 116 metres east of Gordon Drive
Contaminants:
Emission Control:

---

17 | ***1 of 2*** | ***NE/161.3*** | ***100.8 / 3.69*** | ***MISSISSAUGA CITY HURONTARIO ST/HARBORN RD. MISSISSAUGA CITY ON*** | ***CA***

Certificate #: 3-0582-97-
Application Year: 97

Issue Date:	5/28/1997
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
17	2 of 2	NE/161.3	100.8 / 3.69	Hurontario St and North Service Rd, Mississauga MISSISSAUGA ON	SPL

Ref No:	1-27VXPK	**Municipality No:**	
Year:		**Nature of Damage:**	
Incident Dt:	10/16/2022 12:04:14 AM	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	10/16/2022 6:39:14 AM	**Impact to Health:**	0 No Impact
Dt Document Closed:		**Agency Involved:**	

Site No:	
MOE Response:	Desktop Response
Site County/District:	
Site Geo Ref Meth:	
Site District Office:	Halton-Peel District Office
Nearest Watercourse:	
Site Name:	
Site Address:	Hurontario St and North Service Rd, Mississauga
Site Region:	REGIONAL MUNICIPALITY OF PEEL
Site Municipality:	MISSISSAUGA
Site Lot:	
Site Conc:	
Site Geo Ref Accu:	
Site Map Datum:	
Northing:	
Easting:	
Entity Operating Name:	
Client Name:	
Client Type:	
Source Type:	
Incident Cause:	
Incident Preceding Spill:	Line Strike
Incident Reason:	
Incident Summary:	TSSA/Enbridge - 4 inch pl IP main dmg, made safe- Hurontario/N Service Rd
Environment Impact:	1 Minor Impact
Health Env Consequence:	
Nature of Impact:	
Contaminant Qty:	0 other - see notes
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	NATURAL GAS
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	Air
Activity Preceding Spill:	
Property 2nd Watershed:	Lake Ontario and Niagara Peninsula
Property Tertiary Watershed:	02HB-Credit - 16 Mile
Sector Type:	NATURAL GAS DISTRIBUTION
SAC Action Class:	
Call Report Locatn Geodata:	{"integration_ids":["PR00002453548"],"wkts":["POINT (-79.6017550000 43.5698926000)"],"creation_date":"2022-

10-16"}

Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

18 | ***1 of 1*** | ***E/166.3*** | ***98.2 / 1.03*** | ***2055 Hurontario St ON*** | ***WWIS***

Well ID:	7371907	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	11/03/2020
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Y7ON8NJX	***Contractor:***	7360
Tag:	A297843	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY (PORT CREDIT)		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7371907.pdf

Additional Detail(s) (Map)

Well Completed Date:	07/16/2020
Year Completed:	2020
Depth (m):	10.668
Latitude:	43.5682422120198
Longitude:	-79.600248732302
Point X:	-79.60024858171411
Point Y:	43.568242209364406
Path:	737\7371907.pdf

Bore Hole Information

Bore Hole ID:	1008490888	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	613035.00
Code OB Desc:		***North83:***	4824872.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	07/16/2020	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			

Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008491015
Layer: 2
Color:
General Color:
Material 1: 34
Material 1 Desc: TILL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 10.0
Formation End Depth: 20.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008491016
Layer: 3
Color:
General Color:
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 20.0
Formation End Depth: 35.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008491014
Layer: 1
Color:
General Color:
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 10.0
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491124
Layer: 1
Plug From: 0.0
Plug To: 23.0

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491095
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008490953
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008490932
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008491046
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 25.0
Casing Diameter: 2.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1008491061
Layer: 1
Slot: 0.1
Screen Top Depth: 25.0
Screen End Depth: 35.0
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1008490933
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:

Levels UOM: ft
Rate UOM: GPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1008490981
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 1.0
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1008491076
Diameter: 6.0
Depth From: 0.0
Depth To: 35.0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

19 | ***1 of 3*** | ***N/173.8*** | ***100.8 / 3.69*** | ***HURONTARIO OFFICE CENTRE INC.***
2100 HURONTARIO ST.
MISSISSAUGA CITY ON L5B 1M8 | ***CA***

Certificate #: 3-1084-99-
Application Year: 99
Issue Date: 9/16/1999
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

19 | ***2 of 3*** | ***N/173.8*** | ***100.8 / 3.69*** | ***2100 Hurontario St***
Mississauga ON L5B 1M8 | ***EHS***

Order No: 20121106002
Status: C
Report Type: Standard Report
Report Date: 07-NOV-12
Date Received: 06-NOV-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.602609
Y: 43.570058

---

19 | ***3 of 3*** | ***N/173.8*** | ***100.8 / 3.69*** | ***Mobilinx***
2100 Hurontario Street
Mississauga ON L5B 1M8 | ***GEN***

Generator No.: ON5973701
Years Reported: 22,21

Alternate Locations

Generator No: ON5973701
Generator Nm: MOBILINX
Site Addr: 2100 HURONTARIO STREET
City: MISSISSAUGA
Reported Year(s): 22,21

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 22,21

Waste Class: 146 - OTHER SPECIFIED INORGANICS
Reported Years: 22,21

2022 Generator Info

NAICS Code 1: 237110
NAICS 1 Description: Water and Sewer Line and Related Structures Construction
Contaminated Fac: N
MHSW Facility: N

2021 Generator Info

NAICS Code 1: 237110
NAICS 1 Description: Water and Sewer Line and Related Structures Construction
Contaminated Fac: N
MHSW Facility: N

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	1 of 5	E/190.6	97.1 / -0.03	Stewart Foodservice Inc Hurrontario , QEW EB on ramp Mississauga ON	GEN

Generator No.: ONS0305-1-5SRL29-1
Years Reported: 25,24

Alternate Locations

Generator No: ONS0305-1-5SRL29-1
Generator Nm: STEWART FOODSERVICE INC
Site Addr: HURRONTARIO , QEW EB ON RAMP
City: MISSISSAUGA
Reported Year(s): 25,24

2025 Generator Info

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 24

2025 Waste Info

Waste Code: 251 **Waste Char Cd:** L
Waste Description: Oil Skimmings & Sludges **Waste Char Desc:** Liquid Industrial Waste

2024 Generator Info

NAICS Code:
NAICS Description:
Contamin'd Fac: No
MHSW Facility: No

2024 Manifest Summary

Waste Code: 251 **Waste Char Code:** L
Waste Description: Oil Skimmings & Sludges **Waste Char Desc:** Liquid Industrial Waste
Qty Received (kg): 0 **Waste Count:** 1

---

20 **2 of 5** **E/190.6** **97.1 / -0.03** ***TRANSPORT TRUCK HURONTARIO ST. (JUST NORTH OF QEW) TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON*** **SPL**

Ref No: 72480 **Municipality No:** 21102
Year: **Nature of Damage:**
Incident Dt: 6/22/1992 **Discharger Report:**
Dt MOE Arvl on Scn: **Material Group:**
MOE Reported Dt: 6/22/1992 **Impact to Health:**
Dt Document Closed: **Agency Involved:** REG. OF PEEL
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: MISSISSAUGA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER CONTAINER LEAK
Incident Preceding Spill:
Incident Reason: UNKNOWN
Incident Summary: TRANSPORT TRUCK -180 L. DIESEL FUEL TO ROAD & DITCH, CONTAINED.
Environment Impact: CONFIRMED
Health Env Consequence:
Nature of Impact: Soil Contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

20 | ***3 of 5*** | ***E/190.6*** | ***97.1 / -0.03*** | ***PRIVATE OWNER QEW WESTBOUND, EAST OF HWY 10 MOTOR VEHICLE (OPERATING FLUID) MISSISSAUGA CITY ON*** | ***SPL***

Ref No: 166712
Year:
Incident Dt: 4/18/1999
Dt MOE Arvl on Scn:
MOE Reported Dt: 4/18/1999
Dt Document Closed:
Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: MISSISSAUGA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: TRUCK/TRAILER OVERTURN
Incident Preceding Spill:
Incident Reason: ERROR
Incident Summary: DYNAMIC IRON: 50L DIESEL SPILLED TO HWY.
Environment Impact: NOT ANTICIPATED
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:

Municipality No: 21102
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved: OPP,WORKS,FIRE DEPT

Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

20 | ***4 of 5*** | ***E/190.6*** | ***97.1 / -0.03*** | ***QEW & Hurontario St. Mississauga ON*** | ***SPL***

Ref No:	0618-7W4SZ2	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:		***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	9/21/2009	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	

Site No:
MOE Response:
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: at a Dufferin Construction Site <UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Equipment Failure
Incident Summary: Cusentino Trucking - 6 L of motor oil to retention pond.
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 6 L
Contaminant Qty 1: 6
Contaminant Unit: L
Contaminant Code: 46
Contaminant Name: USED MOTOR OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Watercourse Spills

Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

20 | ***5 of 5*** | ***E/190.6*** | ***97.1 / -0.03*** | ***QEW Eastbound Hunrontario Street exit ramp Mississauga ON*** | ***SPL***

Ref No: 7064-A96RRC
Year:
Incident Dt: 2016/04/19
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/04/19
Dt Document Closed: 2016/06/04
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: QEW Shoulder<UNOFFICIAL>
Site Address: QEW Eastbound Hunrontario Street exit ramp
Site Region:
Site Municipality: Mississauga
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: 4824722
Easting: 613116
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Equipment Failure
Incident Summary: QEW: Diesel to asphalt, contained and cleaning
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 100 L
Contaminant Qty 1: 100
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Highway Spills (usually highway accidents)
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

21 **1 of 1** **NNW/192.4** **100.8 / 3.69** **ON** **WWIS**

Well ID:	7260102	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:		**Data Entry Status:**	Yes
Use 2nd:		**Data Src:**	
Final Well Status:		**Date Received:**	03/30/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	C29923	**Contractor:**	6809
Tag:	A163355	**Form Version:**	8
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	
Municipality:	MISSISSAUGA CITY		
Site Info:			

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/726\7260102.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/21/2015
Year Completed:	2015
Depth (m):	
Latitude:	43.5704228824424
Longitude:	-79.6033312888104
Point X:	-79.60333113865846
Point Y:	43.5704228798493
Path:	726\7260102.pdf

Bore Hole Information

Bore Hole ID:	1005916091	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	612782.00
Code OB Desc:		**North83:**	4825110.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/21/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
22	1 of 1	S/193.1	99.8 / 2.69	VICKI BURKHOLDER 96 PREMIUM WAY MISSISSAUGA ON	CFOT

Inventory No: 46677064
Inventory Status: Active
Installation Year: NULL
Capacity: 0
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material:
Corrosion Protect:
Overfill Protection:
Inventory Context: FS Fuel Oil Tank
Inventory Item: FS FUEL OIL TANK

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	NNW/197.4	100.8 / 3.69	2114 Hurontario Street Mississauga ON L5B 1M8	EHS

Order No: 20120103022
Status: C
Report Type: Standard Report
Report Date: 1/12/2012 5:05:51 PM
Date Received: 1/3/2012 5:05:51 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality: PEEL
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.603363
Y: 43.570465

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 1	E/199.8	97.6 / 0.41	NE of QEW off Ramp at Hurontario MISSISSAUGA ON	SPL

Ref No: 1-23D8EI
Year:
Incident Dt: 8/13/2022 1:00:00 PM
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/15/2022 12:39:50 PM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: NE of QEW off Ramp at Hurontario
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: MISSISSAUGA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: Mobilinx [10L Concrete Wash] to soil; Contained; Mississauga
Environment Impact: 1 Minor Impact
Health Env Consequence:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Nature of Impact:
Contaminant Qty: 10 litre (L)
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name: UNKNOWN LIQUID
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HB-Credit - 16 Mile
Sector Type: OTHER HEAVY AND CIVIL ENGINEERING CONSTRUCTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001693213","PR00002453548"],"wkts":["POINT (-79.8232390000 43.7329549000)","POINT (-79.6016532854 43.5674852556)"],"creation_date":"2022-08-15"}
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

25 | ***1 of 2*** | ***SW/203.1*** | ***100.1 / 2.89*** | ***ENBRIDGE GAS INC***
2080 GORDON DR,,MISSISSAUGA,ON,L5B 1S5, CA
ON | ***PINC***

Incident Id:
Incident No: 2821430
Incident Reported Dt: 4/6/2020
Type: FS-Pipeline Incident
Status Code:
Tank Status: Pipeline Damage Reason Est
Task No:
Spills Action Centre:
Fuel Type:
Fuel Occurrence Tp:
Date of Occurrence:
Occurrence Start Dt:
Depth:
Customer Acct Name: ENBRIDGE GAS INC
Incident Address: 2080 GORDON DR,,MISSISSAUGA,ON,L5B 1S5,CA
Operation Type:
Pipeline Type:
Regulator Type:
Summary:
Reported By:
Affiliation:
Occurrence Desc:
Damage Reason:
Notes:

Pipe Material:
Fuel Category:
Health Impact:
Environment Impact:
Property Damage:
Service Interrupt:
Enforce Policy:
Public Relation:
Pipeline System:
PSIG:
Attribute Category:
Regulator Location:
Method Details:

---

25 | ***2 of 2*** | ***SW/203.1*** | ***100.1 / 2.89*** | ***Enbridge Energy Distribution Inc.***
2080 Gordon Dr.
Mississauga ON | ***SPL***

Ref No: 7707-BNCU3F
Year:
Municipality No:
Nature of Damage:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Dt:	2020/04/04	**Discharger Report:**	
Dt MOE Arvl on Scn:		**Material Group:**	
MOE Reported Dt:	2020/04/04	**Impact to Health:**	2 - Minor Environment
Dt Document Closed:	2020/05/16	**Agency Involved:**	
Site No:	NA		
MOE Response:	No		
Site County/District:	Regional Municipality of Peel		
Site Geo Ref Meth:			
Site District Office:	Halton-Peel		
Nearest Watercourse:			
Site Name:	Residential<UNOFFICIAL>		
Site Address:	2080 Gordon Dr.		
Site Region:	Central		
Site Municipality:	Mississauga		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Enbridge Energy Distribution Inc.		
Client Type:	Corporation		
Source Type:	Pipeline/Components		
Incident Cause:			
Incident Preceding Spill:	Leak/Break		
Incident Reason:	Operator/Human Error		
Incident Summary:	TSSA FSB: Enbridge Gas, ½" plastic IP service line damaged, made safe		
Environment Impact:			
Health Env Consequence:			
Nature of Impact:			
Contaminant Qty:	0 other - see incident description		
Contaminant Qty 1:	0		
Contaminant Unit:	other - see incident description		
Contaminant Code:	35		
Contaminant Name:	NATURAL GAS (METHANE)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:	1075		
Receiving Medium:	Air		
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Miscellaneous Communal		
SAC Action Class:	TSSA - Fuel Safety Program Notifications		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
26	1 of 1	E/206.6	98.6 / 1.43	Hurontario St/ QEW (Ramps on Hwy) Mississauga ON	EHS

Order No:	20081031030	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	11/4/2008	**Search Radius (km):**	0.25
Date Received:	10/31/2008	**X:**	-79.599787
Previous Site Name:		**Y:**	43.567993

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Lot/Building Size:
Additional Info Ordered:

---

27 **1 of 1** **E/214.3** **97.7 / 0.52** **60 S Service Rd ON** **WWIS**

Well ID:	7371899	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	11/03/2020
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	8G47X4CV	**Contractor:**	7360
Tag:	A292456	**Form Version:**	9
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: MISSISSAUGA CITY (PORT CREDIT)
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/737\7371899.pdf

Additional Detail(s) (Map)

Well Completed Date:	04/16/2020
Year Completed:	2020
Depth (m):	5.7912
Latitude:	43.5683699563618
Longitude:	-79.5996513778889
Point X:	-79.5996512282802
Point Y:	43.56836995371632
Path:	737\7371899.pdf

Bore Hole Information

Bore Hole ID:	1008490864	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	613083.00
Code OB Desc:		**North83:**	4824887.00
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	04/16/2020	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1008490995
Layer: 4
Color: 6
General Color: BROWN
Material 1: 27
Material 1 Desc: OTHER
Material 2: 08
Material 2 Desc: FINE SAND
Material 3:
Material 3 Desc:
Formation Top Depth: 4.5
Formation End Depth: 11.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490994
Layer: 3
Color: 6
General Color: BROWN
Material 1: 11
Material 1 Desc: GRAVEL
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 1.5
Formation End Depth: 4.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490996
Layer: 5
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2: 26
Material 2 Desc: ROCK
Material 3:
Material 3 Desc:
Formation Top Depth: 11.5
Formation End Depth: 19.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490992
Layer: 1
Color: 6
General Color: BROWN
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0

Formation End Depth: 0.75
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1008490993
Layer: 2
Color: 2
General Color: GREY
Material 1: 27
Material 1 Desc: OTHER
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.75
Formation End Depth: 1.5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491087
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1008491116
Layer: 1
Plug From: 3.0
Plug To: 7.0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 1008490945
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1008490916
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1008491038
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.0
Depth To: 9.0

Casing Diameter:	2.0
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1008491053
Layer:	1
Slot:	0.1
Screen Top Depth:	9.0
Screen End Depth:	19.0
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Results of Well Yield Testing

Pumping Test Method Desc:	
Pump Test ID:	1008490917
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Water Details

Water ID:	1008490979
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	19.0
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1008491068
Diameter:	6.0
Depth From:	0.0
Depth To:	19.0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	1 of 23	NNE/224.5	100.8 / 3.69	**GWL Realty Advisors Inc.** **2085 Hurontario St** **Mississauga ON L5A 4G1**	CA

Certificate #:	7256-7AYSJE
Application Year:	2008
Issue Date:	5/13/2008
Approval Type:	Air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

28 | 2 of 23 | NNE/224.5 | 100.8 / 3.69 | EASR

GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA
2085 HURONTARIO STREET
MISSISSAUGA ON L5A 4G1

Approval No: R-003-6281211592
Status: REGISTERED
Date: 2012-11-16
Record Type: EASR
Link Source: MOFA
Project Type: Heating System
Full Address:
Approval Type: EASR-Heating System
SWP Area Name: Credit Valley
PDF NAICS Code:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2591
PDF Site Location:

MOE District: Halton-Peel
Municipality: MISSISSAUGA
Latitude: 43.570526
Longitude: -79.601616
Geometry X:
Geometry Y:

---

28 | 3 of 23 | NNE/224.5 | 100.8 / 3.69 | EASR

GOVERNMENT OF THE PROVINCE OF BRITISH COLUMBIA
2085 HURONTARIO STREET
MISSISSAUGA ON L5A 4G1

Approval No: R-002-1281397037
Status: REGISTERED
Date: 2012-11-16
Record Type: EASR
Link Source: MOFA
Project Type: Standby Power System
Full Address:
Approval Type: EASR-Standby Power System
SWP Area Name: Credit Valley
PDF NAICS Code:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2592
PDF Site Location:

MOE District: Halton-Peel
Municipality: MISSISSAUGA
Latitude: 43.570526
Longitude: -79.601616
Geometry X:
Geometry Y:

---

28 | 4 of 23 | NNE/224.5 | 100.8 / 3.69 | EBR

GWL Realty Advisors Inc.
2085 Hurontario St Mississauga Ontario
Mississauga
ON

EBR Registry No: IA07E0252
Ministry Ref No: 3622-6YDRCW
Notice Type: Instrument Decision
Section:
Notice Stage:
Act 1:
Act 2:
Site Location Map:
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)

Decision Posted:
Exception Posted:
Bulletin Posted:
Appeal Posted:
Notice Date: May 16, 2008
Proposal Date: February 14, 2007
Year: 2007

Off Instrument Name:
Posted By:
Company Name: GWL Realty Advisors Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 90 Burnhamthorpe Road West , Unit 206, Mississauga Ontario, Canada L5B 3C3
Comment Period:
URL:
Summary:

Site Location Details:

2085 Hurontario St Mississauga Ontario Mississauga

---

28 | ***5 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***GWL Realty Advisors Inc.***
2085 Hurontario St
Mississauga ON | ***ECA***

Approval No:	7256-7AYSJE	***MOE District:***	Halton-Peel
Approval Date:	2008-05-13	***City:***	
Status:	Approved	***Longitude:***	-79.601616
Record Type:	ECA	***Latitude:***	43.570526
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Credit Valley	***Geometry Y:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Business Name:	GWL Realty Advisors Inc.		
Address:	2085 Hurontario St		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/3622-6YDRCW-14.pdf		
PDF Site Location:			

---

28 | ***6 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***2085 Hurontario Street***
MISSISSAUGA ON L5A 4G1 | ***EHS***

Order No:	20090504064w	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Self Serve Instant Report	***Client Prov/State:***	IL
Report Date:	5/4/2009	***Search Radius (km):***	0.25
Date Received:	5/4/2009	***X:***	0
Previous Site Name:		***Y:***	0
Lot/Building Size:			
Additional Info Ordered:			

---

28 | ***7 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***2085 Hurontario Street***
Mississauga ON L5A 4G1 | ***EHS***

Order No:	20110824019	***Nearest Intersection:***	Hurontario Street and North Service Road
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	9/1/2011	***Search Radius (km):***	0.25
Date Received:	8/24/2011 10:54:35 AM	***X:***	-79.601922
Previous Site Name:		***Y:***	43.570265
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	8 of 23	NNE/224.5	100.8 / 3.69	2085 Hurontario St Mississauga ON L5A4G1	EHS

Order No: 20170417117
Status: C
Report Type: Standard Report
Report Date: 21-APR-17
Date Received: 17-APR-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.601748
Y: 43.570529

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	9 of 23	NNE/224.5	100.8 / 3.69	2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1	EHS

Order No: 22082602172
Status: C
Report Type: Standard Express - SNAP
Report Date: 29-AUG-22
Date Received: 26-AUG-22
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.6016407
Y: 43.5704418

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	10 of 23	NNE/224.5	100.8 / 3.69	The Great West Life Assurance Company 2085 Hurontario St. Mississauga ON	GEN

Generator No.: ON8446233
Years Reported: 09,08,07,06,05,04

Alternate Locations

Generator No: ON8446233
Generator Nm: THE GREAT WEST LIFE ASSURANCE COMPANY
Site Addr: 2085 HURONTARIO ST.
City: MISSISSAUGA
Reported Year(s): 09,08,07,06,05,04

Waste Reported

Waste Class: 252 - WASTE OILS & LUBRICANTS
Reported Years: 09,08,07,06,05

Waste Class: 212 - ALIPHATIC SOLVENTS
Reported Years: 09,08,07,06,05

Waste Class: 145 - PAINT/PIGMENT/COATING RESIDUES
Reported Years: 09,08,07,06,05

2009 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility: N
MHSW Facility: N

2008 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility: N
MHSW Facility: N

2007 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility:
MHSW Facility:

2006 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility:
MHSW Facility:

2005 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility:
MHSW Facility:

2004 Generator Info

NAICS Code 1: 551114
NAICS 1 Description: Head Offices
Contaminated Facility:
MHSW Facility:

---

28 | ***11 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***Starneon Ltd partnership***
2085 Hurontario St.
Mississauga ON L5A4G1 | ***GEN***

Generator No.: ON8164955
Years Reported: 21,20

Alternate Locations

Generator No: ON8164955
Generator Nm: STARNEON LTD PARTNERSHIP
Site Addr: 2085 HURONTARIO ST.
City: MISSISSAUGA
Reported Year(s): 21,20

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 21,20

2021 Generator Info

NAICS Code 1: 531310
NAICS 1 Description: Real Estate Property Managers
Contaminated Fac: N
MHSW Facility: N

2020 Generator Info

NAICS Code 1:	531310
NAICS 1 Description:	Real Estate Property Managers
Contaminated Fac:	N
MHSW Facility:	N

2020 Manifest Summary

Waste Code:	221	***Waste Char Code:***	L
Waste Description:	LIGHT FUELS	***Waste Char Desc:***	LIQUID INDUSTRIAL WASTE
Quantity (kg):	1100.0	***Waste Count:***	1

---

28 ***12 of 23*** ***NNE/224.5*** ***100.8 / 3.69*** ***Trillium Health Partners***
2085 Hurontario Street
Missisauga ON L5A4G1 ***GEN***

Generator No.:	ON4047570
Years Reported:	25,24,23,22,21,20,19,18,17,16,15,14,13,12,11,10

Alternate Locations

Generator No:	ON4047570
Generator Nm:	TRILLIUM HEALTH PARTNERS
Site Addr:	2085 HURONTARIO STREET
City:	MISSISAUGA
Reported Year(s):	25,24,23,22,21,20,19,18,17,16,15,14,13,12

Generator No:	ON4047570
Generator Nm:	TRILLIUM HEALTH CENTRE
Site Addr:	2085 HURONTARIO STREET
City:	MISSISAUGA
Reported Year(s):	11,10

2025 Generator Info

Waste Reported

Waste Class:	312 - PATHOLOGICAL WASTES
Reported Years:	24,23,22,21,20,19,18,17,16,15,14,13,12,11,10

2025 Waste Info

Waste Code:	312	***Waste Char Cd:***	P
Waste Description:	Pathological Wastes	***Waste Char Desc:***	Pathological

2024 Generator Info

NAICS Code:	621499
NAICS Description:	All Other Out-Patient Care Centres
Contamin'd Fac:	No
MHSW Facility:	No

2024 Manifest Summary

Waste Code:	312	***Waste Char Code:***	P

Waste Description:	Pathological Wastes	**Waste Char Desc:**	Pathological
Qty Received (kg):	174.59	**Waste Count:**	5

2023 Generator Info

NAICS Code:	621499
NAICS Description:	All Other Out-Patient Care Centres
Contamin'd Fac:	No
MHSW Facility:	No

2023 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	Pathological Wastes	**Waste Char Desc:**	Pathological
Qty Received (kg):	134	**Waste Count:**	6

2022 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2022 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	158.41	**Waste Count:**	3.0

2021 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2021 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	125.27	**Waste Count:**	6

2020 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2020 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	106.88	**Waste Count:**	4

2019 Generator Info

NAICS Code 1:	621499

NAICS 1 Description: All Other Out-Patient Care Centres
Contaminated Fac: N
MHSW Facility: N

2019 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 160.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 6

2018 Generator Info

NAICS Code 1: 621499
NAICS 1 Description: All Other Out-Patient Care Centres
Contaminated Fac: N
MHSW Facility: N

2018 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 71.59
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 3

2017 Generator Info

NAICS Code 1: 621499
NAICS 1 Description: All Other Out-Patient Care Centres
Contaminated Fac: N
MHSW Facility: N

2017 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 88.67
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4

2016 Generator Info

NAICS Code 1: 621499
NAICS 1 Description: All Other Out-Patient Care Centres
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 55.08
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 5

2015 Generator Info

NAICS Code 1: 621499
NAICS 1 Description: All Other Out-Patient Care Centres
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	71.45	**Waste Count:**	5

2014 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2014 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	75.88	**Waste Count:**	6

2013 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2013 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	71	**Waste Count:**	7

2012 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Fac:	N
MHSW Facility:	N

2012 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	64.31	**Waste Count:**	9

2011 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Facility:	N
MHSW Facility:	N

2011 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	27	**Waste Count:**	3

2010 Generator Info

NAICS Code 1:	621499
NAICS 1 Description:	All Other Out-Patient Care Centres
Contaminated Facility:	N
MHSW Facility:	N

2010 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	38	**Waste Count:**	2

---

28 | ***13 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***GWL REALTY ADVISORS***
2085 HURONTARIO Street
MISSISSAUGA ON L5A4G1 | ***NPRI***

NPRI ID:	8800000322	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	WAYNE
Report Year:	2004	**Cont Last Name:**	PROULX
Not-Current Rpt?:		**Contact Position:**	MANAGER ENERGY AND ENVIRONMENTAL SERVICES
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	SOUTHGATE EXECUTIVE CENTRE - 2085 HURONTARIO	**Cont Area Code:**	905
Fac Address1:		**Contact Tel.:**	3618193
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	905
Facility Lat:		**Contact Fax:**	3618188
Facility Long:		**Contact Email:**	wayne.proulx@gwlra.com
DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	10	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			
American SIC Code:			
NAICS Code (2 digit):	53		
NAICS 2 Description:	Real Estate and Rental and Leasing		
NAICS Code (4 digit):	5311		
NAICS 4 Description:	Lessors of Real Estate		
NAICS Code (6 digit):	531120		
NAICS 6 Description:	Lessors of Non-Residential Buildings (except Mini-Warehouses)		

Substance Release Report

CAS No:	11104-93-1
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	

Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2004
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M08
Report ID:
Rpt Period: 2004
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 10024-97-2
Report ID:
Rpt Period: 2004
Subst Released: Nitrous oxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 124-38-9

Report ID:
Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:
Total Releases:
Units: tonnes

---

28 | **14 of 23** | **NNE/224.5** | **100.8 / 3.69** | **J T GILMOUR INC.**
2085 HURONTARIO ST SUITE 300
MISSISSAUGA ON L5A 4G1 | **SCT**

Scott S ID: 19558727
Latitude:
Longitude:

Historical Details

Established: 1894
Plant Size (ft²): 0
Employment: 1

Historical Details

Description: Book, Periodical and Newspaper Wholesaler-Distributors
SIC/NAICS Code: 414420

Historical Details

Description: All Other Wholesaler-Distributors
SIC/NAICS Code: 418990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	15 of 23	NNE/224.5	100.8 / 3.69	REPRODUX LIMITED 2085 HURONTARIO ST SUITE 101 MISSISSAUGA ON L5A 4G1	SCT

Scott S ID: 19749376
Latitude:
Longitude:

Historical Details

Established: 1963
Plant Size (ft²): 1400
Employment: 4

Historical Details

Description: Quick Printing
SIC/NAICS Code: 323114

Historical Details

Description: Digital Printing
SIC/NAICS Code: 323115

Historical Details

Description: Other Printing
SIC/NAICS Code: 323119

Historical Details

Description: Business Service Centres
SIC/NAICS Code: 561430

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
28	16 of 23	NNE/224.5	100.8 / 3.69	STEPHAN MACHINERY (CANADA) LTD 2085 HURONTARIO ST SUITE 300 MISSISSAUGA ON L5A 4G1	SCT

Scott S ID: 18855075
Latitude:
Longitude:

Historical Details

Established: 1908
Plant Size (ft²): 0
Employment: 1

Historical Details

Description: FOOD PRODUCTS MACHINERY
SIC/NAICS Code: 3556

Historical Details

Description: INDUSTRIAL AND COMMERCIAL MACHINERY AND EQUIPMENT, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3599

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Historical Details

Description: SURGICAL AND MEDICAL INSTRUMENTS AND APPARATUS
SIC/NAICS Code: 3841

---

28 ***17 of 23*** ***NNE/224.5*** ***100.8 / 3.69*** ***Cincom Systems of Canada Ltd***
2085 Hurontario St Suite 200
Mississauga ON L5A 4G1 ***SCT***

Scott S ID: 18483412
Latitude:
Longitude:

Historical Details

Established: 01-JUN-67
Plant Size (ft²):
Employment:

Historical Details

Description: Software Publishers
SIC/NAICS Code: 511210

---

28 ***18 of 23*** ***NNE/224.5*** ***100.8 / 3.69*** ***ONIX SYSTEMS GROUP INC.***
2085 Hurontario St Suite 300
Mississauga ON L5A 4G1 ***SCT***

Scott S ID: 19735721
Latitude:
Longitude:

Historical Details

Established: 1991
Plant Size (ft²): 0
Employment: 3

Historical Details

Description: Computer Systems Design and Related Services
SIC/NAICS Code: 541510

Historical Details

Description: Software Publishers
SIC/NAICS Code: 511210

---

28 ***19 of 23*** ***NNE/224.5*** ***100.8 / 3.69*** ***Reprodux Copy Centres Ltd.***
2085 Hurontario St Suite 101
Mississauga ON L5A 4G1 ***SCT***

Scott S ID: 19749376
Latitude:
Longitude:

Historical Details

Established: 01-JUL-63
Plant Size (ft²): 1400
Employment:

Historical Details

Description: Stationery and Office Supplies Wholesaler-Distributors
SIC/NAICS Code: 418210

Historical Details

Description: Quick Printing
SIC/NAICS Code: 323114

Historical Details

Description: Other Printing
SIC/NAICS Code: 323119

Historical Details

Description: Digital Printing
SIC/NAICS Code: 323115

Historical Details

Description: Business Service Centres
SIC/NAICS Code: 561430

Historical Details

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

---

28 | ***20 of 23*** | ***NNE/224.5*** | ***100.8 / 3.69*** | ***Stephan Machinery (Canada) Limited***
2085 Hurontario St Suite 300
Mississauga ON L5A 4G1 | ***SCT***

Scott S ID: 18855075
Latitude:
Longitude:

Historical Details

Established: 1908
Plant Size (ft²): 175
Employment: 1

Historical Details

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Historical Details

Description: Service Establishment Machinery, Equipment and Supplies Wholesaler-Distributors

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
SIC/NAICS Code:		417920			

28 **21 of 23** **NNE/224.5** **100.8 / 3.69** **Autobranch Technologies** **SCT**
2085 Hurontario St Suite 300
Mississauga ON L5A 4G1

Scott S ID: 20123121
Latitude:
Longitude:

Historical Details

Established: 1999
Plant Size (ft²):
Employment: 20

Historical Details

Description: Software Publishers
SIC/NAICS Code: 511210

28 **22 of 23** **NNE/224.5** **100.8 / 3.69** **Owen Media Partners Inc.** **SCT**
2085 Hurontario St Suite 208
Mississauga ON L5A 4G1

Scott S ID: 30155073
Latitude:
Longitude:

Historical Details

Established: 01-AUG-97
Plant Size (ft²):
Employment:

Historical Details

Description: Directory and Mailing List Publishers
SIC/NAICS Code: 511140

28 **23 of 23** **NNE/224.5** **100.8 / 3.69** **OCWA Corporate Head office** **SCT**
2085 Hurontario St
Mississauga ON L5A2E6

Scott S ID: 304127752
Latitude: 43.5703
Longitude: -79.6017

Details

Bus Type 1:	Manufacturer	**Employee Count:**	750
Bus Type 2:	Utilities	**Square Footage:**	0
Bus Type 3:		**Estimated Sales:**	Over $100 Million
Product Cat 1:	Water treatment plant	**Export Indicator:**	
Product Cat 2:		**Export Country 1:**	
Product Cat 3:		**Export Country 2:**	
Product Cat 4:		**Export Country 3:**	
Product Cat 5:		**Export Country 4:**	
Product Cat 6:		**Export Country 5:**	

Product Cat 7:		***Export Country 6:***	
Product Cat 8:		***Geocoded by:***	Address
Company Name:	OCWA Corporate Head office		
Address Line 1:	2085 Hurontario St		
Address Line 2:			
City:	Mississauga		
Province:	ON		
Postal Code:	L5A2E6		
Census Division:	Peel Regional Municipality; ON		
Metro Area:	Toronto		
Year Established:	1993		
Head Office Indicator:			
Parent Company Nm:			
Parent Cmpny Addr 1:			
Parent Cmpny Addr 2:			
Parent Cmpny City:			
Parent Cmpny Prov:			
Parent Cmpy PC:			
Parent Cmpy Cntry:			
Head Office Nm:			
H Office Addr Line 1:			
H Office Addr Line 2:			
Head Office City:			
Head Office Province:			
Head Office PC:			
Head Office Cntry:			
Telephone:	800-667-6292		
Fax:			
Website:	https://www.ocwa.com/		
Pri NAICS Desc:	221310-Water Supply and Irrigation Systems		
NAICS Code 1:	221310-Water Supply and Irrigation Systems		
NAICS Code 2:	333310-Commercial and Service Industry Machinery M		
NAICS Code 3:			
NAICS Code 4:			
NAICS Code 5:			

29 ***1 of 1*** ***NNE/224.8*** ***100.8 / 3.69*** ***2085 Hurontario Street Mississauga ON Mississauga ON L5A 4G1*** ***EHS***

Order No:	22070500249	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	08-JUL-22	***Search Radius (km):***	.25
Date Received:	05-JUL-22	***X:***	-79.6015146
Previous Site Name:		***Y:***	43.5703874
Lot/Building Size:			
Additional Info Ordered:			

30 ***1 of 1*** ***NNE/230.0*** ***100.8 / 3.69*** ***ON*** ***BORE***

Borehole ID:	654424	***Inclin FLG:***	No
OGF ID:	215554769	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	OCT-1962	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.570518
Total Depth m:	4.9	***Longitude DD:***	-79.601687
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	612915

Drill Method:	Boring	**Northing:**	4825123
Orig Ground Elev m:	101	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	102		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218543320	**Mat Consistency:**	Dense
Top Depth:	2.6	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL,SAND. GREY,VERY DENSE. 00000041000220610008509O, SA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218543319	**Mat Consistency:**	Dense
Top Depth:	.7	**Material Moisture:**	
Bottom Depth:	2.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL,SAND. BROWN,VERY DENSE.		

Geology Stratum ID:	218543318	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	CLAY,SILT. BROWN.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 250890 NTS_Sheet: 30M12A		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Originators: Geological Survey of Canada

---

31 | **1 of 1** | **WNW/231.8** | **96.1 / -1.02** | **Berkley Homes (Gordon Woods II) Inc.**
Grange Dr
Mississauga ON L4K 3N3 | **ECA**

Approval No:	5403-7JTR2T	**MOE District:**	Halton-Peel
Approval Date:	2008-09-25	**City:**	
Status:	Approved	**Longitude:**	-79.6059
Record Type:	ECA	**Latitude:**	43.5693
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Berkley Homes (Gordon Woods II) Inc.
Address: Grange Dr
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/0695-7JML2H-14.pdf
PDF Site Location:

---

32 | **1 of 1** | **NW/232.2** | **101.8 / 4.69** | **2143 Grange Drive**
Mississauga ON | **EHS**

Order No:	20150402059	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	10-APR-15	**Search Radius (km):**	.25
Date Received:	02-APR-15	**X:**	-79.604947
Previous Site Name:		**Y:**	43.570276
Lot/Building Size:			
Additional Info Ordered:			

---

33 | **1 of 1** | **N/233.4** | **100.8 / 3.69** | **HURONTARIO ST**
Mississauga ON | **WWIS**

Well ID:	7277550	**Flowing (Y/N):**	
Construction Date:		**Flow Rate:**	
Use 1st:	Monitoring	**Data Entry Status:**	
Use 2nd:		**Data Src:**	
Final Well Status:	Observation Wells	**Date Received:**	12/23/2016
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:	Z240276	**Contractor:**	6607
Tag:	A209776	**Form Version:**	7
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	
Depth to Bedrock:		**Concession:**	
Well Depth:		**Concession Name:**	
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: MISSISSAUGA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/727\7277550.pdf

Additional Detail(s) (Map)

Well Completed Date: 10/24/2016

Year Completed: 2016
Depth (m): 5.2
Latitude: 43.570783925126
Longitude: -79.6026666060828
Point X: -79.60266645649486
Point Y: 43.57078392250439
Path: 727\7277550.pdf

Bore Hole Information

Bore Hole ID: 1006318477
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/24/2016
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612835.00
North83: 4825151.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006512740
Layer: 3
Color: 2
General Color: GREY
Material 1: 28
Material 1 Desc: SAND
Material 2:
Material 2 Desc:
Material 3: 77
Material 3 Desc: LOOSE
Formation Top Depth: 3.700000047683716
Formation End Depth: 5.199999809265137
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1006512738
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 11
Material 2 Desc: GRAVEL
Material 3: 79
Material 3 Desc: PACKED
Formation Top Depth: 0.0
Formation End Depth: 0.8999999761581421
Formation End Depth UOM: m

Overburden and Bedrock

Materials Interval

Formation ID:	1006512739
Layer:	2
Color:	6
General Color:	BROWN
Material 1:	28
Material 1 Desc:	SAND
Material 2:	
Material 2 Desc:	
Material 3:	77
Material 3 Desc:	LOOSE
Formation Top Depth:	0.8999999761581421
Formation End Depth:	3.700000047683716
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006512747
Layer:	1
Plug From:	0.0
Plug To:	0.30000001192092896
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006512748
Layer:	2
Plug From:	0.30000001192092896
Plug To:	3.0999999046325684
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	1006512746
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006512737
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006512743
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.30000001192092896
Depth To:	3.700000047683716
Casing Diameter:	5.099999904632568
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Screen

Screen ID:	1006512744
Layer:	1
Slot:	10
Screen Top Depth:	3.700000047683716
Screen End Depth:	5.199999809265137
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.400000095367432

Water Details

Water ID:	1006512742
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	3.700000047683716
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006512741
Diameter:	18.0
Depth From:	0.0
Depth To:	5.199999809265137
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

34 | ***1 of 1*** | ***NNE/240.5*** | ***100.8 / 3.69*** | ***2085 Hurontario Street, Mississauga, ON Mississauga ON L5A 4G1*** | ***EHS***

Order No:	22090100302	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Report	***Client Prov/State:***	ON
Report Date:	07-SEP-22	***Search Radius (km):***	.25
Date Received:	01-SEP-22	***X:***	-79.6015816
Previous Site Name:		***Y:***	43.5705833
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

---

35 | ***1 of 1*** | ***NNW/244.9*** | ***100.8 / 3.69*** | ***Forntinf West Side of Hurontario 2130 Hurontario Street Mississauga ON*** | ***EHS***

Order No:	20080411025	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Complete Report	***Client Prov/State:***	ON
Report Date:	4/17/2008	***Search Radius (km):***	0.25
Date Received:	4/11/2008	***X:***	-79.603537
Previous Site Name:		***Y:***	43.570995
Lot/Building Size:			
Additional Info Ordered:			

---

36 | ***1 of 1*** | ***S/246.2*** | ***99.8 / 2.69*** | ***lot 2 con 3 ON*** | ***WWIS***

Well ID:	4902195	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	

Use 1st:	Domestic	**Data Entry Status:**	
Use 2nd:	0	**Data Src:**	1
Final Well Status:	Water Supply	**Date Received:**	01/27/1959
Water Type:		**Selected Flag:**	TRUE
Casing Material:		**Abandonment Rec:**	
Audit No:		**Contractor:**	2613
Tag:		**Form Version:**	1
Constructn Method:		**Owner:**	
Elevation (m):		**County:**	PEEL
Elevatn Reliabilty:		**Lot:**	002
Depth to Bedrock:		**Concession:**	03
Well Depth:		**Concession Name:**	CIR R
Overburden/Bedrock:		**Easting NAD83:**	
Pump Rate:		**Northing NAD83:**	
Static Water Level:		**Zone:**	
Clear/Cloudy:		**UTM Reliability:**	

Municipality: MISSISSAUGA CITY
Site Info:

PDF URL (Map): https://d2khazk8e83rdv.cloudfront.net/moe_mapping/downloads/2Water/Wells_pdfs/490\4902195.pdf

Additional Detail(s) (Map)

Well Completed Date: 11/06/1958
Year Completed: 1958
Depth (m): 15.24
Latitude: 43.5658814912032
Longitude: -79.6030573267036
Point X: -79.60305717723872
Point Y: 43.56588148833298
Path: 490\4902195.pdf

Bore Hole Information

Bore Hole ID:	10317038	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	612812.60
Code OB Desc:		**North83:**	4824606.00
Open Hole:		**Org CS:**	
Cluster Kind:		**UTMRC:**	9
Date Completed:	11/06/1958	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	p9

Location Method Desc: Original Pre1985 UTM Rel Code 9: unknown UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 932037051
Layer: 2
Color: 3
General Color: BLUE
Material 1: 17
Material 1 Desc: SHALE
Material 2:
Material 2 Desc:
Material 3:

Material 3 Desc:
Formation Top Depth: 13.0
Formation End Depth: 50.0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 932037050
Layer: 1
Color: 6
General Color: BROWN
Material 1: 09
Material 1 Desc: MEDIUM SAND
Material 2:
Material 2 Desc:
Material 3:
Material 3 Desc:
Formation Top Depth: 0.0
Formation End Depth: 13.0
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID: 964902195
Method Construction Code: 1
Method Construction: Cable Tool
Other Method Construction:

Pipe Information

Pipe ID: 10865608
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930523984
Layer: 1
Material: 1
Open Hole or Material: STEEL
Depth From:
Depth To: 19.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 930523985
Layer: 2
Material: 4
Open Hole or Material: OPEN HOLE
Depth From:
Depth To: 50.0
Casing Diameter: 5.0
Casing Diameter UOM: inch
Casing Depth UOM: ft

Results of Well Yield Testing

Pumping Test Method Desc:	PUMP
Pump Test ID:	994902195
Pump Set At:	
Static Level:	15.0
Final Level After Pumping:	15.0
Recommended Pump Depth:	15.0
Pumping Rate:	3.0
Flowing Rate:	
Recommended Pump Rate:	3.0
Levels UOM:	ft
Rate UOM:	GPM
Water State After Test Code:	1
Water State After Test:	CLEAR
Pumping Test Method:	1
Pumping Duration HR:	3
Pumping Duration MIN:	0
Flowing:	No

Water Details

Water ID:	933790193
Layer:	1
Kind Code:	1
Kind:	FRESH
Water Found Depth:	30.0
Water Found Depth UOM:	ft

---

37 | ***1 of 1*** | ***NE/260.5*** | ***99.8 / 2.69*** | ***ELF ATOCHEM CANADA INC.***
QEW EAST/WESTBOUND - 2055 HURONTARIO
ST. TRANSPORT TRUCK (CARGO)
MISSISSAUGA CITY ON L5A 2E6 | ***SPL***

Ref No:	92116	***Municipality No:***	21102
Year:		***Nature of Damage:***	
Incident Dt:	10/7/1993	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	10/7/1993	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	REGION OF PEEL
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:			
Site Address:			
Site Region:			
Site Municipality:	MISSISSAUGA CITY		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:			
Client Type:			
Source Type:			
Incident Cause:	OTHER CONTAINER LEAK		
Incident Preceding Spill:			
Incident Reason:	UNKNOWN		
Incident Summary:	ELF ATOCHEM: 800L WASHINGLIQUID LEAK TO HWY AND PARKING LOT		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Environment Impact:	CONFIRMED
Health Env Consequence:	
Nature of Impact:	Soil contamination
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	
Contaminant Code:	
Contaminant Name:	
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	LAND
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	
SAC Action Class:	
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

---

38 *1 of 2* *NNW/264.0* *100.8 / 3.69* ***PLM Holdings Inc.***
2150 Hurontario Street
Mississauga ON L5B 1M8 ***CA***

Certificate #:	9288-693SFN
Application Year:	2005
Issue Date:	2/1/2005
Approval Type:	Municipal and Private Sewage Works
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

---

38 *2 of 2* *NNW/264.0* *100.8 / 3.69* ***PLM Holdings Inc.***
2150 Hurontario Street
Mississauga ON M8Z 1N6 ***ECA***

Approval No:	9288-693SFN	**MOE District:**	Halton-Peel
Approval Date:	2005-02-01	**City:**	
Status:	Approved	**Longitude:**	-79.60408
Record Type:	ECA	**Latitude:**	43.57104
Link Source:	IDS	**Geometry X:**	
SWP Area Name:	Credit Valley	**Geometry Y:**	

Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name:	PLM Holdings Inc.
Address:	2150 Hurontario Street
Full Address:	
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2415-692VC7-14.pdf
PDF Site Location:	

39 **1 of 1** **ENE/286.7** **99.8 / 2.69** **ON** **BORE**

Borehole ID:	654425	**Inclin FLG:**	No
OGF ID:	215554770	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1968	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.569551
Total Depth m:	4.7	**Longitude DD:**	-79.599183
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	613119
Drill Method:	Power auger	**Northing:**	4825019
Orig Ground Elev m:	100	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	101		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218543323	**Mat Consistency:**	Hard
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,HARD.		

Geology Stratum ID:	218543324	**Mat Consistency:**	Soft
Top Depth:	4	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SHALE. GREY,SOFT. 00007043000600800013009O **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218543321	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL.		

Geology Stratum ID:	218543322	**Mat Consistency:**	Dense
Top Depth:	.2	**Material Moisture:**	

Bottom Depth:	1.8	**Material Texture:**	Fine to Medium
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SAND-FINE TO MEDIUM. BROWN,DENSE.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 250900 NTS_Sheet: 30M12A		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

40 | ***1 of 1*** | ***NNW/292.6*** | ***100.8 / 3.69*** | ***2156 Hurontario Street Mississauga ON L5B 1M8*** | ***EHS***

Order No:	20150511253	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	19-MAY-15	**Search Radius (km):**	.25
Date Received:	11-MAY-15	**X:**	-79.604326
Previous Site Name:		**Y:**	43.571169
Lot/Building Size:			
Additional Info Ordered:			

---

41 | ***1 of 3*** | ***WNW/294.0*** | ***100.9 / 3.76*** | ***88 Bronte College Court Mississauga ON L5B 1M9*** | ***EHS***

Order No:	20190716183	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	23-JUL-19	**Search Radius (km):**	.25
Date Received:	16-JUL-19	**X:**	-79.605994
Previous Site Name:		**Y:**	43.57059
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; Aerial Photos		

---

41 | ***2 of 3*** | ***WNW/294.0*** | ***100.9 / 3.76*** | ***BRONTE COLLEGE OF CANADA 88 BRONTE COLLEGE COURT MISSISSAUGA ON L5B 1M9*** | ***GEN***

Generator No.:	ON4119045
Years Reported:	22,21,20,19,18,17,16,15,14,13,12,11,10

Alternate Locations

Generator No: ON4119045
Generator Nm: BRONTE COLLEGE OF CANADA
Site Addr: 88 BRONTE COLLEGE COURT
City: MISSISSAUGA
Reported Year(s): 22,21,20,19,18,17,16,15,14,13,12,11,10

Waste Reported

Waste Class: 263 - ORGANIC LABORATORY CHEMICALS
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10

Waste Class: 146 - OTHER SPECIFIED INORGANICS
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10

Waste Class: 148 - INORGANIC LABORATORY CHEMICALS
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10

2022 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2021 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2020 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2019 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2019 Manifest Summary

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS
Quantity (kg): 20.0
Waste Char Code: C
Waste Char Desc: CORROSIVE
Waste Count: 1

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS
Quantity (kg): 20.0
Waste Char Code: I
Waste Char Desc: IGNITABLE
Waste Count: 1

2018 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2018 Manifest Summary

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS
Quantity (kg): 60.0
Waste Char Code: C
Waste Char Desc: CORROSIVE
Waste Count: 2

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS
Quantity (kg): 50.0
Waste Char Code: I
Waste Char Desc: IGNITABLE
Waste Count: 1

2017 Generator Info

NAICS Code 1: 611110
NAICS 1 Description: Elementary and Secondary Schools
Contaminated Fac: N
MHSW Facility: N

2016 Generator Info

NAICS Code 1: 611210
NAICS 1 Description: Community Colleges and C.E.G.E.P.s
Contaminated Fac: N
MHSW Facility: N

2015 Generator Info

NAICS Code 1: 611210
NAICS 1 Description: Community Colleges and C.E.G.E.P.s
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code: 148
Waste Description: INORGANIC LABORATORY CHEMICALS
Quantity (kg): 40.0
Waste Char Code: C
Waste Char Desc: CORROSIVE
Waste Count: 1

Waste Code: 263
Waste Description: ORGANIC LABORATORY CHEMICALS
Quantity (kg): 50.0
Waste Char Code: I
Waste Char Desc: IGNITABLE
Waste Count: 1

2014 Generator Info

NAICS Code 1: 611210
NAICS 1 Description: Community Colleges and C.E.G.E.P.s
Contaminated Fac: N
MHSW Facility: N

2013 Generator Info

NAICS Code 1: 611210
NAICS 1 Description: Community Colleges and C.E.G.E.P.s
Contaminated Fac: N
MHSW Facility: N

2013 Manifest Summary

Waste Code:	148	***Waste Char Code:***	C
Waste Description:	INORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	10	***Waste Count:***	1
Waste Code:	263	***Waste Char Code:***	I
Waste Description:	ORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	4	***Waste Count:***	1

2012 Generator Info

NAICS Code 1:	611210
NAICS 1 Description:	Community Colleges and C.E.G.E.P.s
Contaminated Fac:	N
MHSW Facility:	N

2011 Generator Info

NAICS Code 1:	611210
NAICS 1 Description:	Community Colleges and C.E.G.E.P.s
Contaminated Facility:	N
MHSW Facility:	N

2010 Generator Info

NAICS Code 1:	611210
NAICS 1 Description:	Community Colleges and C.E.G.E.P.s
Contaminated Facility:	N
MHSW Facility:	N

2010 Manifest Summary

Waste Code:	148	***Waste Char Code:***	B
Waste Description:	INORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	HAZARDOUS WASTE CHEMICAL
Quantity (kg):	1	***Waste Count:***	1
Waste Code:	146	***Waste Char Code:***	T
Waste Description:	OTHER SPECIFIED INORGANICS	***Waste Char Desc:***	LEACHATE TOXIC
Quantity (kg):	5	***Waste Count:***	1
Waste Code:	148	***Waste Char Code:***	C
Waste Description:	INORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	CORROSIVE
Quantity (kg):	1	***Waste Count:***	1
Waste Code:	263	***Waste Char Code:***	I
Waste Description:	ORGANIC LABORATORY CHEMICALS	***Waste Char Desc:***	IGNITABLE
Quantity (kg):	1	***Waste Count:***	1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	*3 of 3*	*WNW/294.0*	*100.9 / 3.76*	***Kenaidan Contracting Ltd*** ***88 Bronte College Court*** ***Mississauga ON L5B 1M9***	*GEN*

Generator No.:	ON001066937
Years Reported:	25

Alternate Locations

Generator No:	ON001066937
Generator Nm:	KENAIDAN CONTRACTING LTD

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Addr: 88 BRONTE COLLEGE COURT
City: MISSISSAUGA
Reported Year(s): 25

2025 Generator Info

2025 Waste Info

Waste Code: 251
Waste Description: Oil Skimmings & Sludges
Waste Char Cd: L
Waste Char Desc: Liquid Industrial Waste

Waste Code: 252
Waste Description: Waste Oils & Lubricants
Waste Char Cd: L
Waste Char Desc: Liquid Industrial Waste

---

42 | **1 of 1** | **SW/297.4** | **99.8 / 2.69** | **155 Harborn Road MISSISSAUGA ON** | **SPL**

Ref No: 1-24EIWS
Year:
Incident Dt: 8/26/2022 9:11:00 AM
Dt MOE Arvl on Scn:
MOE Reported Dt: 8/26/2022 10:32:11 AM
Dt Document Closed:
Site No:
MOE Response: Desktop Response
Site County/District:
Site Geo Ref Meth:
Site District Office: Halton-Peel District Office
Nearest Watercourse:
Site Name:
Site Address: 155 Harborn Road
Site Region: REGIONAL MUNICIPALITY OF PEEL
Site Municipality: MISSISSAUGA
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill:
Incident Reason:
Incident Summary: TSSA/Natural Gas Leak
Environment Impact: 0 No Impact
Health Env Consequence:
Nature of Impact:
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Activity Preceding Spill:
Property 2nd Watershed: Lake Ontario and Niagara Peninsula
Property Tertiary Watershed: 02HB-Credit - 16 Mile
Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 0 No Impact
Agency Involved:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Sector Type: NATURAL GAS DISTRIBUTION
SAC Action Class:
Call Report Locatn Geodata: {"integration_ids":["PR00001832902"],"wkts":["POINT (-79.6054201000 43.5662498000)"],"creation_date":"2022-08-26"}
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

43 | ***1 of 2*** | ***W/297.4*** | ***99.8 / 2.64*** | ***Fernanda Leal***
2122 Gordon Drive
Mississauga ON L5B 1S7 | ***CA***

Certificate #: 2724-5QDJMA
Application Year: 2003
Issue Date: 8/25/2003
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

43 | ***2 of 2*** | ***W/297.4*** | ***99.8 / 2.64*** | ***Fernanda Leal***
2122 Gordon Drive
Mississauga ON L4Y 3R7 | ***ECA***

Approval No: 2724-5QDJMA
Approval Date: 2003-08-25
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
MOE District: Halton-Peel
City:
Longitude: -79.60715
Latitude: 43.56708
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: Fernanda Leal
Address: 2122 Gordon Drive
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8857-5Q6N3Z-14.pdf
PDF Site Location:

---

44 | ***1 of 7*** | ***E/297.6*** | ***99.8 / 2.69*** | ***SNC LAVALIN PROFAC INC.***
49 South Service Road
Mississauga ON | ***GEN***

Generator No.: ON6197573
Years Reported: 09

Alternate Locations

Generator No: ON6197573
Generator Nm: SNC LAVALIN PROFAC INC.

Site Addr: 49 SOUTH SERVICE ROAD
City: MISSISSAUGA
Reported Year(s): 09

Waste Reported

Waste Class: 221 - LIGHT FUELS
Reported Years: 09

2009 Generator Info

NAICS Code 1: 922120
NAICS 1 Description:
Contaminated Facility: N
MHSW Facility: N

2009 Manifest Summary

Waste Code: 221
Waste Description: LIGHT FUELS
Quantity (kg): 527
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	2 of 7	E/297.6	99.8 / 2.69	**Civil Underground and excavation company** **49 south service rd** **mississauga ON**	GEN

Generator No.: ON5756807
Years Reported: 10

Alternate Locations

Generator No: ON5756807
Generator Nm: CIVIL UNDERGROUND AND EXCAVATION COMPANY
Site Addr: 49 SOUTH SERVICE RD
City: MISSISSAUGA
Reported Year(s): 10

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 10

2010 Generator Info

NAICS Code 1: 238190
NAICS 1 Description: Other Foundation Structure and Building Exterior Contractors
Contaminated Facility: N
MHSW Facility: N

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	3 of 7	E/297.6	99.8 / 2.69	**Mobilinx** **49 South Service Rd** **Mississauga ON L5G 2R8**	GEN

Generator No.: ON9628654
Years Reported: 22

Alternate Locations

Generator No: ON9628654
Generator Nm: MOBILINX
Site Addr: 49 SOUTH SERVICE RD
City: MISSISSAUGA
Reported Year(s): 22

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 22

Waste Class: 146 - OTHER SPECIFIED INORGANICS
Reported Years: 22

2022 Generator Info

NAICS Code 1: 237130
NAICS 1 Description: Power and Communication Line and Related Structures Construction
Contaminated Fac: N
MHSW Facility: N

---

44 | **4 of 7** | **E/297.6** | **99.8 / 2.69** | **SNC Lavalin-ProFac**
49 South Service Road
Mississauga ON | **GEN**

Generator No.: ON8719017
Years Reported: 09,08,07

Alternate Locations

Generator No: ON8719017
Generator Nm: SNC LAVALIN-PROFAC
Site Addr: 49 SOUTH SERVICE ROAD
City: MISSISSAUGA
Reported Year(s): 09,08,07

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 09,08,07

2009 Generator Info

NAICS Code 1: 561210
NAICS 1 Description: Facilities Support Services
Contaminated Facility: N
MHSW Facility: N

2009 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 662
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 1686
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 2

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE

Quantity (kg): 1000 **Waste Count:** 1

2008 Generator Info

NAICS Code 1: 561210
NAICS 1 Description: Facilities Support Services
Contaminated Facility: N
MHSW Facility: N

2008 Manifest Summary

Waste Code: 251 **Waste Char Code:** L
Waste Description: OIL SKIMMINGS & SLUDGES **Waste Char Desc:** LIQUID INDUSTRIAL WASTE
Quantity (kg): 1030.0 **Waste Count:** 2

2007 Generator Info

NAICS Code 1: 561210
NAICS 1 Description: Facilities Support Services
Contaminated Facility:
MHSW Facility:

2007 Manifest Summary

Waste Code: 251 **Waste Char Code:** L
Waste Description: OIL SKIMMINGS & SLUDGES **Waste Char Desc:** LIQUID INDUSTRIAL WASTE
Quantity (kg): 1030.0 **Waste Count:** 2

---

44 **5 of 7** **E/297.6** **99.8 / 2.69** ***Salini Impregilo Civil Works Inc.***
49 South Service Road Mississauga, ON L5G 2R8 Canada
ON L5G 2R8 **PTTW**

EBR Registry No: 019-4614 **Decision Posted:** June 1, 2022
Ministry Ref No: 1000146116 **Exception Posted:**
Notice Type: Instrument **Bulletin Posted:**
Section: Section 34 **Appeal Posted:**
Notice Stage: Decision **Notice Date:**
Act 1: Ontario Water Resources Act, R.S.O. 1990 **Proposal Date:** November 12, 2021
Act 2: Ontario Water Resources Act **Year:** 2021
Site Location Map: 43.568042,-79.598223
Instrument Type: Permit to take water
Off Instrument Name: Permit to Take Water (OWRA s. 34)
Posted By: Ministry of the Environment, Conservation and Parks
Company Name:
Site Address: 49 South Service Road
Mississauga,
ON
L5G 2R8
Canada
Location Other:
Proponent Name: Salini Impregilo Civil Works Inc.
Proponent Address: Salini Impregilo Civil Works Inc.
110 Matheson Boulevard
Mississauga,
ON
L5R 3R3
Canada
Comment Period: November 12, 2021 - December 12, 2021 (30 days) Closed
URL: https://ero.ontario.ca/notice/019-4614
Summary:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Site Location Details:					

44	6 of 7	E/297.6	99.8 / 2.69	EDENSHAW SSR DEVELOPMENTS LIMITED 49 South Service RD Mississauga ON	RSC

RSC No:	B-403-4271442939	X:	-79.59829211359825
RA No:		Y:	43.568245246721716
Status:	FILED	Latitude:	43.57166667
Filing Date:		Longitude:	-79.59555556
Date Ack:		UTM Coordinates:	
Date Returned:		Latitude Longitude:	
Approval Date:	May 24, 2024	Accuracy Estimate:	
Cert Date:		Measurement Method:	
Cert Prop Use No:		Mailing Address:	
Curr Property Use:		Telephone:	
Intended Prop Use:		Fax:	
Restoration Type:		Email:	
Soil Type:		Postal Code:	L5G 2R8
Criteria:		Ministry District:	
Stratified (Y/N):		MOE District:	Halton-Peel
Audit (Y/N):		SWP Area Name:	Credit Valley
Entire Leg Prop. (Y/N):		Qual Person Name:	Sarah Vlantis
CPU Issu Sect 1686:		Consultant:	
Business Name:	EDENSHAW SSR DEVELOPMENTS LIMITED		
Address:	49 South Service RD		
Legal Desc:			
Site Pin:	13504-0978 (LT)		
Asmt Roll No:			
Project Type:	RSC based on Phase One and Two ESAs		
Approval Type:	RSC-RSC based on Phase One and Two ESAs		
Applicable Standards:			
PDF Link:	https://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=3504495		

44	7 of 7	E/297.6	99.8 / 2.69	SNC Lavalin Profac<UNOFFICIAL> 49 South Service Road Mississauga ON L5G 2R8	SPL

Ref No:	7041-7N2P92	Municipality No:	
Year:		Nature of Damage:	
Incident Dt:		Discharger Report:	
Dt MOE Arvl on Scn:		Material Group:	
MOE Reported Dt:	1/6/2009	Impact to Health:	
Dt Document Closed:		Agency Involved:	
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	SNC Lavalin Profac<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Mississauga		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Name:	SNC Lavalin Profac<UNOFFICIAL>
Client Type:	
Source Type:	
Incident Cause:	Other Discharges
Incident Preceding Spill:	
Incident Reason:	Spill
Incident Summary:	SNC Lavalin Profac: Oily water to storm drain
Environment Impact:	Confirmed
Health Env Consequence:	
Nature of Impact:	Other Impact(s); Surface Water Pollution
Contaminant Qty:	
Contaminant Qty 1:	
Contaminant Unit:	other - see incident description
Contaminant Code:	
Contaminant Name:	OIL AND WATER MIXTURE
Contaminant Limit 1:	
Contam Limit Freq 1:	
Contaminant UN No 1:	
Receiving Medium:	
Activity Preceding Spill:	
Property 2nd Watershed:	
Property Tertiary Watershed:	
Sector Type:	Other
SAC Action Class:	Watercourse Spills
Call Report Locatn Geodata:	
Time Reported:	
System Facility Address:	
Source Sector Type:	
Conservtn Auth Name:	
Primary Watershed:	
Quaternary Watershed:	
Offsite Impacts:	
Waterbody Impacted:	

---

45 | ***1 of 4*** | ***NNE/297.7*** | ***100.8 / 3.69*** | ***2100 Sherobee Road Mississauga ON L5A 4C5*** | ***EHS***

Order No:	20100303008	**Nearest Intersection:**	QEW/Hurontario Street
Status:	C	**Municipality:**	Peel
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	3/11/2010	**Search Radius (km):**	0.25
Date Received:	3/3/2010	**X:**	-79.601142
Previous Site Name:		**Y:**	43.571648
Lot/Building Size:			
Additional Info Ordered:			

---

45 | ***2 of 4*** | ***NNE/297.7*** | ***100.8 / 3.69*** | ***Enersource Hydro Mississauga 2100 Sherobee Road Mississauga ON L5A4C5*** | ***GEN***

Generator No.:	ON6368899
Years Reported:	16

Alternate Locations

Generator No:	ON6368899
Generator Nm:	ENERSOURCE HYDRO MISSISSAUGA
Site Addr:	2100 SHEROBEE ROAD
City:	MISSISSAUGA
Reported Year(s):	16

Waste Reported

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 16

2016 Generator Info

NAICS Code 1: 221122
NAICS 1 Description: Electric Power Distribution
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 2200.0
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

---

45 ***3 of 4*** ***NNE/297.7*** ***100.8 / 3.69*** ***2100 Sherobe Dr Mississauga ON*** ***SPL***

Ref No: 3414-6ZBN8G
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 3/15/2007
Dt Document Closed: 3/27/2007
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: 2100 Sherobe Drive
Site Address:
Site Region:
Site Municipality: Mississauga
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing: NA
Easting: NA
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Discharge Or Bypass To A Watercourse
Incident Preceding Spill:
Incident Reason: Damage By Moving Equipment - Containers damaged by moving
Incident Summary: S. 21(1)(f): 375 lbs of R134 refrigerant to atmosphere
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Air Pollution
Contaminant Qty: 375 lb
Contaminant Qty 1: 375
Contaminant Unit: lb
Contaminant Code: 38
Contaminant Name: REFRIGERANT GAS, N.O.S.
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Air
Municipality No:
Nature of Damage:
Discharger Report:
Material Group: Gases/Particulate
Impact to Health:
Agency Involved:

Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Other
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

45 | ***4 of 4*** | ***NNE/297.7*** | ***100.8 / 3.69*** | ***Enersource Hydro Mississauga Inc.***
2100 Sherobee Rd.
Mississauga ON | ***SPL***

Ref No: 6852-A92P53
Year:
Incident Dt: 2016/04/15
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/04/15
Dt Document Closed:
Site No: NA
MOE Response: No
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: apartment building<UNOFFICIAL>
Site Address: 2100 Sherobee Rd.
Site Region:
Site Municipality: Mississauga
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum: NAD83
Northing: 4825257
Easting: 612922
Entity Operating Name:
Client Name: Enersource Hydro Mississauga Inc.
Client Type:
Source Type:
Incident Cause:
Incident Preceding Spill: Leak/Break
Incident Reason: Unknown / N/A
Incident Summary: Enersource - transformer oil to concrete pad & soil, non-PCB
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 0 L
Contaminant Qty 1: 0
Contaminant Unit: L
Contaminant Code: 15
Contaminant Name: TRANSFORMER OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: Land
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Sector Type: Unknown / N/A
SAC Action Class: Land Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

---

46 | **1 of 1** | **SSE/298.1** | **97.0 / -0.16** | **BRUCE PARSONS**
1637 GLENBURNIE ROAD
MISSISSAUGA ON | **CFOT**

Inventory No: 61118339
Inventory Status: Active
Installation Year: NULL
Capacity: 1892.7
Capacity Unit:
Tank Type:
Manufacturer:
Model:
Description:

Tank Material: Steel
Corrosion Protect:
Overfill Protection:
Inventory Context: FS Fuel Oil Tank
Inventory Item: FS FUEL OIL TANK

---

47 | **1 of 3** | **NW/298.8** | **101.2 / 4.05** | **2180 Hurontario Street**
Mississauga ON L5B 1M8 | **EHS**

Order No: 20080704031
Status: C
Report Type: Complete Report
Report Date: 7/15/2008
Date Received: 7/4/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.604896
Y: 43.571541

---

47 | **2 of 3** | **NW/298.8** | **101.2 / 4.05** | **TURNER & PORTER FUNERAL DIRECTORS**
2180 HURONTARIO STREET
MISSISSAUGA ON L5B 1M8 | **GEN**

Generator No.: ONF037100
Years Reported: 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,04,03,01,00,99,98,97,96,95,94,93,92,91,90,89,88

Alternate Locations

Generator No: ONF037100
Generator Nm: TURNER & PORTER FUNERAL DIRECTORS
Site Addr: 2180 HURONTARIO STREET
City: MISSISSAUGA
Reported Year(s): 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,04,03,01,00,99,98,97,93,92,91

Generator No: ONF037100
Generator Nm: TURNER & PORTER FUNERAL DIRECTORS
Site Addr: LIMITED
City: MISSISSAUGA
Reported Year(s): 90,89,88

Generator No: ONF037100

Generator Nm: TURNER & PORTER FUNERAL DIRECTORS 44-371
Site Addr: LIMITED
City: MISSISSAUGA
Reported Year(s): 96,95,94

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,01,00,99,98,97,96,95,94,93,92,91,90,89,88

Waste Class: 251 - OIL SKIMMINGS & SLUDGES
Reported Years: 22,21,20,19,18,17,16,15,14,13,12,11,10,09,08,07,06,05,01,00,99,98,97,96,95,94,93,92,91

2022 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2022 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 37.28
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 4.0

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 68.51
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 14.0

2021 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2021 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 126.91
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 19

2020 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2020 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 97.12
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 12

2019 Generator Info

NAICS Code 1: 812210

NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2019 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 49.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 10

2018 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2018 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 83.4
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 12

2017 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2017 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 116.1
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 13

2016 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2016 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 90.52
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 10

2015 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Fac: N
MHSW Facility: N

2015 Manifest Summary

Waste Code:	251	**Waste Char Code:**	L
Waste Description:	OIL SKIMMINGS & SLUDGES	**Waste Char Desc:**	LIQUID INDUSTRIAL WASTE
Quantity (kg):	1900.0	**Waste Count:**	1
Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	115.15	**Waste Count:**	13

2014 Generator Info

NAICS Code 1:	812210
NAICS 1 Description:	Funeral Homes
Contaminated Fac:	N
MHSW Facility:	N

2014 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	122.8	**Waste Count:**	11

2013 Generator Info

NAICS Code 1:	812210
NAICS 1 Description:	Funeral Homes
Contaminated Fac:	N
MHSW Facility:	N

2013 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	115	**Waste Count:**	13

2012 Generator Info

NAICS Code 1:	812210
NAICS 1 Description:	Funeral Homes
Contaminated Fac:	N
MHSW Facility:	N

2012 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	99.0	**Waste Count:**	10

2011 Generator Info

NAICS Code 1:	812210
NAICS 1 Description:	Funeral Homes
Contaminated Facility:	N
MHSW Facility:	N

2011 Manifest Summary

Waste Code:	312	**Waste Char Code:**	P
Waste Description:	PATHOLOGICAL WASTES	**Waste Char Desc:**	PATHOLOGICAL
Quantity (kg):	76	**Waste Count:**	7

2010 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility: N
MHSW Facility: N

2010 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg): 200
Waste Char Code: L
Waste Char Desc: LIQUID INDUSTRIAL WASTE
Waste Count: 1

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 113
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 12

2009 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility: N
MHSW Facility: N

2009 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 245
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 26

2008 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility: N
MHSW Facility: N

2008 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 422.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 49

2007 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility:
MHSW Facility:

2007 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 422.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 49

2006 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility:
MHSW Facility:

2006 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 636.0
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 50

2005 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility:
MHSW Facility:

2005 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 261.35
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 46

2004 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility:
MHSW Facility:

2003 Generator Info

NAICS Code 1: 812210
NAICS 1 Description: Funeral Homes
Contaminated Facility:
MHSW Facility:

2001 Generator Info

SIC Code: 9731
SIC Description: FUNERAL HOMES

2001 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 150.75
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 29

2000 Generator Info

SIC Code: 9731
SIC Description: FUNERAL HOMES

2000 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 57.6
Waste Char Code: P
Waste Char Desc: PATHOLOGICAL
Waste Count: 10

1999 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1999 Manifest Summary

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL
Quantity (kg): 725.2 ***Waste Count:*** 42

1998 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1998 Manifest Summary

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL
Quantity (kg): 837.45 ***Waste Count:*** 39

1997 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1997 Manifest Summary

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL
Quantity (kg): 273.25 ***Waste Count:*** 19

Waste Code: 251 ***Waste Char Code:*** L
Waste Description: OIL SKIMMINGS & SLUDGES ***Waste Char Desc:*** LIQUID INDUSTRIAL WASTE
Quantity (kg): 341.25 ***Waste Count:*** 1

1996 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1996 Manifest Summary

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL
Quantity (kg): 2 ***Waste Count:*** 1

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL
Quantity (kg): 285 ***Waste Count:*** 11

1995 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1995 Manifest Summary

Waste Code: 312 ***Waste Char Code:*** P
Waste Description: PATHOLOGICAL WASTES ***Waste Char Desc:*** PATHOLOGICAL

Quantity (kg):	123	***Waste Count:***	16
Waste Code:	312	***Waste Char Code:***	P
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	PATHOLOGICAL
Quantity (kg):	27	***Waste Count:***	5

1994 Generator Info

SIC Code:	9731	***SIC Description:***	FUNERAL HOMES

1994 Manifest Summary

Waste Code:	312	***Waste Char Code:***	
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	
Quantity (kg):	11.25	***Waste Count:***	1.0
Waste Code:	251	***Waste Char Code:***	
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	
Quantity (kg):	227.0	***Waste Count:***	1.0
Waste Code:	251	***Waste Char Code:***	
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	
Quantity (kg):	227.5	***Waste Count:***	1.0
Waste Code:	312	***Waste Char Code:***	
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	
Quantity (kg):	272.0	***Waste Count:***	25.0

1993 Generator Info

SIC Code:	9731	***SIC Description:***	FUNERAL HOMES

1993 Manifest Summary

Waste Code:	251	***Waste Char Code:***	
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	
Quantity (kg):	227.5	***Waste Count:***	1.0
Waste Code:	312	***Waste Char Code:***	
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	
Quantity (kg):	366.75	***Waste Count:***	26.0

1992 Generator Info

SIC Code:	9731	***SIC Description:***	FUNERAL HOMES

1992 Manifest Summary

Waste Code:	312	***Waste Char Code:***	
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	
Quantity (kg):	337	***Waste Count:***	13
Waste Code:	312	***Waste Char Code:***	
Waste Description:	PATHOLOGICAL WASTES	***Waste Char Desc:***	
Quantity (kg):	301	***Waste Count:***	9
Waste Code:	251	***Waste Char Code:***	
Waste Description:	OIL SKIMMINGS & SLUDGES	***Waste Char Desc:***	
Quantity (kg):	409	***Waste Count:***	2

1991 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1991 Manifest Summary

Waste Code: 251
Waste Description: OIL SKIMMINGS & SLUDGES
Quantity (kg):
Waste Char Code:
Waste Char Desc:
Waste Count:

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg):
Waste Char Code:
Waste Char Desc:
Waste Count:

1990 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1990 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 161.55
Waste Char Code:
Waste Char Desc:
Waste Count: 21.0

1989 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

1989 Manifest Summary

Waste Code: 312
Waste Description: PATHOLOGICAL WASTES
Quantity (kg): 141.75
Waste Char Code:
Waste Char Desc:
Waste Count: 14.0

1988 Generator Info

SIC Code: 9731 ***SIC Description:*** FUNERAL HOMES

---

47 ***3 of 3*** ***NW/298.8*** ***101.2 / 4.05*** ***Turner & Porter Funeral Directors Ltd.*** ***GEN***
2180 Hurontario Street
Mississauga ON L5B 1M8

Generator No.: ON9465628
Years Reported: 25,23

Alternate Locations

Generator No: ON9465628
Generator Nm: TURNER & PORTER FUNERAL DIRECTORS LTD.
Site Addr: 2180 HURONTARIO STREET
City: MISSISSAUGA
Reported Year(s): 25,23

2025 Generator Info

Waste Reported

Waste Class: 312 - PATHOLOGICAL WASTES
Reported Years: 23

2025 Waste Info

Waste Code: 312
Waste Description: Pathological Wastes
Waste Char Cd: P
Waste Char Desc: Pathological

2023 Generator Info

NAICS Code: 813920
NAICS Description: Professional Organizations
Contamin'd Fac: No
MHSW Facility: No

2023 Manifest Summary

Waste Code: 312
Waste Description: Pathological Wastes
Qty Received (kg): 0
Waste Char Code: P
Waste Char Desc: Pathological
Waste Count: 15

Unplottable Summary

Total: 49 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	The Regional Municipality of Peel	Birchwood Drive, Gordon Drive, Isabella Avenue and Mississauga Rd	Mississauga ON	
CA	Berkley Homes (Gordon Woods II) Inc.	Grange Dr	Mississauga ON	
CA	Berkley Homes (Gordon Woods II) Inc.	Premium Way	Mississauga ON	
CA		Westlock Road and Premium Way	Mississauga ON	
CA	MISSISSAUGA CITY	HURONTARIO ST., HERITAGE WALK	MISSISSAUGA CITY ON	
CA	GOTTARDO PROPERTIES LTD. & GOTTARDO CORP	HURONTARIO ST. STREET A	MISSISSAUGA CITY ON	
CA	GOTTARDO PROPERTIES LTD. & GOTTARDO CORP	HURONTARIO ST. STREET A	MISSISSAUGA CITY ON	
CA	JOSEPH GYETVAN	HURONTARIO ST.	MISSISSAUGA CITY ON	
CA	MISSISSAUGA CITY CITY CENTRE PLAZA	HURONTARIO ST. PH. 1 TO 5	MISSISSAUGA CITY ON	
CA	E. ESCUBEDO, C. DIPLACIDO & R. LAYFIELD	HURONTARIO ST./STM-WATER MGT.	MISSISSAUGA CITY ON	
CA	Herpreet Singh Sohi	From Autumn Breeze Drive North to 80m North	Mississauga ON	
CA	MISSISSAUGA CITY	HURONTARIO STREET	MISSISSAUGA CITY ON	
ECA	EllisDon Corporation operating as EDCO Constructors QEW/CR Joint Venture	Premium Way	Mississauga ON	L4Y 1M4
ECA	The Regional Municipality of Peel	Westlock Road and Premium Way	Mississauga ON	L6T 4B9
ECA	The Regional Municipality of Peel	Queensway W Hurontario Street, Sherobee Road, and North Service Road	Mississauga ON	L6T 4B9
SPL	The Corporation of the Regional Municipality of Peel	Premium Way, West of Hwy 10	Mississauga ON	

SPL	Toronto Zenith Contracting Limited	At the QEW	Mississauga ON	NA
SPL	Enersource Hydro Mississauga Inc.		Mississauga ON	
SPL	Enersource Hydro Mississauga Inc.		Mississauga ON	
SPL	SHIPPIGAN FISHERIES	QEW TRANSPORT TRUCK (CARGO)	MISSISSAUGA CITY ON	
SPL	Transportation Network Carrier<UNOFFICIAL>	QEW, Eastbound Lane - Just east of Hwy 10	Mississauga ON	
WWIS		con 1	ON	
WWIS		N/A North Service Rd. lot 15 con 1	Mississauga ON	
WWIS		con 1	ON	
WWIS		con 1	ON	
WWIS		lot 15 con 1	ON	
WWIS		lot 15 con 1	ON	
WWIS		lot 15 con 1	ON	
WWIS		lot 15 con 1	ON	
WWIS		lot 15 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	
WWIS		lot 16 con 1	ON	

WWIS	lot 16 con 1	ON
WWIS	lot 16 con 1	ON
WWIS	lot 16 con 1	ON
WWIS	lot 15 con 1	ON
WWIS	lot 15 con 1	ON
WWIS	lot 15 con 1	ON
WWIS	Premium Way	Mississauga ON
WWIS	PREMIUM WAY	Mississauga ON
WWIS	con 1	ON
WWIS	lot 16 con 1	ON

Unplottable Report

Site: ***The Regional Municipality of Peel***
Birchwood Drive, Gordon Drive, Isabella Avenue and Mississauga Rd Mississauga ON

Database: ***CA***

Certificate #: 1030-8GZRG2
Application Year: 2011
Issue Date: 5/27/2011
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Berkley Homes (Gordon Woods II) Inc.***
Grange Dr Mississauga ON

Database: ***CA***

Certificate #: 5403-7JTR2T
Application Year: 2008
Issue Date: 9/25/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Berkley Homes (Gordon Woods II) Inc.***
Premium Way Mississauga ON

Database: ***CA***

Certificate #: 9140-7JMHNJ
Application Year: 2008
Issue Date: 9/22/2008
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Westlock Road and Premium Way Mississauga ON

Database: ***CA***

Certificate #: 6308-4PXRDB

Application Year: 00
Issue Date: 10/12/00
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the Regional Municipality of Peel
Client Address: 10 Peel Centre Drive
Client City: Brampton
Client Postal Code: L6T 4B9
Project Description: Construction of watermains on Westlock Road and Premium Way.
Contaminants:
Emission Control:

Site: ***MISSISSAUGA CITY***
HURONTARIO ST., HERITAGE WALK MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 3-0914-97-
Application Year: 97
Issue Date: 8/18/1997
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***GOTTARDO PROPERTIES LTD. & GOTTARDO CORP***
HURONTARIO ST. STREET A MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 3-0471-88-
Application Year: 88
Issue Date: 5/5/1988
Approval Type: Municipal sewage
Status: Revised
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***GOTTARDO PROPERTIES LTD. & GOTTARDO CORP***
HURONTARIO ST. STREET A MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 7-0417-88-
Application Year: 88
Issue Date: 5/5/1988
Approval Type: Municipal water
Status: Revised
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***JOSEPH GYETVAN***
HURONTARIO ST. MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 7-0850-87-
Application Year: 87
Issue Date: 6/25/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MISSISSAUGA CITY CITY CENTRE PLAZA***
HURONTARIO ST. PH. 1 TO 5 MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 7-2058-88-
Application Year: 88
Issue Date: 1/20/1989
Approval Type: Municipal water
Status: Approved in 1989
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***E. ESCUBEDO, C. DIPLACIDO & R. LAYFIELD***
HURONTARIO ST./STM-WATER MGT. MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 3-0848-92-
Application Year: 92
Issue Date: 9/17/1992
Approval Type: Municipal sewage
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Herpreet Singh Sohi***
From Autumn Breeze Drive North to 80m North Mississauga ON

Database: ***CA***

Certificate #: 7403-83TTGH
Application Year: 2010
Issue Date: 3/24/2010
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***MISSISSAUGA CITY***
HURONTARIO STREET MISSISSAUGA CITY ON

Database: ***CA***

Certificate #: 3-1325-88-
Application Year: 88
Issue Date: 8/3/1988
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***EllisDon Corporation operating as EDCO Constructors QEW/CR Joint Venture***
Premium Way Mississauga ON L4Y 1M4

Database: ***ECA***

Approval No: 0949-C7JG6R
Approval Date: 2021-10-19
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Credit Valley
MOE District: Halton-Peel
City:
Longitude:
Latitude:
Geometry X: -8859655.5581999999
Geometry Y: 5403186.6629000017
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: EllisDon Corporation operating as EDCO Constructors QEW/CR Joint Venture
Address: Premium Way
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2322-C6FKUS-14.pdf
PDF Site Location: Premium Way and Mississauga Road
City of Mississauga, Regional Municipality of Peel

Site: ***The Regional Municipality of Peel***
Westlock Road and Premium Way Mississauga ON L6T 4B9

Database: ***ECA***

Approval No: 6308-4PXRDB
Approval Date: 2000-10-12
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Business Name: The Regional Municipality of Peel
Address: Westlock Road and Premium Way
Full Address:
Full PDF Link:
PDF Site Location:

Site: ***The Regional Municipality of Peel***
Queensway W Hurontario Street, Sherobee Road, and North Service Road Mississauga ON L6T 4B9

Database: ***ECA***

Approval No: 6662-9TNPY3
MOE District:

Approval Date:	2015-02-26	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	

Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Business Name: The Regional Municipality of Peel
Address: Queensway W Hurontario Street, Sherobee Road, and North Service Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/2523-9PVH43-14.pdf
PDF Site Location:

Site: ***The Corporation of the Regional Municipality of Peel***
Premium Way, West of Hwy 10 Mississauga ON

Database: ***SPL***

Ref No:	4101-8DXMNR	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2/10/2011	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2/10/2011	***Impact to Health:***	
Dt Document Closed:	5/17/2011	***Agency Involved:***	

Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: Mary Fix Creek<UNOFFICIAL>
Site Address: Premium Way, West of Hwy 10
Site Region:
Site Municipality: Mississauga
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name: The Corporation of the Regional Municipality of Peel
Client Type:
Source Type:
Incident Cause: Pipe Or Hose Leak
Incident Preceding Spill:
Incident Reason: Other - Reason not otherwise defined
Incident Summary: Watermain Break Discharge Directly into Mary Fix Creek
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 0 other - see incident description
Contaminant Qty 1: 0
Contaminant Unit: other - see incident description
Contaminant Code: 99
Contaminant Name: WATER
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Water Supply
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:

Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Toronto Zenith Contracting Limited***
At the QEW Mississauga ON NA

Database: ***SPL***

Ref No: 2006-BKZMEV
Year:
Incident Dt: 2020/01/14
Dt MOE Arvl on Scn:
MOE Reported Dt: 2020/01/20
Dt Document Closed: 2020/02/03
Site No: 0528-BL2K5R
MOE Response: No
Site County/District: Regional Municipality of Peel
Site Geo Ref Meth: NA
Site District Office: Halton-Peel
Nearest Watercourse: Etobicoke Creek
Site Name: Etobicoke Creek
Site Address: At the QEW
Site Region: Central
Site Municipality: Mississauga
Site Lot:
Site Conc: NA
Site Geo Ref Accu: NA
Site Map Datum: NA
Northing: NA
Easting: NA
Entity Operating Name:
Client Name: Toronto Zenith Contracting Limited
Client Type: Corporation
Source Type: Other
Incident Cause:
Incident Preceding Spill: Process Upset/Malfunction
Incident Reason: Weather Conditions
Incident Summary: Toronto Zenith: Gravel to Etobicoke Creek - Coffer Dam Failure
Environment Impact:
Health Env Consequence:
Nature of Impact:
Contaminant Qty: 1 other - see incident description
Contaminant Qty 1: 1
Contaminant Unit: other - see incident description
Contaminant Code: 99
Contaminant Name: SAND/GRAVEL
Contaminant Limit 1:
Contam Limit Freq 1: n/a
Contaminant UN No 1: n/a
Receiving Medium: Land; Surface Water
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Miscellaneous Industrial
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health: 2 - Minor Environment
Agency Involved:

Site: ***Enersource Hydro Mississauga Inc.***
Mississauga ON

Database: ***SPL***

Ref No:	4022-9LERFW	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2014/06/25	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2014/06/25	***Impact to Health:***	
Dt Document Closed:	2014/07/10	***Agency Involved:***	
Site No:	NA		
MOE Response:	No Field Response		
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	Enola Ave, between The Greenway and Lakeshore<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Mississauga		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Enersource Hydro Mississauga Inc.		
Client Type:			
Source Type:			
Incident Cause:	Collision/Accident		
Incident Preceding Spill:			
Incident Reason:	Unknown / N/A		
Incident Summary:	40L pcb (14ppm) transformer oil to road, cb, cleaning		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Surface Water Pollution		
Contaminant Qty:	40 L		
Contaminant Qty 1:	40		
Contaminant Unit:	L		
Contaminant Code:	15		
Contaminant Name:	TRANSFORMER OIL (N.O.S.)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Transformer		
SAC Action Class:	Watercourse Spills		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Site: ***Enersource Hydro Mississauga Inc.***
Mississauga ON

Database: ***SPL***

Ref No:	8785-9KBJTE	***Municipality No:***	
Year:		***Nature of Damage:***	
Incident Dt:	2014/04/28	***Discharger Report:***	

Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	2014/05/21	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	
Site No:	NA		
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			
Site District Office:			
Nearest Watercourse:			
Site Name:	6901 Glory Crt<UNOFFICIAL>		
Site Address:			
Site Region:			
Site Municipality:	Mississauga		
Site Lot:			
Site Conc:			
Site Geo Ref Accu:			
Site Map Datum:			
Northing:			
Easting:			
Entity Operating Name:			
Client Name:	Enersource Hydro Mississauga Inc.		
Client Type:			
Source Type:			
Incident Cause:	Leak/Break		
Incident Preceding Spill:			
Incident Reason:	Equipment Failure		
Incident Summary:	Enersource Hydro: 118L non PCB transformer oil to grd		
Environment Impact:	Confirmed		
Health Env Consequence:			
Nature of Impact:	Soil Contamination		
Contaminant Qty:	118 L		
Contaminant Qty 1:	118		
Contaminant Unit:	L		
Contaminant Code:	15		
Contaminant Name:	TRANSFORMER OIL (N.O.S.)		
Contaminant Limit 1:			
Contam Limit Freq 1:			
Contaminant UN No 1:			
Receiving Medium:			
Activity Preceding Spill:			
Property 2nd Watershed:			
Property Tertiary Watershed:			
Sector Type:	Transformer		
SAC Action Class:	Land Spills		
Call Report Locatn Geodata:			
Time Reported:			
System Facility Address:			
Source Sector Type:			
Conservtn Auth Name:			
Primary Watershed:			
Quaternary Watershed:			
Offsite Impacts:			
Waterbody Impacted:			

Site: ***SHIPPIGAN FISHERIES***
QEW TRANSPORT TRUCK (CARGO) MISSISSAUGA CITY ON

Database: ***SPL***

Ref No:	31678	***Municipality No:***	21102
Year:		***Nature of Damage:***	
Incident Dt:	3/6/1990	***Discharger Report:***	
Dt MOE Arvl on Scn:		***Material Group:***	
MOE Reported Dt:	3/6/1990	***Impact to Health:***	
Dt Document Closed:		***Agency Involved:***	FIRE DEPT, MOT, OPP
Site No:			
MOE Response:			
Site County/District:			
Site Geo Ref Meth:			

Site District Office:
Nearest Watercourse:
Site Name:
Site Address:
Site Region:
Site Municipality: MISSISSAUGA CITY
Site Lot:
Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: OTHER TRANSPORTATION ACCIDENT
Incident Preceding Spill:
Incident Reason: ADVERSE ROAD CONDITION
Incident Summary: SHIPPIGAN FISHERIES: 150LDIESEL FUEL TO ROADWAY
Environment Impact: POSSIBLE
Health Env Consequence:
Nature of Impact: Soil contamination
Contaminant Qty:
Contaminant Qty 1:
Contaminant Unit:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium: LAND
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type:
SAC Action Class:
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Transportation Network Carrier<UNOFFICIAL>***
QEW, Eastbound Lane - Just east of Hwy 10 Mississauga ON

Database: ***SPL***

Ref No: 8830-877QB3
Year:
Incident Dt:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/9/2010
Dt Document Closed:
Site No:
MOE Response: No Field Response
Site County/District:
Site Geo Ref Meth:
Site District Office:
Nearest Watercourse:
Site Name: QEW, Eastbound Lane - East of Hwy 10<UNOFFICIAL>
Site Address:
Site Region:
Site Municipality:
Site Lot:

Municipality No:
Nature of Damage:
Discharger Report:
Material Group:
Impact to Health:
Agency Involved:

Site Conc:
Site Geo Ref Accu:
Site Map Datum:
Northing:
Easting:
Entity Operating Name:
Client Name:
Client Type:
Source Type:
Incident Cause: Other Transport Accident
Incident Preceding Spill:
Incident Reason: Equipment Failure - Malfunction of system components
Incident Summary: TT MVA on QEW - EB, 250-300L to grnd & CBs
Environment Impact: Confirmed
Health Env Consequence:
Nature of Impact: Surface Water Pollution
Contaminant Qty: 300 L
Contaminant Qty 1: 300
Contaminant Unit: L
Contaminant Code: 13
Contaminant Name: DIESEL FUEL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Receiving Medium:
Activity Preceding Spill:
Property 2nd Watershed:
Property Tertiary Watershed:
Sector Type: Transport Truck
SAC Action Class: Watercourse Spills
Call Report Locatn Geodata:
Time Reported:
System Facility Address:
Source Sector Type:
Conservtn Auth Name:
Primary Watershed:
Quaternary Watershed:
Offsite Impacts:
Waterbody Impacted:

Site: ***Database:*** ***WWIS***

con 1 ON

Well ID: 4908210
Construction Date:
Use 1st: Not Used
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: 75172
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 07/08/1997
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3656
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10322769	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	06/30/1997	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932062382
Layer:	1
Color:	
General Color:	
Material 1:	00
Material 1 Desc:	UNKNOWN TYPE
Material 2:	
Material 2 Desc:	
Material 3:	
Material 3 Desc:	
Formation Top Depth:	
Formation End Depth:	
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	964908210
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	

Pipe Information

Pipe ID:	10871339
Casing No:	1
Comment:	
Alt Name:	

Site:
N/A North Service Rd. lot 15 con 1 Mississauga ON

Database: ***WWIS***

Well ID:	7484825	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:	Monitoring	***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:	Observation Wells	***Date Received:***	08/27/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	DBU79VLL	***Contractor:***	6607
Tag:	A405868	***Form Version:***	9
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS S

Overburden/Bedrock: ***Easting NAD83:***
Pump Rate: ***Northing NAD83:***
Static Water Level: ***Zone:***
Clear/Cloudy: ***UTM Reliability:***
Municipality: MISSISSAUGA CITY
Site Info: Well located 2m N. of South Curb of N. Service Rd

Bore Hole Information

Bore Hole ID: 1010406743 ***Elevation:***
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 612956.00
Code OB Desc: ***North83:*** 4825085.00
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 4
Date Completed: 04/12/2024 ***UTMRC Desc:*** margin of error : 30 m - 100 m
Remarks: ***Location Method:*** wwr
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1010406953
Layer: 1
Color: 6
General Color: BROWN
Material 1: 28
Material 1 Desc: SAND
Material 2: 06
Material 2 Desc: SILT
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 0.0
Formation End Depth: 4.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1010406954
Layer: 2
Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 28
Material 2 Desc: SAND
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 4.5
Formation End Depth: 6.0
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1010406955
Layer: 3

Color: 2
General Color: GREY
Material 1: 06
Material 1 Desc: SILT
Material 2: 05
Material 2 Desc: CLAY
Material 3: 66
Material 3 Desc: DENSE
Formation Top Depth: 6.0
Formation End Depth: 7.599999904632568
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1010407093
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1010407130
Layer: 1
Plug From: 0.0
Plug To: 0.30000001192092896
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1010407131
Layer: 2
Plug From: 0.30000001192092896
Plug To: 4.199999809265137
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID: 1010406844
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1010406813
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1010407001
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0.10000000149011612
Depth To: 4.5
Casing Diameter: 5.099999904632568
Casing Diameter UOM: cm

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1010407025
Layer: 1
Slot: 10
Screen Top Depth: 4.5
Screen End Depth: 7.599999904632568
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.400000095367432

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1010406814
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1010406906
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.0
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1010407063
Diameter: 21.0
Depth From: 0.0
Depth To: 7.599999904632568
Hole Depth UOM: m
Hole Diameter UOM: cm

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908323
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: 75174
Tag:
Constructn Method:
Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 04/17/1998
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3656
Form Version: 1
Owner:

Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

County: PEEL
Lot:
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 10322859
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/27/1998
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Method of Construction & Well Use

Method Construction ID: 964908323
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871429
Casing No: 1
Comment:
Alt Name:

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4908322
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: 75175
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src: 1
Date Received: 04/17/1998
Selected Flag: TRUE
Abandonment Rec:
Contractor: 3656
Form Version: 1
Owner:
County: PEEL
Lot:
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Municipality: MISSISSAUGA CITY
Site Info:

Bore Hole Information

Bore Hole ID: 10322858
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 03/06/1998
Remarks:
Location Method Desc: Not Applicable i.e. no UTM
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Method of Construction & Well Use

Method Construction ID: 964908322
Method Construction Code: 0
Method Construction: Not Known
Other Method Construction:

Pipe Information

Pipe ID: 10871428
Casing No: 1
Comment:
Alt Name:

Site:
lot 15 con 1 ON

Database: ***WWIS***

Well ID: 7490270
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z437348
Tag: A372950
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 6032
Form Version: 7
Owner:
County: PEEL
Lot: 015
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010472256
DP2BR:

Elevation:
Elevrc:

Spatial Status:		***Zone:***	17
Code OB:		***East83:***	611954.00
Code OB Desc:		***North83:***	4826570.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/19/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 15 con 1 ON

Well ID:	7489686	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/04/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z438186	***Contractor:***	6946
Tag:	A414564	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010466923	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	610847.00
Code OB Desc:		***North83:***	4827528.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/29/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 15 con 1 ON

Well ID:	7489685	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/04/2024
Water Type:		***Selected Flag:***	TRUE

Casing Material:		***Abandonment Rec:***	
Audit No:	Z438185	***Contractor:***	6946
Tag:	A414566	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010466920	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	610846.00
Code OB Desc:		***North83:***	4827534.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	10/29/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 15 con 1 ON

Well ID:	7489684	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/04/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z438184	***Contractor:***	6946
Tag:	A414565	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010466917	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	610841.00
Code OB Desc:		***North83:***	4827536.00
Open Hole:		***Org CS:***	UTM83

Cluster Kind:		***UTMRC:***	4
Date Completed:	10/29/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 15 con 1 ON

Well ID:	7486718	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	09/26/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z423792	***Contractor:***	7557
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	WELLINGTON
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	CON
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	PEEL TOWNSHIP		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010444202	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	527452.00
Code OB Desc:		***North83:***	4828704.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/12/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 16 con 1 ON

Well ID:	7487981	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	10/07/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z435006	***Contractor:***	7215
Tag:	A157247	***Form Version:***	7
Constructn Method:		***Owner:***	

Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010448827
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/11/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 609959.00
North83: 4827335.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7487980
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z435007
Tag: A327532
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 10/07/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010448824
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/11/2024
Remarks:
Location Method Desc: on Water Well Record

Elevation:
Elevrc:
Zone: 17
East83: 610004.00
North83: 4827336.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7487979
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z435008
Tag: A327518
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 10/07/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010448821
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/11/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 609988.00
North83: 4827296.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7487978
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z435009
Tag: A327517
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 10/07/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010448818
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/11/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610015.00
North83: 4827289.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7490520
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428971
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010474254
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation:
Elevrc:
Zone: 17
East83: 610179.00
North83: 4827559.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Source Revision Comment:
Supplier Comment:

Site:
lot 16 con 1 ON

Database:
WWIS

Well ID: 7490519
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428970
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010474251
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610185.00
North83: 4827571.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database:
WWIS

Well ID: 7490518
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428972
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Municipality: MISSISSAUGA CITY
Site Info:

Bore Hole Information

Bore Hole ID: 1010474248
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610202.00
North83: 4827586.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7490517
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428982
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010474245
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610195.00
North83: 4827602.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:

Database:

lot 16 con 1 ON **WWIS**

Well ID:	7490516	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/18/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z428973	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	016
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010474104	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	610190.00
Code OB Desc:		***North83:***	4827602.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	09/03/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:***
lot 16 con 1 ON ***WWIS***

Well ID:	7490515	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/18/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z428975	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	016
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID: 1010474101
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610184.00
North83: 4827607.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7490514
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z428974
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 11/18/2024
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7241
Form Version: 7
Owner:
County: PEEL
Lot: 016
Concession: 01
Concession Name: DS N
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010474098
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 09/03/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 610145.00
North83: 4827549.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 16 con 1 ON

Database: ***WWIS***

Well ID: 7490513
Construction Date:
Use 1st:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes

Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	11/18/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z428976	***Contractor:***	7241
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	016
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS N
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010501081	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	610174.00
Code OB Desc:		***North83:***	4827539.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	09/03/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site: ***Database:*** ***WWIS***

lot 15 con 1 ON

Well ID:	7492919	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	12/30/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z434270	***Contractor:***	7644
Tag:	A418446	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS S
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010511895	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17

Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/27/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

East83: 612611.00
North83: 4825451.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 15 con 1 ON

Database: ***WWIS***

Well ID: 7492918
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z439531
Tag: A418448
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Clear/Cloudy:
Municipality: MISSISSAUGA CITY
Site Info:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 12/30/2024
Selected Flag: TRUE
Abandonment Rec:
Contractor: 7644
Form Version: 7
Owner:
County: PEEL
Lot: 015
Concession: 01
Concession Name: DS S
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1010511892
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 06/26/2024
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 612653.00
North83: 4825474.00
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Site:
lot 15 con 1 ON

Database: ***WWIS***

Well ID: 7492917
Construction Date:
Use 1st:
Use 2nd:
Final Well Status:
Water Type:
Casing Material:

Flowing (Y/N):
Flow Rate:
Data Entry Status: Yes
Data Src:
Date Received: 12/30/2024
Selected Flag: TRUE
Abandonment Rec:

Audit No:	Z434269	***Contractor:***	7644
Tag:	A418447	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	015
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS S
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010511889	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612598.00
Code OB Desc:		***North83:***	4825408.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	06/27/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Site:
Premium Way Mississauga ON

Database:
WWIS

Well ID:	7391933	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	07/12/2021
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	Yes
Audit No:	Z353329	***Contractor:***	7610
Tag:		***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	--
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	
Well Depth:		***Concession Name:***	
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	---		
Site Info:			

Bore Hole Information

Bore Hole ID:	1008712228	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	9

Date Completed: 06/23/2021
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

UTMRC Desc: unknown UTM
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1009913434
Layer: 1
Plug From: 0.0
Plug To: 3.5
Plug Depth UOM: m

Pipe Information

Pipe ID: 1009767781
Casing No: 0
Comment:
Alt Name:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1009915805
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Site:
PREMIUM WAY Mississauga ON

Database: ***WWIS***

Well ID: 7407145
Construction Date:
Use 1st:
Use 2nd:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z377669
Tag:
Constructn Method:
Elevation (m):
Elevatn Reliabilty:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:

Flowing (Y/N):
Flow Rate:
Data Entry Status:
Data Src:
Date Received: 12/29/2021
Selected Flag: TRUE
Abandonment Rec: Yes
Contractor: 7610
Form Version: 7
Owner:
County:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:

Clear/Cloudy:
Municipality:
Site Info:

UTM Reliability:

Bore Hole Information

Bore Hole ID: 1008905679
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 12/02/2021
Remarks:
Location Method Desc: on Water Well Record
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: -1
East83:
North83:
Org CS: UTM83
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1010060080
Layer: 1
Plug From: 7.5
Plug To: 0.0
Plug Depth UOM: m

Pipe Information

Pipe ID: 1009976583
Casing No: 0
Comment:
Alt Name:

Results of Well Yield Testing

Pumping Test Method Desc:
Pump Test ID: 1010061265
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code:
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing: No

Site:
con 1 ON

Database: ***WWIS***

Well ID: 4909196
Construction Date:
Use 1st: Not Used

Flowing (Y/N):
Flow Rate:
Data Entry Status:

Use 2nd:		***Data Src:***	1
Final Well Status:	Abandoned-Other	***Date Received:***	07/04/2003
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	253141	***Contractor:***	1663
Tag:		***Form Version:***	1
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL
Elevatn Reliabilty:		***Lot:***	
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS S
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	10546467	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	05/29/2003	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Location Method Desc:	Not Applicable i.e. no UTM		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Method of Construction & Well Use

Method Construction ID:	964909196
Method Construction Code:	A
Method Construction:	Digging
Other Method Construction:	

Pipe Information

Pipe ID:	11095037
Casing No:	1
Comment:	
Alt Name:	

Site: ***Database:*** ***WWIS***

lot 16 con 1 ON

Well ID:	7487928	***Flowing (Y/N):***	
Construction Date:		***Flow Rate:***	
Use 1st:		***Data Entry Status:***	Yes
Use 2nd:		***Data Src:***	
Final Well Status:		***Date Received:***	10/07/2024
Water Type:		***Selected Flag:***	TRUE
Casing Material:		***Abandonment Rec:***	
Audit No:	Z435059	***Contractor:***	7215
Tag:	A407287	***Form Version:***	7
Constructn Method:		***Owner:***	
Elevation (m):		***County:***	PEEL

Elevatn Reliabilty:		***Lot:***	016
Depth to Bedrock:		***Concession:***	01
Well Depth:		***Concession Name:***	DS S
Overburden/Bedrock:		***Easting NAD83:***	
Pump Rate:		***Northing NAD83:***	
Static Water Level:		***Zone:***	
Clear/Cloudy:		***UTM Reliability:***	
Municipality:	MISSISSAUGA CITY		
Site Info:			

Bore Hole Information

Bore Hole ID:	1010448125	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	612309.00
Code OB Desc:		***North83:***	4825307.00
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	08/10/2024	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Location Method Desc:	on Water Well Record		
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

This database of licensed and permitted pits and quarries is maintained by the Ontario Ministry of Natural Resources and Forestry (MNRF), as regulated under the Aggregate Resources Act, R.S.O. 1990. Aggregate site data has been divided into active and inactive sites. Active sites may be further subdivided into partial surrenders. In partial surrenders, defined areas of a site are inactive while the rest of the site remains active.

Government Publication Date: Up to Oct 2025

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-May 2025

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Apr 30, 2025

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2024

Commercial Fuel Oil Tanks: Provincial CFOT

Locations of commercial underground fuel oil tanks. This is not a comprehensive or complete inventory of commercial fuel tanks in the province; this listing is a copy of records of registered commercial underground fuel oil tanks obtained under Access to Public Information.
Note that the following types of tanks do not require registration: waste oil tanks in apartments, office buildings, residences, etc.; aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Chemical Manufacturers and Distributors: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jan 31, 2020

Chemical Register: Private CHM

This database includes a listing of locations of facilities within the Province or Territory that either manufacture and/or distributes chemicals.

Government Publication Date: 1999-Apr 30, 2025

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Feb 2026

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Aug 2025

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994 - Mar 31, 2026

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database (ODHD) is offered by the Province of Ontario's Ministry of Mines. The dataset contains information for over 164,000 percussion, overburden, sonic and diamond-drill holes. The presence of assay results with cutoff values for gold, silver, copper, zinc, lead, nickel and platinum group elements is noted. Drill hole data are compiled from assessment files that have been submitted to the ministry in accordance with the Ontario Mining Act (OMA). Source assessment file numbers are captured for cross reference with the Ontario Assessment File Database (OAFD). Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Jul 2025

Delisted Fuel Tanks: Provincial DTNK

List of fuel storage tank sites that were once found in - and have since been removed from - the list of fuel storage tanks made available by the regulatory agency under Access to Public Information.

Government Publication Date: Oct 2023

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011 - Feb 28, 2026

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994 - Mar 31, 2026

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011 - Feb 28, 2026

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Feb 28, 2026

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Apr 30, 2022

Environmental Offenders Registry: Federal EOR

The Environmental Offenders Registry, enforced by Environment and Climate Change Canada and Parks Canada, tracks corporations convicted under specific federal environmental laws. The registry includes corporate convictions resulting from court proceedings. Court prosecutions are one of several enforcement measures used when violations or potential violations are detected. Other measures like tickets, warning letters, or compliance orders may also be employed to restore compliance. Although not affected by the Environmental Enforcement Act, convictions obtained by Environment and Climate Change Canada under the Species at Risk Act and the Pollution Prevention Provisions of the Fisheries Act are also included.

Government Publication Date: Feb 28, 2026

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment, Conservation and Parks (MECP). These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2025

Excess Soil Registry: Provincial ESNR

The Excess Soil Registry is made available by the Resource Productivity and Recovery Authority (RPRA). Excess soil is soil dug up mainly during construction and excavation activities that must be removed from the development site because it cannot or will not be reused. The Minister of the Environment, Conservation and Parks directed the RPRA to establish and maintain the Excess Soil Registry, enabling regulated parties to comply with registration and filing notice requirements, the ministry to access data, and the public to view information from those filings. From January 1, 2023, construction and development project leaders, as well as operators and owners of soil Reuse Sites, and Residential Development Soil Depot sites, must file notices detailing how excess soil is reused and disposed of in compliance with Ontario's Excess Soil Regulation.

Government Publication Date: Oct 31, 2025

List of Expired Fuels Safety Facilities: Provincial EXP

List of facilities and tanks for which there was once a fuel registration. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province; this listing is a copy of previously registered tanks and facilities obtained under Access to Public Information. Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc; includes tanks which have been removed from the ground.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government. Includes fire training sites and sites at which Per- and Polyfluoroalkyl Substances (PFAS) are a concern.

Government Publication Date: Jun 2000-Feb 2026

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada (DFO) maintains an inventory of aboveground & underground fuel storage tanks located on DFO property or controlled by the DFO. The DFO provided 2019 data. Environment and Climate Change Canada (ECCC) provided the 2024 data on owned and regulated storage tank systems, as required from the Canadian Environmental Protection Act (CEPA) and its associated regulations. The ECCC might have information pertaining to non-regulated tanks or ones which are not owned and operated by DFO.

Government Publication Date: 1964-Mar 2025

Federal Identification Registry for Storage Tank Systems (FIRSTS): Federal FRST

A list of federally regulated Storage tanks from the Federal Identification Registry for Storage Tank Systems (FIRSTS). FIRSTS is Environment and Climate Change Canada's database of storage tank systems subject to the Storage Tank for Petroleum Products and Allied Petroleum Products Regulations. The main objective of the Regulations is to prevent soil and groundwater contamination from storage tank systems located on federal and aboriginal lands. Storage tank systems that do not have a valid identification number displayed in a readily visible location on or near the storage tank system may be refused product delivery.

Government Publication Date: 31 Mar, 2025

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks. This is not a comprehensive or complete inventory of private and retail fuel storage tanks in the province; this listing is a copy of registered private and retail fuel storage tanks, obtained under Access to Public Information.
Notes: registration was not required for private fuel underground/aboveground storage tanks prior to January 1990, nor for furnace oil tanks prior to May 1, 2002; registration is not required for waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. As of January 1, 2023, businesses and institutions subject to the amended Reg. 347: General – Waste Management are required to report their activities and pay fees through Resource Productivity & Recovery Authority (RPRA) online Hazardous Waste Program Registry (HWPR) rather than the Hazardous Waste Information Network (HWIN) system previously operated by the Ministry of the Environment, Conservation and Parks (MECP). Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Sep 30, 2025

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Jan 2026

Historical Business Activity Risk: Federal HBAR

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this list does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including BC Directories, Hendersons, Mights, Sun Directories, Vernons, and Wrights; spanning roughly 1920s through 1990 depending on information available by city.

This list is currently limited to sites as reported in the following provinces: Alberta, British Columbia, Saskatchewan, Manitoba, New Brunswick, Nova Scotia, Ontario, and Quebec.

Government Publication Date: 1920s - 1990

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

Fuel Oil Spills and Leaks: Provincial INC

Listing of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC). This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province; this listing in a copy of incidents reported to the SAC, obtained under Access to Public Information. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness.

Government Publication Date: Oct 2023

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the Ministry of the Environment, Conservation and Parks compiles new and updated information. Includes small and large landfills currently operating as well as those which are closed and historic. Operators of larger landfills provide landfill information for the previous operating year to the ministry for LIMO including: estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Mar 31, 2022

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2026

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment Conservation and Parks (MECP) provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act. MECP publicly releases the Environmental Compliance Report (ECR) on the Ontario Data Catalogue. In Ontario, all facilities with regulated wastewater discharges or air emissions under the Ontario Water Resources Act and the Environmental Protection Act must monitor and report any cases where approved operating limits have been exceeded.

Government Publication Date: Dec 31, 2024

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Nov 2023

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jan 31, 2026

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

Notice of Contamination List: Federal NOC

This dataset contains Notice of Contamination (NOC) submissions reported to the Canada Energy Regulator (CER), including the most recent annual update information where applicable. Regulated companies are required to submit an NOC when contamination is identified or encountered during any phase of a facility's lifecycle and confirmed through analytical sampling, or when contamination resulting from an incident cannot be remediated within 12 weeks of being reported to the CER. Blank values in the Annual Update Year and annual update fields indicate that the site has achieved remediation closure, has been identified as third-party contamination, or was reported recently and does not yet require an annual update.

Government Publication Date: Nov, 2025

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPR2

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of pollutant releases (to air, water and land), disposals, and transfers for recycling. The inventory, managed by Environment and Climate Change Canada, tracks over 300 substances. Under the authority of the Canadian Environmental Protection Act (CEPA), owners or operators of facilities that meet published reporting requirements are required to report to the NPRI.

Government Publication Date: Feb 2024

National Pollutant Release Inventory - Historic: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances. This data holds historic records; current records are found in NPR2.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Feb 28, 2025

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the Ministry of Natural Resources (MNR) handed over to the Ontario Oil, Gas and Salt Resources (OGSR) Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database includes well owner/operator, location, permit issue date, and well cap date, license number, status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provided for each well record.

Government Publication Date: 1800-May 2025

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994 - Mar 31, 2026

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: Oct 2011 - Feb 28, 2026

Ontario PFAS Spills: Provincial PFAS

This specific list of spills includes those incidents where one or more of the listed contaminants are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA), is originally sourced from the Ministry of the Environment, Conservation and Parks spills related data. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Jun 2024; Aug 2024; Oct-Nov 2024

NPRI Reporters - PFAS Substances: Federal PFCH

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This listing of PFAS substance reporters includes those NPRI facilities that reported substances that are found in either: a) the Comprehensive Global Database of PFASs compiled by the Organisation for Economic Co-operation and Development (OECD), b) the US Environmental Protection Agency (US EPA) Master List of PFAS Substances, c) the US EPA list of PFAS chemicals without explicit structures, or d) the US EPA list of PFAS structures (encompassing the largest set of structures having sufficient levels of fluorination to potentially impart PFAS-type properties).

Government Publication Date: Feb 2024

Potential PFAS Handlers from NPRI: Federal PFHA

The National Pollutant Release Inventory (NPRI) is Canada's public inventory of releases, disposals, and transfers, tracking over 320 pollutants. Per - and polyfluoroalkyl substances (PFAS) are a group of over 4,700 human-made substances for which adverse environmental and health effects have been observed. This list of potential PFAS handlers includes those NPRI facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used, or released by the facility - these are facilities that potentially handle PFAS based on their industrial profile.

Government Publication Date: Feb 2024

Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills). This is not a comprehensive or complete inventory of pipeline incidents in the province; this listing in an historical copy of records previously obtained under Access to Public Information. Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2021

Potential PFAS Handlers from EASR: Provincial PPHA

The Ontario Environmental Activity and Sector Registry (EASR), described in Ontario Regulation 245/11, allows businesses with less complex operations - and hence not requiring an Environmental Compliance Approval - to register their activities with the Ontario Ministry of the Environment, Conservation and Parks (MECP). This list of potential PFAS handlers includes those EASR facilities that reported business activity (NAICS code) included in the US Environmental Protection Agency (US EPA) list of Potential PFAS-Handling Industry Sectors, further described as operating in industry sectors where literature reviews indicate that PFAS may be handled and/or released. Inclusion of a facility in this listing does not indicate that PFAS are being manufactured, processed, used.

Government Publication Date: Dec 31, 2025

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994 - Mar 31, 2026

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-1990, 1992-2021

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up. RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09). The Government of Ontario states that it is not responsible for the accuracy of the information in this Registry.

Government Publication Date: 1997-Sept 2001, Oct 2004 - 31 Mar, 2026

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Apr 30, 2025

Scott's Manufacturing Directories: Private SCT

Scott's Directories is a data bank containing information on various manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, applicable NAICS Codes, and product categories are included in this database.

Government Publication Date: 1992-Mar 2011; Feb 2025

Ontario Spills: Provincial SPL

List of spills and incidents made available by the Ministry of the Environment, Conservation and Parks. This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988- Feb 2026

Wastewater Discharger Registration Database: Provincial SRDS

Facilities that report either municipal treated wastewater effluent or industrial wastewater discharges under the Effluent Monitoring and Effluent Limits (EMEL) and Municipal/Industrial Strategy for Abatement Regulations. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment keeps record of direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation, Mining, Petroleum Refining, Organic Chemicals, Inorganic Chemicals, Pulp & Paper, Metal Casting, Iron & Steel, and Quarries.

Government Publication Date: 1990-Dec 31, 2024

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970 - Apr 2024

Variances for Abandonment of Underground Storage Tanks: Provincial VAR

Listing of variances granted for storage tank abandonment. This is not a comprehensive or complete inventory of tank abandonment variances in the province; this listing is a copy of tank abandonment variance records previously obtained under Access to Public Information. In Ontario, registered underground storage tanks must be removed within two years of disuse; if removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness.

Government Publication Date: Feb 28, 2022

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011 - Feb 28, 2026

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Waste Management Site: Provincial WMS

This data contains Waste Disposal Site types collected by the Ministry of Natural Resource (MNR). The new data class brings over data from the Waste Management Information System (WMIS), which is an MS Access based database used by MNR to track Waste Management Sites. This was married with the spatial data from Waste Disposal Sites where possible. Different Waste Disposal Site types collected by the Ministry of Natural Resources include: compost disposal, hazardous waste disposal, household waste disposal, industrial waste disposal, septic drying bed, septic field, sewage disposal, tile bed, and transfer station. The data is currently under development, meaning the data is currently in the process of being created by the MNR.

Government Publication Date: April 30, 2025

Water Well Information System: Provincial WWIS

This database consists of information submitted by well contractors detailing locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table. The database is provided by the Ontario Ministry of Environment, Conservation and Parks.

Government Publication Date: Jul 31, 2025

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.


The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.


Appendix ‘G’

1. 1954 Aerial Photograph;
2. 1966 Aerial Photograph;
3. 1980 Aerial Photograph;
4. 1989 Aerial Photograph;
5. 1995 Aerial Photograph;
6. 2000 Aerial Photograph;
7. 2005 Aerial Photograph;
8. 2007 Aerial Photograph;
9. 2009 Aerial Photograph;
10. 2014 Aerial Photograph;
11. 2018 Aerial Photograph, and;
12. 2024 Aerial Photograph.

Aerial Photo – 1954



Aerial Photo – 1966




Aerial Photo – 1980




Aerial Photo – 1989



Aerial Photo – 1995



Aerial Photo – 2000




Aerial Photo – 2005



Aerial Photo – 2007



Aerial Photo – 2009



Aerial Photo – 2014



Aerial Photo – 2018




Aerial Photo – 2024



Appendix ‘H’

1. 1909 Topographic Map;
2. 1938 Topographic Map;
3. 1962 Topographic Map, and;
4. 1994 Topographic Map;



LEGEND

★ = Site Location

NOTES:

1. This drawing should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Topographic Map of Ontario, Brampton Sheet 30 M/12

3. Base map provided by "Geographical Section, General Staff 1909".

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.


PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Topographic Map 1909

PROJECT No.	SM 260253-E
SCALE	1: 63,360
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Topo 1909.vsd

DRAWING No. 4a



LEGEND

★ = Site Location

NOTES:

1. This drawing should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Topographic Map of Ontario, Brampton Sheet 30 M/12.

3. Base map provided by the "Geographical Section, General Staff; Department of National Defence, 1938".

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.


PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Topographic Map 1938

PROJECT No.	SM 260253-E
SCALE	1: 63,360
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Topo 1938.vsd

DRAWING No. 4b



LEGEND

★ = Site Location

NOTES:

1. This drawing should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Topographic Map of Ontario, Brampton Sheet 30 M/12a,11d, Edition 2.

3. Base map provided by the "Mapping Department of Energy, Mines and Resources, 1962".

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.


PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Topographic Map 1962

PROJECT No.	SM 260253-E
SCALE	1: 25,000
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Topo 1962.vsd

DRAWING No. 4C



LEGEND

☆ = Site Location

NOTES:

1. This drawing should be read in conjunction with Soil-Mat Engineers and Consultants Ltd. Report No.: SM 260253-E

2. Topographic Map of Ontario, Brampton Sheet 30 M/12, Edition 7.

3. Base map provided by "©1994, Her Majesty The Queen in Right of Canada".

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.

PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Topographic Map 1994

PROJECT No.	SM 260253-E
SCALE	1: 50,000
DATE	April 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Topo 1994.vsd

DRAWING No. 4d

Appendix ‘I’

1. Table of Current and Past Uses

6 Lakeside Drive, Grimsby, Ontario:


PIN 46016-0212 (LT)

Years	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1997 to Present	The Corporation of the Town of Grimsby	The Phase One Property is comprised of a wastewater treatment facility, however, at the time of the 2026 Site reconnaissance, the Phase One Property was vacant.	Community Use	• The 2026 Site reconnaissance revealed a single storey brick building with a basement level on the eastern portion of the Site, and two [2] rectangular concrete open-air sediment tanks on the western portion of the Site that were part of the former wastewater treatment facility. • Aerial pho photographs from 2009, 2016, and 2025 illustrate the former wastewater treatment plant [as observed during the Site reconnaissance] on the Phase One Property
1969 to 1997	Regional Municipality of Niagara	The Phase One Property is comprised of a wastewater treatment facility.	Community Use	• Aerial photographs from 1972, 1989, and 1994 illustrate the former wastewater treatment plant [as observed during the Site reconnaissance] on the Phase One Property. • Topographic maps from 1978 and 1996 illustrate one building on the Phase One Property.
1954 to 1969	The Corporation of the Town of Grimsby	The Phase One Property was developed as a wastewater treatment plant between 1955 and 1961	Community Use	• An aerial photograph from 1955 illustrates that the orchards are no longer present, however, the Phase One Property remains a vacant parcel of undeveloped land. • An aerial photograph from 1965 illustrates the former wastewater treatment plant [as observed during the Site reconnaissance] on the Phase One Property. • A topographic map from 1961 illustrates one building on the Phase One Property.
1945 to 1954	Hilda F. Gardham	The property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1938 illustrates orchard lands on the southern portion of the Phase One Property.
1926 to 1945	Canada Permanent Mortgage Corporations	The property was comprised undeveloped land.	Agricultural or Other	• An aerial photograph from 1934 illustrates the Phase One Property as primarily orchard lands. • A topographic map from 1938 illustrates orchard lands on the southern portion of the Phase One Property.
1913 to 1926	Murray Fitch	The property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1923 illustrates the Phase One Property as vacant undeveloped lands.
1906 to 1913	William Whittaker	The property was comprised undeveloped land.	Agricultural or Other	• A topographic map from 1907 illustrates the Phase One Property as vacant undeveloped lands.
1901 to 1906	John Durham	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.

Years	Name of Owner	Description of Property Use	Property Use	Other Observations from Aerial Photographs, Fire Insurance Plans, Etc.
1889 to 1901	John H. Grout	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1885 to 1889	John Grout, George Grout, & Eliza J. Grout	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1874 to 1885	Eliza Grout	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1863 to1874	James Patten	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1860 to 1863	Samuel G. Patten	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1860 to 1860	George S. Patten	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1857 to 1860	Samuel Patten & Hugh McInnes	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1851 to 1857	Pierre Chariotte	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1830 to 1851	Benjamin Crooks	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1807 to 1830	William Crooks	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1802 to 1807	Samuel Green	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
1798 to 1802	John Green	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.
Up to 1798	Crown	The property was comprised undeveloped land.	Agricultural or Other	• There were no readily available visual aids for the Phase One Property for this time period.

Appendix ‘J’

1. Phase One Conceptual Site Model;



LEGEND

- = Phase One ESA Property Boundary
- = Phase One ESA Study Area
- = Residential Properties
- = Commercial Properties
- = Agricultural or Other
- = Parkland
- = Institutional

Soil-Mat
Engineers & Consultants Ltd.

CLIENT
W.E. OUGHTRED AND ASSOCIATES INC.

PROJECT TITLE
Phase One Environmental Site Assessment
60 Harborn Road
Mississauga, Ontario

DRAWING TITLE
Phase One Conceptual Site Model

PROJECT No.	SM 260253-E
DATE	May 2026
CHECKED	KG
DRAWN	LC

FILE NAME
260253 Phase One CSM.vsd

DRAWING No. i

Conceptual Site Model Notes

CSM Off-Site Property Number	Current Occupant	Potential Contaminating Activity	Contaminants of Potential Concern	Qualified Person Specific Comments
1	Smola Inc. [Construction materials wholesaler]; A residential dwelling which is registered as commercial retail use lands	None	Not Applicable	Operations are limited to commercial services that are not considered potential contaminating activities.
2	Rabba Fine Foods, Subway, Mississauga Dental Specialists, Harborn Dental, Tiara Spa Nails, Beauty Supply Outlet, Hiway 10 Pharmacy, Sanctuary Grooming Lounge, Onaré Salon, Starbucks Coffee, Code Ninjas, Zara Spa Nails	None	Not Applicable	Operations are limited to commercial services that are not considered potential contaminating activities.
3	Vacant/undeveloped – future commercial and high-rise residential development	None	Not Applicable	Operations are limited to industrial services that are not considered potential contaminating activities.
4	Elegance Hospitality Management	None	Not Applicable	Operations are limited to commercial services that are not considered potential contaminating activities.
5	Ontario Clean Water Agency Corporate Office, Access Employment, Trillium Health Partners Foundation, Hanco Technologies	None	Not Applicable	Operations are limited to commercial services that are not considered potential contaminating activities.

SUPPORTING INFORMATION TO SATISFY TABLE 1, SCHEDULE D, PART VI OF THE RSC REGULATION

1. Based on the findings of the Phase One Environmental Site Assessment [ESA], no potentially contaminating activities [PCAs] were identified on the Phase One Property or within the Phase One ESA Study Area that would cause an area of potential environmental concern [APEC] on the Phase One Property.

2. There are no water bodies in whole or in part on the Phase One Property. However, the Phase One Property is bounded by Mary Fix Creek to the south. The local groundwater flow is expected to the south towards Mary Fix Creek. Regional groundwater flow is expected to the southeast towards Lake Ontario.

3. There are no areas of natural significance located in whole or in part on the Phase One Property or in the Phase One ESA Study Area.

4. The reconnaissance of the Site did not reveal any obvious visual evidence of a suspected groundwater well or cistern. In addition, a review of the MOE's water well records did not reveal any potable groundwater wells or monitoring wells on the Phase One Property.

   In addition to the above, our review of the MOE's water well records did not reveal any potable groundwater wells within the Phase One Study Area. However, our review of the available records revealed thirty-six [36] groundwater monitoring wells in the Phase One Study Area. The groundwater monitoring wells are reportedly located between 105 and 225 metres from the Site and range from 4.6 to 10.7 metres in depth.

5. The Phase One Property is serviced with any buried utilities, including storm and sanitary sewers, a municipal water supply, hydro and other soft services. The depth and location of these service trenches are not anticipated to have affected the distribution of contaminants of potential concern on the Phase One Property.

6. A review of the Ministry of Northern Development and Mine's "Quaternary Geology of the Brampton Area, Southern Ontario Sheet Map P3171" and the "Paleozoic Geology of the Brampton Area, Southern Ontario Sheet Map M2337", revealed the Site to be underlain by deltaic and lacustrine deposits of predominantly gravelly sand and silty sand, in turn, underlain by Upper Ordovician Georgian Bay Formation shale bedrock.

7. The validity of the CSM may be affected if the future use of the Phase One Property diverts from the current understanding of the proposed development to include the installation of multi-level basements or deep groundwater wells that may artificially alter or redirect local groundwater toward the Phase One Property. In this scenario, given the distance of the limited potential contaminating activities with relation to the Site, these activities are not considered a significant liability to the Phase One property, and as a result it is recommended that intrusive soil and/or groundwater sampling and monitoring would not be required in this scenario.

8. Based on the results of the Phase One ESA, it is the opinion of SOIL-MAT ENGINEERS & CONSULTANTS LTD. that the Site is suitable for a residential development and that a Record of Site Condition in support of a residential development can be filed for the Site.

Appendix ‘K’

1. Site Reconnaissance Photographs;




Photo showing the Site dwelling taken from the west end of the Site, facing southeast.



Photo showing the entrance to the Site, taken from the centre of the property, facing northwest.



Photo taken from the southeast corner of the Site, facing south, showing Mary Fix Creek in the background.



Photo taken from the southeast end of the Site, facing east.

Appendix ‘L’

1. Qualifications of Assessor

COMPANY BACKGROUND

SOIL-MAT ENGINEERS & CONSULTANTS LTD. [SOIL-MAT ENGINEERS] is a Canadian Consulting Engineering firm owned by its senior staff. Over the past thirty years the principals of SOIL-MAT ENGINEERS have undertaken geotechnical investigations in all areas of Hamilton and surrounding area and are familiar with the distinct geology of the area and therefore well-versed with the various soil, bedrock and groundwater conditions. SOIL-MAT ENGINEERS has a staff of over twenty-five engineers and technical staff who specialize in geotechnical assignments, environmental assessments, hydrogeological investigations and construction quality control/assurance projects. The company commenced operation on June 15, 1992 and has undertaken over 5,000 projects since its inception. The firm and all professional staff are in good standing with Professional Engineers Ontario. The company has maintained a current Certificate of Authorisation since it was granted on April 28, 1992. The firm's office and laboratory facilities are located at 130 Lancing Drive in Hamilton, Ontario.

REPORT AUTHORS

Peter Markesic, B.Sc.
Project Manager

Mr. Markesic has over nineteen years of experience in conducting Phase I ESA research and Phase II ESA fieldwork, including soil and groundwater sampling. Mr. Markesic has also been a key project member on a number of Phase III Environmental Site Assessment projects, including the decommissioning of underground fuel storage tanks and both in-situ and ex-situ remediation projects.

Keith Gleadall, B.A., EA Dipl.

Vice-President [Senior Professional]

Mr. Gleadall has over twenty years of experience in conducting Phase I, II and III Environmental Site Assessments and has successfully completed the requirements of the Associated Environmental Site Assessors of Canada and a Post Graduate Diploma in Environmental Site Assessment from Niagara College. Mr. Gleadall is responsible for undertaking numerous hydrogeological investigations, primarily within the City of Hamilton, associated with the development of residential and commercial subdivision projects, together with Phase I, II and III Environmental Site Assessments. Projects have included the decommissioning of underground and above ground fuel oil storage tanks, the implementation of in-situ and ex-situ remediation programmes, the decommissioning of a former dry cleaning facility and numerous 'dig and dump' remediation projects.

Ian Shaw, P. Eng, QP_{esa}
Senior Engineer/Principal/Director

Mr. Shaw has over twenty-four years of experience in geotechnical and environmental projects with Soil-Mat Engineers, and is a licensed Professional Engineer with PEO, as well as a Qualified Person [QP_{esa}] with the Ministry of Environment, Conservation, and Parks [MECP] under Regulation 153/04 [as amended]. As a Director of the firm since 2007 Mr. Shaw is responsible for overseeing the delivery of a large portion of the company's geotechnical, environmental and construction quality control services, directing engineering staff and field technicians.

Mr. Shaw has supervised the geotechnical investigations and construction quality control for the replacement/rehabilitation of bridge/culvert structures, reconstruction of municipal services and roadways, numerous residential and industrial subdivision projects, slope stability assignments and stormwater management consultations associated with several Conservation Authorities [Niagara, Hamilton, Halton, Credit Valley, Toronto, Grand River, Long Point, etc.], hydrogeological studies and several high rise developments in Hamilton, Burlington, Oakville, Mississauga, Brantford, St. Catharines, and Niagara Falls. Mr. Shaw has supervised the geotechnical investigation work and associated construction quality control services for a wide range of institutional projects, including the Burlington Performing Arts Centre, the Niagara Health Centre in St. Catharines, several schools in Hamilton [public and Catholic Boards] and Niagara [Catholic Board], numerous projects on McMaster University campus [Les Prince Residence, Ron Joyce Stadium, new track and field facility, New Engineering Building, Wilson Building, etc.], numerous residential developments, and numerous roadway reconstruction projects in Hamilton, Halton, Niagara, Haldimand, and Norfolk. Mr. Shaw has also been the general review engineer for the construction review of numerous segmental unit retaining wall projects.

As a Qualified Person [QP] Mr. Shaw has been the review engineer for numerous Phase One and Two Environmental Site Assessments [ESA], site remediation works, and Record of Site Condition [RSC] filings under Regulation 153/04. As well, Mr. Shaw has been the QP for excess soil management under Regulation 406/19 for numerous public and private development projects. Mr. Shaw was a guest presenter on the implementation of excess soil management at the Ontario Sewer & Watermain Construction Association annual general meeting in 2023.